Historic, Archive Document

Do not assume content reflects current scientific knowledge, policies, or practices.





U.S. Dept. of agriculture. Bureau of home economics.

Farm housing survey [Preliminary reports by counties and states]





17531

UNITED STATES DEPARTMENT OF AGRICULTURE

FEDERAL CIVIL WORKS ADMINISTRATION

Bureau of Home Economics in cooperation with Bureau of Agricultural Engineering, Extension Service, and Office of the Secretary

FARM HOUSING SURVEY

House	No. (1)		County	
Date_			State	
			Townsh	ip
			A	
Name	of occupant		Post-office a	ddress
White	(2)	Negro, Indian, or other	er nonwhite (3)	
House	owned (4)	Not owned (5)	Nai	me of owner
Post-o	ffice address of owner			
Total	acres in farm (6)		Acres ti	llable (7)
		B. HOUSE—GEN	VERAL INFORM	ATION
				unpainted (3)
Kind:	Log (1)	Earth (2)	Frame	painted (4)
				stucco (5)
	Brick (6)	Stone (7)		Concrete (8)
Age of				to 24 years (10)
				and over years (12)
One st				story (14)
Size: 7	Total number of room	as (15)	Total number of	of rooms not in use at any time of year
	(16)	Total number of regula	ar occupants (1	7)
		C. CONDIT	ON OF HOUSE	E

	PRESENT CONDITION		ION	Repairs or alter-	Replacement or
	Good	Fair	Poor	ations needed	new installation needed
Foundation	(1)	(2)	(3)	(4)	(5)
Walls, exterior	(6)	(7)	(8)	(9)	(10)
Roof	(11)	(12)	(13)	(14)	(15)
Chimneys	(16)	(17)	(18)	(19)	(20)
Doors and windows	(21)	(22)	(23)	(24)	(25)
Screens	(26)	(27)	(28)	(29)	(30)
Paint, exterior	(31)	(32)	(33)	(34)	(35)
Interior walls and ceiling	(36)	(37)	(38)	(39)	(40)
Floors	(41)	(42)	(43)	(44)	(45)
Stairs	(46)	(47)	(48)	(49)	(50)
Insulation	(51)	(52)	(53)	(54)	(55)

D. SPACE REQUIREMENTS

	Have now	Additional room needed
Bedrooms	(1) No	(2) No
Living room	(3)	(4)
Dining room.	(5)	(6)
Kitchen	(7)	(8)
Work room	(9)	(10)
Wash room for farm help	(11)	(12)
Bathroom	(13)	(14)
Halls	(15)	(16)
Basement	(17)	(18)
Closets	(19) No	(20) No
Front or side porch	(21)	(22)
Back porch	(23)	(24)
Storage space for fresh fruits and vegetables	(25)	(26)

E. WATER SUPPLY AND SEWAGE DISPOSAL

	Have now	Repairs or alter- ations needed	New installation needed
Source of water:			
Well, drilled or driven	(1)	(2)	(3)
Well, dug or bored	(4)	(5)	(6)
Spring	(7)	(8)	(9)
Cistern	(10)	(11)	(12)
Stream	(13)	x x x	x x x
Water supply for house:			
Carried (distance (14) ft.)	x x x	x x x	x x x
Hand pump in dwelling	(15)	(16)	(17)
Piped, cold	(18)	(19)	(20)
Piped, hot	(21)	(22)	(23)
Sanitary facilities:			
Outdoor toilet (privy):			
Improved	(24)	(25)	(26)
Unimproved	(27)	x x x	x x x
Indoor:			
Chemical	(28)	(29)	(30)
Flush	(31)	(32)	(33)
Bathroom fixtures:			
Tub	(34)	(35)	(36)
Shower	(37)	(38)	(39)
Lavatory	(40)	(41)	(42)
Kitchen sink with drain	(43)	(44)	(45)
Disposal of sewage:			
Septic tank	(46)	(47)	(48)
Cesspool	(49)	(50)	(51)
Stream	(52)	(53)	(54)
Surface	(55)	x x x	x x x

F. LIGHT AND HEAT

	Have now	Repairs or alterations needed	New installation needed
Lighting:			
Kerosene or gasoline lamps	(1)	x x x	(2)
Acetylene	(3)	(4)	(5)
Piped gas	(6)	(7)	(8)
Electric:			
Home plant	(9)	(10)	(11)
Power line	(12)	(13)	(14)
How far is nearest power line? (Distance (15) miles)_	$\mathbf{x} \mathbf{x} \mathbf{x}$	x x x	x x x
Heating:			
Fireplaces	(16)	(17)	(18)
Stoves	(19)	(20)	(21)
Circulating heater	(22)	(23)	(24)
Pipeless furnace	(25)	(26)	(27)
Piped warm air, steam, or water furnace	(28)	(29)	(30)

G. REFRIGERATION, LAUNDRY, AND COOKING FACILITIES

	Have now	Repairs or alterations needed	New installation needed
Refrigeration:			
Ice	(1)	(2)	(3)
Mechanical	(4)	(5)	(6)
Laundry:			
Where done:			1
Out-of-doors	(7)	x x x	x x x
In kitchen	(8)	(9)	(10)
In basement	(11)	(12)	(13)
In special room on same level with kitchen	(14)	(15)	(16)
Equipment:			
Fixed tubs	(17)	(18)	(19)
Power machine	(20)	(21)	(22)
Hand machine	(23)	(24)	(25)
Cooking facilities:			
Wood or coal stoves	(26)	(27)	(28)
Kerosene or gasoline stove	(29)	(30)	(31)
Gas stove	(32)	(33)	(34)
Electric stove	(35)	(36)	(37)

H. LANDSCAPING OF HOUSE

	Have now	Repairs or alter- ations needed	New installation needed
Yard:			
Surface drainage away from house	(1)	(2)	(3)
Lawn established	(4)	(5)	(6)
Plantings	(7)	(8)	(9)
Walks and drives	(10)	(11)	(12)
Fences	(13)	(14)	(15)

I. RELATIVE IMPORTANCE OF REPAIRS AND IMPROVEMENTS WANTED

Were the following specified amounts available for improving your home, what would you spend them for?

	\$500	\$250	\$100
House repairs and improvements:			
Foundation	(1)	(2)	(3)
Exterior walls	(4)	(5)	(6)
Roof	(7)	(8)	(9)
Chimneys	(10)	(11)	(12)
Doors, windows, screens.	(13)	(14)	(15)
Porches	(16)	(17)	(18)
Interior walls, ceilings, floors	(19)	(20)	(21)
Additional room	(22)	(23)	(24)
Water system	(25)	(26)	(27)
Sanitary facilities	(28)	(29)	(30)
ighting system	(31)	(32)	(33)
leating system	(34)	(35)	(36)
Bathroom equipment	(37)	(38)	(39)
aundry facilities	(40)	(41)	(42)
Cooking facilities	(43)	(44)	(45)
andscaping	(46)	(47)	(48)
Electricity:			
Home plant	(49)	(50)	(51)
Power line	(52)	(53)	(54)
Built-in equipment	(55)	(56)	(57)
Turnishings	(58)	(59)	(60)

J. NEW CONSTRUCTION AND FINANCING

Is construction of new house contemplated within next 3 years? (1)
(2) Estimated expenditure (3)
Give value of repairs or improvements made on the present house during the last 3 years: Less than \$100
(4); \$100 to \$499 (5); \$500 and over (6) Expenditure for repairs or improvements
contemplated within next 12 months (7) \$ Is money available from local credit sources to finance
house construction, repairs, or improvements (8) Would you be interested in borrowing money to
finance construction, repairs, or improvements provided interest rate is satisfactory and repayments can be
distributed over a period of 10 years? (9) Yes; (10) No How much would you desire
to borrow? (11) \$ What would you consider a satisfactory rate of interest? (12)
Remarks:
Value of record assigned by enumerator A B C D
Record obtained from: Man Both
Name of enumerator
Record checked by

Press Service, U.S.D.A.

For papers in counties having rural housing survey.

December 22, 1933.

TANK FILL SON

(NAME OF COUNTY) COUNTY SELECTED FOR FARM HOUSING SURVEY

First workers Almong by Tree

While business men are taking their January inventories, to see how they are to prepare for 1934, the farm families of (name of county) County will be having another and most interesting inventory of their own plants, the farm homes, through the medium of the rural housing survey to be conducted by the Bureau of Home Economics in Washington and the Home Extension agents in the various States.

here in County the work will be directly in charge of
(name of county)
, working under the direction of, State director
(name of county chairman), working under the direction of, State director
of extension work, in The survey has been approved as a Federal (name of State)
Civil Works Administration project, and the field work will be done by women who
will be appointed from the re-employment rolls in the county. Employment is thus
made available to those who need it while valuable information is collected as to
the present adequacy of farm homes and the needs and resources for improvement.
"It is heartening for the men and women in farm homes to see that farmers
are to be regarded again as consumers and employers, " says, home
demonstration agent here, in speaking of the survey, which is expected to begin
locally "They have wanted new houses, or new rooms or porches or (insert date)
repairs or furnaces or electricity. For too many years, they have had to budget




their crop returns with the utmost care to provide for food and clothing and taxes and interest. In too many cases there hasn't been enough income to pay for the repairs that every good housekeeper and every farmer know are necessary to keep the property from running down, and there has been practically nothing for new equipment.

"The community in general, I feel sure, will be interested in the tabulations that will be made after the field survey. These will show farm house condition and if they have adequate equipment.

"Not every county will be surveyed, but in those selected all farms will be visited. Full information will be obtained as to the condition of the house and equipment, and the need for repairs and improvement.

"Just after Christmas is the time when all women begin to think of fixing up their homes. For that reason I am sure the women here will cooperate with our field agents in every way. We recognize of course that this survey is only a foundation for what may be done in the future, perhaps only after several years any have passed. But even if farm people can't see their way clear to making/improvements on their houses this year we want their full cooperation as we now make the survey which will give the facts as a foundation for future planning."



FARM HOUSING SURVEY - 1934

COUNTY TABULATIONS AND SUMMARIES

Tabulation sheets will be mailed to each county, in order that the schedules may be summarized in the county.

- l. House number The house number should be assigned in the county office and the schedules should be arranged and entered in numerical sequence; that is, the lowest number first followed by higher numbers. Since the schedules are to be classified into four groups (see paragraph 4. below) and the house numbers are assigned to the sakedules as they are received in the county office, the numbers on any one summary sheet will not be in direct sequence. For example, on the "white, owner" sheet the house numbers may run like this: 2, 7, 11, 15, etc.
- 2. Number of columns The number of each vertical column on the tabulation sheets corresponds with the number of the item on the schedule; for example, on the schedule, to the right of the item "House No.", is the numeral "l". The person tabulating this schedule in the county office should place the house number in column "l" of the tabulation sheet "l". This house number should be repeated in column "l" on each successing tabulation sheet of the set.
- 3. Completed schedules should be checked and tabulated. All schedules should be checked by someone other than the enumerator before they are tabulated, and only substantially complete records should be tabulated; that is, the information in the schedule should be substantially complete for all questions between "A" and "H" inclusive. As much information as possible should be shown in sections "I" and "J".
- 4. Sorting of schedules before tabulation. The schedules should be sorted into the following four groups for each township before tabulating them:
 - 1. White occupants who are owners.
 - 2. White occupants who are not owners.
 - 3. Negroes or other non-white occupants who are owners.
 - 4. Negro and non-white occupants who are not owners.

Each of the above groups should be tabulated on separate sets of sheets. The shoets should be marked in the upper left-hand corner under "Classification" to indicate whether they cover the white, non-white, owner or non-owner. There will be two checks on each sheet; i.e., white _____ owner _____.

- 5. Entries on tabulation sheet. Certain of the entries in the columns of the tabulation sheet should be numbers, others should be check marks (). For example, in "Section B House General Information", the information from items "13" and "14" should be transferred to columns "13" and "14" of the tabulation sheet as check marks (). Column "15" of the tabulation sheet should contain the same numeral as is shown on the schedule under item "15", "Total number of rooms."
- 6. Method of tabulating. In tabulating, one person should read from the schedule and a second person should make the entry on the tabulation sheet in ink: The information should be read back from the tabulation sheet to verify the transfer and checked against the schedule.
- 7. Eighty schedules per sheet. Space is provided on each tabulation sheet for eighty schedules. Five schedules should be entered in each horizontal section. Care should be taken to see that five records, no more, no less, are entered in each horizontal space in order to economize on tabulation sheets, insure the identification of a perticular number with the proper schedule, and facilitate the taking of totals.
- 8. Check ell computations. All additions and other computations should be verified by a second person.
- 9. Totals for counties. Totals should be taken for each column in each group. Space for two totals will be found at the bottom of each sheet. The first space, "Total of column", is to be used for the sum of the numbers entered from the various schedules and may be in terms of rooms, persons, dollars, etc. These spaces will be used only in those columns where numbers appear to be totaled. The numbers will be entered in the following columns for the first series of totals, section "A", columns "6" and "7", section "B" columns "15", "16", "17", section "D", columns "1", "2", "19", "20", section "E", column "14", section "F", column "15", section "J", columns "2", "3", "7", and "11". The second space, "Number of entries in column", will be used to indicate the total number of entries in the column. Every column should be totaled in the second space. For example, the total of section "J", column "3", may be \$126,789, which is the estimated expenditure for new construction, while the total on the line below may be 1,375 which is the number of houses on which the estime ted expenditure of \$126,789 is to be spent. The first series of totals should be entered in red ink. The totals on the line below should be entered in black.

10. County summaries. - Totals should be transferred from each township sheet in making the county summaries. Summaries should be made for each of the four groups shown in paragraph 4, above. The following side headings should be printed on the tabulation sheets for the purpose of preparing totals of the columns for the county. Figures for two townships should be entered in each horizontal space of the tabulation sheets, which is used for this summary.

White owners in county

Township or District No. 1: Total of column*

Number of entries in column**

Township or District No. 2: Total of column*

Number of entries in column**

Township or District No. 3: Total of column*

Number of entries in column**

Etc.

Total white owners: Total of column*

Number of entries in column**

White non-owners in county

Township or District No. 1: Total of column*

Number of entries in column**

Township or District No. 2: Total of column*

Number of entries in column*

Township or District No. 3; Total of column*

Number of entries in column**

Etc.

Total white non-owner: Total of column*

Number of entries in column**

Non-white owners

Township or District No. 1: Total of column*

Number of entries in column**

Township or District No. 2: Total of column*

Number of entries in column**

Township or District No. 3: Total of column*

Number of entries in column**

Etc.

Total non-white owners: Total of column*

Number of entries in column**

^{*} Figures should be enterd in red ink.

^{**} Figures should be entered in black ink.

នៃការប្រជាព្រះប្រជាព្រះប្រជាព្រះប្រជាព្រះ នៃ ឆ្នាំរប់មេខ គេរំគែន់ ប៉ុន្តា ប្រជាព្រះ ប្រជាព្រះ ប្រជាព្រះ ប្រជាព ការប្រជាព្រះ នៃ សំខាន់ បាន ខេត្ត នៃ បានប្រជាព្រះ បានប្រជាព្រះ មានប្រជាព្រះ បានប្រជាព្រះ បានប្រជាព្រះ បានប្រជាព បានប្រជាព្រះ ប្រជាព្រះ បានប្រជាព្រះ សំខាន់ បានប្រជាព្រះ បានប្រជាព្រ បានប្រជាព្រះ បានប្រជាព្រះ បានប្រជាព្រះ បានប្រជាព្រះ បានប្រជាព្យ បានប្រជាព្យ បានប្រជាព្យ បានប្រជាព្យ បានប្រជាព្យ បានប្រជាព្យ បានប្រជាព្យ បានប្រជាព្យ បានបានប្រជាព្យ បានប្រជាព្យ បានប្រជាព្យ បានប្រជាព្យ បានប្រជាព្យ បានប្រជាព្យ បានប្រជាព្យ បានប្រជាព្យ បានប្រជាពិសិក្ស បានប្រជាព្យ បានប្រជាព្យ បានប្រជាព្យ បានប្រជាព្យ បានប្រជាពិសិក្ស បានប្រជាព្យ បានប្រជាព្យ បានប្រជាពិសិស្ស បានបានប្រជាពិសិស្ស បានប្រជាពិសិស្ស បានប្រជាពិសិស បានប្រជាពិសិស្ស បានបានប្រជាពិសិស បានប្រជាពិសិស បានប្រជាពិសិស្ស បានប្រជាពិសិស្ស បានប្រជាពិសិស្ស បានប្រជាពិសិស្ស បានប្រជាពិសិស បានប្រជាពិសិស្ស បានប្រជាពិសិស្ស បាន

TARRET LA REPORT DE TARRET DE TOURS DE

Monaries to issue: valued interpretation of the second of

*Recoins to indo! If well and comit to all the true **Indocument of all the true **Indocument of the true **Indocument of

ంగా ఇళ్లో జిల్లా కుట్టుల్లో కాట్టుకట్టి కాటింది. కాటింది. కాటింది. కాటింది.

**Principal allegations (%) require

single, all apparented to be seen as the constant of the seen and the seen apparented to a planted to see the seen appearent.

Paragrican de Anders 25 vall au ludes de marianes. Programa de la lacidad de la propinsión

*charjos ha Lodus (3. 1944) de fare fil su como a d' Manga fon el el lagol de model de

AJAJAA JĀJĀRVAS I... Manska da data a stillina indelos pada est Manska ad natura a Senatania

. The science is for the second of the second residual second in the second residual second in the second second

stand been and some that is the single between the most of the single was something.

Non-white non-owners

Township or District No. 1: Total of column*

x-notice

Number of entries in column**

Township or District No. 2: Total of column*

Number of entries in column**

Township or District No. 3: Total of column*

Number of entries in column**

Etc.

Total non-white non-owners: Total of column*

Number of entries in column**

The totals from this section should be carried forward to the table indicated in paragraph "ll" and grand totals made as indicated in that peragraph.

11. County summaries should be made as follows:

Grand total of column for county:

White owners: Total of column*

Number of entries in column**

White non-owners: Total of column*

Number of entries in column**

1. Total white: Total of column*

Number of entries in column**

Non-white owners: Total of column*

Number of entries in column**

Non-white non-owners: Total of column*

Number of entries in column**

2. Total non-white: Total of column*


Number of entries in column**

3. Grand total thites and non-whites (a); Total of column* Number of entries

in column**

* Figures should be entered in rad ink.

^{**} Figures should be entered in black ink.



Owners - white: Total of column*

Number of intites in column**

Owners - non-white: Total of column*

Number of entries in column**

4. Total owners: Total of column*

Number of entries in column**

Non-owners - white: Total of column*

Number of entries in column**

Non-owners - non-white: Total of column*

Number of entries in column**

5. Total non-owners: Total of column*

Number of entries in column**

6. Grand total owners and non-owners (a): Total of column*

Number of entries
in column**

- (a) Grand total 3 should equal grand total 6.
- * Figures should be entered in red ink.

٠٠ اود رقد ٧٠

** Figures should be entered in black ink.

12. Summery for interest rate, (section J, New construction, item "12")

	2
Rate of interest	Number of schedules reporting rate of interest
Column 1	Column 2
%	NUMBER
1 to 2	1
2.1 to 3	:
3.1 to 4	:
4.1 to 5	
5.1 to 6	:
6.1 to 7	•
7.1 to 8) 0
8.1 to 9	:
9.1 to 10	:
	•

to purificación de destructivos de la composição de la co

Conservation of the conservation

to relate the district of the grand district.

The massifications also because the massificate

*## The second of the second o

*Abdraudike fract teallow-man, - mornio-medi *Maddies at eatrans to medical

್ಟು ತಲ್ಲ ಹಿಳಗಳು ಸಂಪರ್ಧಿ ಕಿಂತ್ರಾಮ್ ಕಟ್ಟಾಗಿ ಎಂದು ಪ್ರಕ್ರಿಸಿದ್ದಾರೆ. ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ರಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ರಿಸಿದ್ದಾರೆ. ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ರಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ರಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ರಿಸಿದ್ದಾರೆ. ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ರಿಸಿದ್ದಾರೆ. ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ರಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ರಿಸಿದ್ದಾರೆ. ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ರಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ರಿಸಿದ್ದಾರೆ. ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ರಿಸಿದ್ದಾರೆ. ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ. ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ. ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ. ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ. ಕಿಂತ್ರಾಮ್ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ. ಕಿಂತ್ರಾಮ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ. ಕಿಂತ್ರಾಮ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ ಪ್ರಕ್ಷಿಸಿದಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ ಪ್ರಕ್ಷಿಸಿದಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ ಪ್ರಕ್ಷಿಸಿದಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ ಪ್ರಕ್ಷಿಸಿದ್ದಾರೆ ಕಿಂತ್ರಾಮ ಪ್ರಕ್ಷಿಸಿದಿದ್ದಾರೆ ಕಿಂತ್ರಾಹಿದ್ದಾರೆ ಕಿಂತ್ರಾಹಿದಿದ್ದಾರೆ ಕಿಂತ್ರಾಹಿದಿದ್ದಾರೆ ಕಿಂತ್ರಾಹಿದಿದ್ದಾರೆ ಕಿಂತ್ರಾಹಿದಿದಿದ್ದಾರೆ ಕಿಂತ್ರಾಹಿಸಿದಿದ್ದಾರೆ ಕಿಂತ್ರಾಹಿದಿದ್ದಾರೆ ಕಿಂತ್ರಾಹಿದಿದಿದ್ದಾರೆ ಕಿಂತ್ರಾಹಿದಿದಿದಿದ್ದಾರೆ ಕಿಂ

with I are I also regulations and reads of Indian contests to the

The was transported by the second of the sec

Andrew Committee of the Committee of the

42 43 2.8

ingle Late and decreased with a molice of a trace the garage and stance of

(Suggested radio talk by Home Demonstration Agents concerning Farm Housing Survey.)

--00000--

Total

I want to tell you women in farm homes who are listening to this broadcast about our farm home survey. This is a civil works project of the Federal and State governments. It is being supervised by the home demonstration agents in each county; in the State by the Agricultural Extension Service; nationally by the Bureau of Home Economics. The persons with whom each of you farm women will come in contact are field agents. They are appointed to work under the home demonstration agent in each county. One of these winter days, quite soon now, a field agent will call at your house.

We don't want you to keep them waiting too long when they come, and that is why I want to tell you tonight what you can do to help in this survey. They will ask you questions about the improvements and additions you would like to make on your houses, as farm prices get better. Everyone hopes that 1934 will bring these better prices, and we want to know what you need to put your farm houses in good repair and make them comfortable throughout. This is a good time for an inventory of the repairs that are needed. Would you like to have papering done? Painting? A new furnace put in, or electricity, or a water system or a bathroom and toilet?

These last few years you have had to let repairs and improvements go because you couldn't afford to spend what they would cost. You are always a producer, but for quite a long time now you have been out of the ranks of consumers of anything but just the necessities of life. This decreased buying power in the farm homes has decreased purchasing power in the cities, and thus has cut down the demand for farm products. So we have started a vicious circle which now we are hoping to break.



While millions of people have been out of work in the cities in the past few years hundreds of thousands of farmers have been living in homes which fall far below modern standards of comfort, or even minimum standards for health. This survey is the first step toward determining the potential demand for better housing on our farms. National leaders hope that such a study will lay a foundation for the working out of a system by which the unemployed people in the cities can be given real jobs making the things which farmers have been doing without, so says Dr. Mordecai Ezekiel, economic advisor to the Secretary of Agriculture, who is in general charge of the present survey. And as the purchasing power of these people in the cities and towns increases the prices for farm products will have a corresponding rise.

These are the things these field agents will want to find out. Think of them now, talk them over with your husband and family, and be ready to answer the agent who comes to your door. She will ask for general information about your house — its size, its material and construction, and the number of people living there regularly. She will ask you too about the condition of the foundation, the outer walls, the roof, the chimneys, the doors and windows and screens, and about the interior walls, floors, stairs and insulation — you will want to talk to the menfolks about these details.

She will ask about the rooms you now have -- bedrooms, living room, dining room, kitchen, work room, wash room for your farm help, bathroom, halls basement, closet space, porches, storage facilities for fruits and vegetables. The list is a long one, to give a basis for study later. All of you won't have or need all of the things listed on her schedule.

She will ask information as to your water supply, drilled or driven wells, spring, cistern or stream. If you have to carry water into the house,



how far must you go? Is the water supply pumped into the house? How? Have you a bathroom and fixtures, kitchen sink and drain? How is waste disposed of? How do you light the house, and do you heat it with fireplace, stove or furnace?

Farm gardens are now regarded by all of us as indispensable parts of our homes, and this survey will ask about your lawn, walks, drives and fences, shrubbery and landscaping features. All of these things add to the value of your property, you know, and they thus have a place in this study.

And here comes a chance for some delightful make-believe. Your caller will ask you what you would do toward remodeling or improving your house if you had \$500; if you had \$250; if you had \$100. You can list your preferences, and in doing this we suggest that you mark your choices One, Two and Three.

The first few days of every new year are given over by merchants and business men to inventories of their property. We believe it is good business for you to make inventories of your homes too, and this month, with work outside the house almost at a standstill, is the right time for a conference as to the real needs for improved farm house facilities.

I want to repeat before I close my talk, the reason for this survey in which we are asking your help. It is a Civil Works project, carried out by the United States Department of Agriculture and the State Agricultural Extension Services. Data will be collected from 300 typical counties in the United States, by women employed under the Civil Works Administration. It will provide valuable facts which have heretofore been unavailable and it will serve as a foundation, upon which to build a program for improved farm homes. A field agent will call at the home of each one of you, within the next few weeks. You will, we are sure, give her all possible cooperation in her work.

UNITED STATES DEPARTMENT OF AGRICULTURE

BUREAU OF HOME ECONOMICS
WASHINGTON, D. C.

January 6, 1934

BULLETIN FOR STATE CHAIRMEN. RURAL HOUSING SURVEY, C. W. A., NO. I.

A flood of telegrams from all over the country has indicated with surprising unanimity the major problems to be encountered in administering the Rural Housing Survey. In order to save time I shall discuss them in this general letter, If individual problems are not solved by this letter, I shall be glad to furnish the information through correspondence.

The three main problems have been delay in receiving the schedules, uncertainty about use of the franking privilege, and travel. In addition, the question of adjustment of personnel to meet the peculiar conditions of individual States has arisen, and that of payment of telephone and telegrath expenses.

In general it should be understood that the Civil Works Administration is anxious to get people to work immediately, and will cooperate to the greatest possible extent to facilitate a speedy execution of our program.

SCHIDULES

Orders for mailing schedules in adequate numbers to all the States were sent to the Government Printing Office on Tuesday and Wednesday, December 26th and 27th. Due to the press of emergency work in that office, not all the schedules were mailed out at the same time, but we have been told that the last were mailed January fourth. If an adequate supply does not arrive by Wednesday, January 8th, please telegraph us. In the meantime, enumerators who have already been employed can be put to work on mimeographed copies of the sample schedule that was sent you, the cost of mimeographing to be paid from your allotment for other than personnel. The data should later be transferred to the printed schedules before tabulating.

TABULATION SHEETS

The county tabulation sheets are being mailed daily. Since the clerks will be able to tabulate much faster than the enumerators can gather the data, it is not necessary for you to have the tabulation sheets as soon as the schedules. The State summary sheets and instructions will be sent later. The county data will be in such form that the State summaries will be a comparatively simple matter. We have estimated that each county will need thirty sets of tabulation sheets, and have sent them out on that basis. Since it is difficult to estimate how many will actually be used, you may need more. If you find as the work of tabulation progresses that you do need more, notify us of the number desired and we will supply them.



FRANKING PRIVILEGE

It has been decided through the cooperation of the Extension Service that the Extension stationery and franked envelopes can be used for correspondence in connection with the Eural Housing Survey. If necessary, the State Extension Office will be reimbursed for this expenditure for stationery, we are sending to each State Chairman an adequate supply of Bureau of Home Economics franks for use in the mailing of large quantities of material. These can be used on Hamila envelopes purchased locally, for the mailing of schedules,

TRAVEL

A new ruling has recently gone into effect throughout the country on the payment of travel by the Civil Works Administration. The State Civil Works Administrators were authorized on December 28th to pay travel expenses for approved Federal projects upon properly certified vouchers from Federal Emergency Relief Administration funds, until January 7th. After that date, travel authorized in connection with the Rural Housing Survey, including expenses of field workers where they are not included in their wages, will be paid by the Department of Agriculture through the Extension Service according to routine procedure. The money to cover travel expenses will be transferred from the Civil Works Administration to the Department of Agriculture next week. While there may be some delay in making this money available, travel will be paid. The money will be deducted from the sum allotted each State for other than personnel. It must be disbursed in accordance with Civil Works Rules and Regulations No. 12, a copy of which we are mailing under separate cover.

CHADGE IN NUMBER OF PERSONNEL

A number of States have requested a change in their allotment of personnel to employ more persons for a shorter time. We have not yet been able to get a definite decision from the Civil Works Administration on the few changes of this kind that we have already submitted for approval. Therefore, our advice is for you to employ your full quota of personnel and go ahead getting as many schedules as possible in the time left. Care should be exerted to finish townships or similar small political areas for the purpose of gathering data comparable to census data. There is a possibility that the time will be extended to enable each State to have the full five weeks for field work as originally designed, but every effort should be made to complete it within the allotted amount of time.

TELEGRAPH AND TELEPHONE

The State Civil Works Administration should pay for telegraph and telephone expenses from your allotment for other than personnel. Where administrative expenses are unusually high we may be able to pay such items as
telephone and telegraph bills from our central administrative fund; but there
can be no increase in State budgets at this late date, and it is desirable
to cut down administrative expenses to the minimum. The State Civil Works
Administrator will supply you with the proper forms and vouchers for telephone, telegraph, rental, supplies and other Expenses other than travel and
personnel.

the control of the co

JUNAST.

the parament is greatly your into effect throughout the country of the parament of paraments of the parameters of the parameters of the parameters of the state of the state of the parameters of the parameters of the parameters of the parameters of the property of the parameters of the pa

ANTIBLAST TO SUR BIG HE SANSON

i surbst of cares have requested a change in their elations of persons of persons of the surial states and portions and a confidence that it should not be not to some and the following courses and the following that a confidence of the source of the sour

WHAT BULLT GOVE THAT THERE

The dealer of the constant of the period that pay for tolograph and holes here expense administrative engages of the constant of the period period of the same and the follows out contrative on pay such items and taliphone and relegantly bills from out contrat administrative funds to taliphone and the tends but there to the contrative funds of the tends of the tends of the tends of the contrative expenses to the minimum. The limit of the contrative for the former fines and venezing for telesticions, in the tends the tends the tends of the tends the tends the tends of the tends the tends of tends of the tends of the tends of tends of the tends of tends of the tends of the te

VAGE RATE

The hourly wage rate was worked out on the basis of a thirty-hour week. In no case should the weekly wage exceed thirty times the maximum hourly rate suggested.

THEKLY RUPORTS

We were able to report 2174 employed persons at work on this project throughout the country last week. Our allotment of personnel is 4,992 and we hope to have this quota filled by the end of next week. Several States did not get their reports to us in time to be included. The reports must reach this office by Monday of each week. They should include all persons employed during the week, from Saturday to Friday, including those expected to be on the payroll of the following Saturday. Some weeks the report will not vary from week to week, but it should be sent in nevertheless. The forms sent you for county reports should be used, with a notation regarding the number of persons employed in the State Office. In order that these reports may reach us each Monday, they should be sent the previous Friday by special delivery or air-mail, and not by telegraph unless it is absolutely necessary in order to get them in on time. The comments written on last week's reports have been very helpful in giving us concise statements of progress and difficulties.

Louise Stanley Chief

Louise Stanley

and the land

្រុះ ប្រទេស ប្រជាជនជាតិ មានប្រជាជនជា ប្រជាជនជា ប្រជាជនជា ប្រជាជនជា ប្រជាជនជា ប្រជាជនជា ប្រជាជនជា ប្រជាជនជា ប្រ ការស្រាស់ ស្រាស់ ស្រាស់ ស្រាស់ ស្រែក ស្រែក ប្រជាជនជា ស្រាស់ ប្រជាជនជា ស្រាស់ ស្រាស់ ស្រាស់ ស្រាស់ ស្រាស់ ស្រាស ស្រាស់ ស្រាស់

The state of the state of

the office of the entropy of the configuration of personal designations of personal designations and entropy of the configuration of th

en de la capità de la produce de la capità de la cap

त्ति काराधकीय । राष्ट्रके प्राच्छी । दिलके स्थि Firm Hone a army)

UNITED STATES DEPARTMENT OF AGRICULTURE

BUREAU OF HOME ECONOMICS WASHINGTON, D. C.

January 15, 1934

FARM HOUSING SURVEY - 1934

BULLETIN TO STATE AND COUNTY CHAIRMEN: COUNTY TABULATION SHEETS

The "Summary Sheets for Engineer's Survey Schedule" (3 pages to a set) have all been mailed out. The tabulation sheets for the main survey are being mailed to you today. The number of farms and the number of townships (shown in the 1930 Census Report) have been considered in estimating the number of tabulation sheets necessary for each county. It is observed that the number of farms per township, especially in the Western States, is frequently very . small. In those cases it is permissible for you to tabulate more than one township on a sheet, for example there may be three farms, occupied by white owners, in Township Number 1, and six farms occupied by white owners in Township Number 2. The schedules for the white owners in Township Number 1 may be tabulated on the first three lines of the White Owner sheet and totaled. A heavy double line should then be drawn. Township Number 2 should be inserted on this line and the six schedules for the white owners in this township tabulated on the lower part of the sheet and totaled.

We are sending the tabulation sheets directly to county chairmen in all cases where we have a complete list for the State. Otherwise we are sending the total number for the State to the State Chairman. There are six sheets to the set. We are sending them out unassembled, that is by pages instead of sets, and they will have to be assembled in the State or County Offices.

Yours sincerely.

Louise Stanley Chief

8301 10 m 31 3

apply that with the

with a second of almost and he we have

Commence of the second second second second

The state of the s

Farm Harring Survey

BUREAU OF HOME ECONOMICS FARM HOUSING SURVEY

January 20, 1934

NOTICE TO STATE CHAIRMEN

You are no doubt puzzled regarding the recent orders sent out by the Federal Civil Works Administration to the State Administrators regarding purchase of supplies and reduction of hours per week in certain classes of workers. These orders are a temporary expedient, we hope, to enable the Vivil Works Administration to check-up on its present financial standing. The regulations regarding reduction of hours do not apply to our workers as they are all working in clerical or supervisory capacities on a thirty hour week. However, you will not be able to add any new names to your payroll while this order is in effect, except to replace workers discharged and fully paid off. Therefore, it is not advisable to lay off any personnel. You may have to transfer enumerators to clerical positions. Supplies already purchased will be paid for ultimately.

We have been asked to give a report to the Civil Works Administration on the obligations against our appropriation for other than personnel and the balance which will be required to carry our project through to February 15. We must have this information from your State at the earliest possible moment. Therefore, will you add it to the blank sent you on January 17 (CWHE-37); or if that blank has already been forwarded, telegraph it to us on Monday.

The information we desire is the total amount of your appropriation for other than personnel which has been expended to date; the amount of this expenditure which has already been paid by the State C.W.A; and the estimated balance which will be required to carry you through to February 15 at the very lowest figure. In calculating these figures, count in your travel, as it has not yet been transferred from your State allotment for other than personnel. A letter of information on travel will follow the first of the week.

In no case do we advise laying off personnel until February 15 at least, unless the survey is completed.

Yours sincerely,
Louise Stanley

Louise Stanley, Chief

BURRAU OF BOME ECONOMICS FARM HOUSING SURVEY

January 20, 1954

NOTICE TO STATE CHAIRMEN

You are no doubt puzzled regarding the recent orders sent out by the Federal Civil Forks Administration to the State Administrators regarding purchase of supplies and reduction of hours per week in certain classes of workers. These orders are a temporary expedient, we hope, to enable the Wivil Works Administration to check-up on its present financial standing. The regulations regarding reduction of hours do not apply to our workers as they are all working in clerical or supervisory capacities on a thirty hour week. However, you will not be able to add any new names to your payroll while this order is in effect, except to replace workers discharged and fully paid off. Therefore, it is not advisable to lay off any personnel. You may have to transfer enumerators to clerical positions. Supplies already parchased will be paid for ultimately.

le have been asked to give a report to the Civil Works Administration on the obligations against our appropriation for other than personnel and the balance which will be required to carry our project through to February 15. o must have this information from your State at the earliest possible moment. Therefore, will you add it to the blank sent you on January 17 (CWAR-27); or if that blank has already been forwarded, telegraph it to us on Monday.

The information we desire is the total asount of your appropriation for other than personnel which has been expended to date; the arount of this expenditure which has already been paid by the State C.V.A; and the estimated belause unich will be required to carry you through to February 15 at the very lowest figure. In ealoulating these figures, count in your travel, as it has not yet been transferred from your brate allegant for other than personnel. A letter of information on travel will fellow the first of the week.

In no osse do we advise lajing off personnel until February 15 wt least, unless the survey is completed.

Yours sincerely,

Louise Susmiey, Chief

UNITED STATES DEPARTMENT OF AGRICULTURE BUREAU OF HOME ECONOMICS WASHINGTON, D. C.

January 23, 1934

BULLETIN TO STATE CHAIRMEN *** FARM HOUSING SURVEY - C.W.A. - NO. II

PERSONNEL

(THE INFORMATION CONTAINED IN THIS BULLETIN IS STRICTLY CONFIDENTIAL)

On Saturday, January 20th, we sent out a letter explaining the interpretation we had been able to get at that time of the new Civil Works ruling as it applied to our project. This will confirm our statement that it is advisable not to lay off personnel before February 15th.


As I understand it, the C.W.A. may want to continue employment of our personnel beyond that date, transferring them to other projects. The allotment of five weeks for the field workers and ten weeks for the other personnel was made by us, and the C.W.A. is not concerned with it. In fact, the C.W.A. is set up on a basis of so many employees to a project and not on a money basis, except in regard to the allotment of funds for other than personnel. Any saving in salaries or wages reverts to the C.W.A. rather than to this project and there can be no transfer of such savings to other parts of our budget. There was no limitation of time (up to February 15th, of course,) in the authorization sent by Mr. Hopkins to the various State Civil Works Administrators.

Give us a week's notice before the completion of the project in your State, in order that we may advise the Federal Office of the C.W.A. that your personnel will be free. Although no authorization has yet actually been made for the continuation of C.W.A. activities beyond February 15th, we are advised to keep our workers on the payrolls until definitely notified to discontinue them.

We have been asked to close out the work in the far southern States by February 10th, if possible; as C.W.A. activities will be curtailed in those States with the coming of warm weather and the opening up of opportunities for employment.

ENGINEERS' SURVEY

de have hed numerous requests for additional Engineers' Schedules and Tabulation Sheets. This is due to a misunderstanding of the extent of the Engineers' Survey. While the engineers were advised to choose one in ten of the schedules for further investigation, it was not intended that they should cover ten per cent of the main survey. We shall be satisfied to have one hundred Engineers' Schedules for County. In fact, we did not have enough printed to supply more. We have on hand



Bulletin to State Chairmen FHS----- No. 2

-2-

enough to allow twenty-five more to each County and will be glad to mail them out in that proportion upon specific request.

CHECKING OF SCHEDULES

State Chairman should call in from each county a number of schedules as soon as they are tabulated for the purpose of checking the editing for inconsistencies within the county and the State as a whole. We should appreciate having a report of the results of such checking at your earliest convenience.

Yours sincarely,

Louise Stanley Chief 71. E. Fare to During

TRIETY STATE DE LA TOUTOUR SASLINGTELL, D. G.

1911

Jumary 30, 1934

LANCESTER TO RELL CHIEFTY - -- FAR'S SCHOOL & SUPPLY

The Civil Jorks Administration has just ruled that our sersonnel, supervisory, clerical and field, will have to be cut to thirty thirty-ninths of their original wages even where they are paid a flat r to for a thirty-hour week. In applying to field workers, the order covers only the basic portion of the pay, and not any sanclement that covers trans-nortation.

loss than half the wookly reports arrived on time this week. It is important for the success of the project that we be able to make a complete report each week. It is not necessary to have the simeographed forms that were cent out for this report as long as the required information is included. Figure see that these reports reach we on Monday of each week. Notes on the progress of the work will be greatly appreciated.

Yours atmosraly,

Louise Stanley Chief



prof. Or organismos

The sound of the sound will be approximated the sound of the sound of

to the form that a decided the first of the form of the first of the form of t

The first state of the second of the state o

A TANK I SHOW

Fr.



Fair Housing Co.,

TEX - 1983

FUNCTIONS OF THE PARTITIONS.

Instructions to the Home Demonstration Agent

Please read the entire blank before filling in any of the answers.

Use a lead pencil, so you can readily make corrections.

Answer each question as it applies to the families of the farm women with whom you most commonly deal in your home demonstration work.

Please contribute additional information, if the questions fail to bring out the important characteristics of the plan of a farmhouse which fits the needs of the typical farm family.

and the second of the second o

general and a second of the se

ganta en la propière de la companya Ren 1917 de la companya de la compa La companya de la co

FUNCTIONS OF THE FARMHOUSE

Name of Home Demonstration Agent
Address
How many years have you worked in this county?
A - HOUSE PLANNING
I. The object of this section is to obtain as complete a list as possible of the major
features characterizing the farmhouses which are best suited to your climate and to the ways
of living and the preferences of your farm families.
II. Answer each question as you think your "average" farm woman would answer it, judg-
ing from the ideas incorporated in houses recently built or remodelled, or from what you know
as to the house planning ideas and preferences of farm families.
III. Unless otherwise indicated, use a check (1/2) to show preference.
1. Where should provision be made for eating meals: in kitchen nook off kitchen
dining room part of living room ?
2. How would the dining room or dining end of living room usually be used: for company meals
only for part of everyday meals for all of everyday meals ?
3. Should laundry be done in basement kitchen •ther room on first floor porch
separate building ?
4. Should canning be done in kitchen other room on first floor basement or
separate building ?
5. Would you have men wash in special washroom in house in special wash room away from
house in laundry room in kitchen on porch ?
6. Should farm help be lodged in the main house: Yes No If so, which location is preferred
for a hired man's room: first floor or second floor ? Should the room be heated:
Yes No Should special toilet facilities be provided for it: Yes No If so, what
fixtures ? If on the first floor,
should it have an entrance leading directly to the outdoors: Yes_No_?
7. Which location is preferred for the parents' bedroom: first floor or second floor?
8. Should arrangements be made for heating family bedrooms: Yes_No_
9. Should a separate room be provided as the farm office: Yes_No_ If not, should the desk
used by the farm operator be located in living room dining room other room (state)
10. For what needs is it desirable to provide out-of-door arrangements in warm weather: Sleeping:
entire family young persons only Dining: continuous use dining occasionally
reading and resting sewing preparation of vegetables washing ironing
other (list)?

the part of the second of the

• And the state of the state of

A company of the state of the s

and the second of the second o

the state of the s

the second secon

Stat	County H.D.A.
11.	What arrangements are most convenient for outdoor activities: Covered porches, screened
	Covered porches, not screened terraces or porches, with floor, but without roof ?
12.	Should there be a pantry, storage closet, or storeroom opening directly from the kitchen:
	Yes_No_ If so, how would it be used: cooking utensils and equipmentstaple groceries
	jellies and jams canned foods in tin canned foods in glass other (state)
13.	Should there be bullt-in kitchen cupboards? Yes No If so, should they be closed
	or open?
14.	Would you have a built-in ironing board or boards If so, where: kitchen laundry
	sewing room diningroom living room porch other (list)
15.	Should a shower bath or baths be installed: Yes No If so, where: basement mens'
	wash room bath room other (list)
16.	Should the telephone be located in from hall back hall living room dining room
	kitchenother (state)
17.	Should the radio be located in the living room or other room (state)
18.	What is the maximum number the living room should seat comfortably for social occasions?
19.	Should space be provided in the living room for writing desk: Yes_No_? Davenport: Yes_
	No_ Piano: Yes_ No_ other articles of furniture (list)
20.	Would you provide for a fireplace in the living room: Yes_No_ other rooms (list rooms)
21.	For which of the following forms of amusement should provision be made? For how many
	persons? Dancing table games (crokinole, cards) other (state kind) ?
22.	Should provision be made for house plants: Yes No If so, for about how many ?
23.	What floor covering is preferred for bedrooms: carpet large rug* small rugs*
	linoleum ? What floor covering on living room: carpet large rug* small rugs*
	linoleum ? What floor covering on dining room: carpet large rug* smallrugs*
	linoleum? *Fabric
24.	Where should the following be located?
	:Separate from : Attached to or : Reason for decision
	:dwelling : part of dwelling:
	1. Milk room
	2. Egg room
	3. Farm shop
	4. Garage Food storage
	5. (Roots, potatoes,

.

71 1	O	77 T) A
State	County	H. D. A.

25. What are other characteristics of a farmhouse suited to the needs of your group? List and give reasons for including them.

B - WORK DONE AT HOME

I. The object of this section is to obtain information as to differences in requirements for work areas among the households of the women with whom you deal in your demonstration work.

Activities:

fable I	
Item	: Percentage of : households - (1) (2)
1. Fruits and vegetables canned (most of supply used by household)	
2. Meats and fish canned (most of supply used by household)	:
3. Meats cured (most of supply used by household)	
4. Fruits or vegetables dried (most of supply used by household)	:
5. Butter made (most of supply used by household)	:
6. Yeast bread made (most of supply used by household)	: :
7. Milk utensils washed in house	:
8. Eggs packed in house	:
9. Poultry dressed for market (in cold weather)	:
10. Sewing done (requiring use of machine)	:
11. Washing done	: :
12. Shoes repaired	:
13. Soap made	: <u>: </u>
	:

⁽¹⁾ It is expected that your answers to the questions calling for percentages will be estimates. If you have factual information on any of these points, please note in the margin.

⁽²⁾ Percentage of households in which process is done to total households considered,

•

. .

**

the state of the first of the state of the s

4 .

State	Cour

Table II	
	:Percentage
Methods and workers	:Households (1) (2)
1. Most of canning done in tin	: %
2. Pressure canner used	
3. Canning done in small amounts at a time along with regular housework	<u>:</u>
4. Canning done in large amounts at a time	:
5. Washing done by homemaker or other member of the family	<u>:</u>
6. Washing done by laundress	
7. Sewing done by homemaker or other member of family	
3. Sewing confined to made-overs, underwear, childrens' clothes, etc.	
9. Womens' new silk or wool dresses made, as well as articles listed abov	c:
10. Sewing concentrated into months when other work is not heavy	
11. Sewing scattered through year or done as need arises	
12. Sewing machine used	:

C - OTHER INFORMATION

I. Kinds of fuel customarily used:

	For Heating			For Cooking	
	Kind	Percentage of Households (1) (2)		Kind	Percentage of Households (1) (2)
1.	Wood	6/, /*,	10.	Wood	%
2.	Soft coal		11.	Coal	
3.	Hard coal		12.	Corncobs	
4.	Corncobs		13.	Gas	
5.	Gas		14.	Electricity :	
6.	Electricity		15.	Gasoline	
7.	Gasoline		16.	Kerosene	
0.	Kerosene		17.	Oil	
9.	Oil		: :		

It is expected that your answers to the questions calling for percentages will be estimates.
 If you have factual information on any of these points, please note in the margin.
 Percentage of households in which process is done to total households considered, for example, if 100 households were considered and 10 of these do most of their canning in tin 10 per cent should be entered opposite item "I".

tion of the second of the seco Company of the Compan - Commission of the second of and the second of the second o

the state of the s and the second and the contract of the contra

and the second of the second o and the control of th

the second of and the second of the second o

and the contract of the contra

State	County H.D.A.
II. Ho	usehold Water Supply
	n what percentage of farms is the amount of water adequate for household uses (that is,
	ing use of septic tank and water system at all times of year) ? On what percentage
	s is there likely to be a shortage of water occasionally for short periods? On
	reentage of farms is the household water supply inadequate most or all of the time?
_	s well water seft medium or hard ?
	ERAL INFORMATION CONCERNING FAMILIES REACHED BY THE HOME DEMONSTRATION PROGRAM.
	ect of this section is to enable the person in charge of the study to compare and
	y returns from various states and to determine the relation between the farmhouse
	d various geographic and social factors.
T. Cli	
	hat are the major characteristics of the climate of your area which influence
	ousing arrangements?
	irection from which come: Cold winds hot winds cooling winds in warm weather
	in A.M. in P.M. at night driving rains
Ni	umber of months are characterized by continuous sunshinecloudy weather
	weather cold enough to require heat other than that supplied by the kitchen stove
	weather warm enough for outdoor activities without extra wraps
	warm nights little or no rainfall
II. Ma	jor farm enterprises:
1.	On what percentage of famus is the only, or the major enterprise yielding a cash return:
	Poultry _Cattle, Hogs, Sheep, Dairy, Orchard fruits, Small fruits
	Vegetables ,Grain ,Cotton ,Tobacco ?
	, , , , , , , , , , , , , , , , , , , ,
	What percentage customarily produce for house use: enough milk eggs and
	poultry, pork, potatoes, apples, cabbage, root vegetables,
	summer garden truck?
III. R	oads:
1	. What percentage of farm houses can be reached by auto during all months of year?
2	• What percentage cannot usually be reached by auto during two months or more?
	Due to what: Snow, high water, mud, other (state)?
IV. Ut	ilities and services:
1.	What percentage are now connected with electric power line, with piped gas?

production of the control of the con

The second secon

 A continue to the continue of the

the property of the transfer of the second s

n de la companya de la co

And the second

The second secon

ch i

0621	b C	County
v_{\bullet}	Cha	racteristics of families reached by home demonstration program.
	1.	What percentage are white, negro, Mexican or Indian?
	2.	For what percentage of white households do ways of living show pronounced foreign
		influence: Dutch, German, Swiss Scandinavian, Russian, French
		Italian, Spanish, Portugueseother (state)?
	з.	Do you think that your replies to the questions in foregoing sections would have
		been about the same if you had answered for all farm families in the county? Yes No
		If not what are the main points of difference?

UNITED STATES DEPARTMENT OF AGRICULTURE 43

BUREAU OF HOME ECONOMICS

Washington, D. C.

Dear

One of the purposes of the C. W. A. Rural Housing Project which has the approval of the Federal Extension Service, is to provide well planned low cost farmhouse plans which may be used by the Extension Service workers in giving assistance with remodeling and new construction needs that are being unearthed through the Rural Housing Survey. We find that we lack certain information concerning the housing needs of typical farm families in the various areas of the United States, in order to make sure that the suggestive plans for each area are adequate and suitable.

We feel that the county Home Demonstration Agents are best qualified to give us this information because of their intimate contact with rural homes, and have therefore worked out a plan to secure these data through them. Attached you will find the following material which explains in detail the plan:

- (1) A letter to be sent to Home Demonstration Agents.
- (2) A description of the study.
- (3) A blank to be filled by Home Demonstration Agents.
- (4) A plank to be filled by five farm women under the direction of the Home Demonstration Agent.

After discussing the matter with the Home Management or Home Improvement Specialists and other persons interested, will you kindly send us a list of the Home Demonstration Agents in your State whom you consider would have the necessary experience and background information to fill out the enclosed blanks? Probably all of your agents except those who have been appointed very recently would be able to give us the needed information.



Janes.

We will then write direct to the Home Demonstration Agent, or, if you prefer, the supply of letters and blanks can be sent to your office for distribution.

There is also attached one sheet headed, "To the State Home Demonstration Leader, Home Management or Home Improvement Specialist". We would appreciate having you, the Specialist and District Agents fill out this sheet so that standards for house plans may be set up on the basis of areas. We would also appreciate it, if you would be willing to have the Home Demonstration Agents send the survey blanks to your office, so that they may be checked for errors before they are sent to me.

You will be interested, I am sure, in learning that Miss Maude Wilson, Purnell Research Worker, College of Agriculture, Corvallis, Oregon is in charge of this phase of the Rural Housing Survey program and she will make the analysis and set up the standard as a result of the information the Home Demonstration Agents send to us.

Will you kindly send me as soon as possible the list of Home Demonstration Agents, whom we may ask to cooperate with us? At the same time please notify us whether you prefer sending the letters out from your office or whether we should address the letters direct from this office.

Very truly yours,

Louise Stanley, Chief

Louise Stanley

. Control of the second second

Frim Nove

FUNCTIONS OF THE FARMHOUSE Description of Study

Objective in Study

Recently a survey of rural housing conditions in the United States was undertaken as a Civil Works Administration project. This survey is expected to reveal the nature and extent of the need for improved rural housing facilities. In addition to the survey, the Civil Works Administration grant is making it possible to employ architects to design houses suitable for various areas. These plans will be available for those who wish to build new houses or to remodel, and will be helpful to agents and specialists who undertake home improvement programs.

It is a matter of importance to Home Economists that these house plans, as well as farmhouse plans which appear in books, bulletins, magazines, newspapers, and mail order catalogues, be well suited to the needs of the families for which they are intended. As an aid to designers it is proposed that check lists of recommended features for rural house plans be prepared for each climatic section.

The enclosed questionnaire asks for certain information concerning the work of the home and preferred housing arrangements, as it applies to the families with which the Home Demonstration agent deals. Such data are almost entirely lacking but are necessary if the preposed check lists are to represent, completely and accourately, the housing needs of farm families in the various sections of the country.

The plans now in preparation in the Bureau of Agricultural Engineering of the United States Department of Agriculture and in various states vary in cost, on the following scale:

Region	: First Price Hange	: Second Price Range	: Third Price Range :
Eastern States	: Under \$1500	: : \$1500 - \$3500	\$3500 – \$7000
Central States	: Under \$1500	\$1500 - \$3500	\$3500 - \$7000
Southern States	Under \$ 750	: : \$ 750 - \$2500	\$2500 - \$5000
Western States	-Under \$1200	\$1200 - \$3000	\$3000 - \$6000

The check lists of functions will apply in the main to the housing needs and preferences of the farm families who would build houses within these cost ranges.

 $\mathbf{e}_{i}(\mathbf{r}) = \mathbf{e}_{i}(\mathbf{r}) = \mathbf{e}_{i}(\mathbf{r}) = \mathbf{e}_{i}(\mathbf{r}) = \mathbf{e}_{i}(\mathbf{r}) = \mathbf{e}_{i}(\mathbf{r})$

Market State of the State of th The state of the s

 \mathbf{v}_{i} , \mathbf{v}_{i} , \mathbf{v}_{i} , \mathbf{v}_{i} , \mathbf{v}_{i} Some of the questions do not apply directly to the house planning problem, but are included to give the person summarizing the data a basis for judging the "Representativeness" of the type of family the Home Demonstration Agent has in mind.

Method of securing information.

- 1. Home demonstration agents are asked to furnish information for the families with whom they deal as to the work done at home and as to housing arrangements preferred or considered desirable.
- 2. Home Demonstration agents are also asked to locate farm women who will supply information for their own homes as to the kind and amount of material for which storage rooms and cabinets should be provided.

*

STORAGE REQUIREMENTS

Section II.

To the Homemaker

Good house plans are a great help to the family desirous of building a new home or of remodeling the old one but many of the plans which appear in magazines and newspapers are poorly suited to the needs of farm families with respect to storage facilities.

You are one of a number of homemakers who have been asked to supply information as to the kind and amount of supplies and equipment stored in the farmhouse. Your cooperation in this study will be valuable in that it contributes to the fund of information needed by designers in determining the kinds of storage facilities to plan for the farmhouse, and the capacity of each. It constitutes a definite contribution, therefore, to the movement for more convenient homes.

Instructions

Read the entire blank before filling in any of the answers. Use a lead pencil, so you can readily make corrections.

Answer each question as it applies to the normal practice of your own household.

Contribute additional information if the questions fail to indicate the kind and amount of storage space needed in your home.

Return the completed blank to your Home Demonstration Agent unless she directs otherwise.



, ÷ .

									ď	WHE - 45	<u>.</u> A
State			- 1	· ·	County			Coope	rator_	1	
7/40-1				4		1 1 1 m 3 m	and the	•••			
.,	·• - 1	ر الم	N _e		TORAGE REC	DUIREMENTS	4.0				
•				•		The state of the s					
Name of	he go	perat	or			Address	 Literandocarponio		-		Seciliare and design, the second
Usual nur	iber of	pers	ons for	whom meal	s are seri	red :	-		ti. Department descripted de l'este en en	•	
						·					
						ES FOR HOM	USE				
1, 0	heok. (in.	colum '	'2" of the	table fo	llowing, th	he food	i suppli	es whi	ch you bu	A OL
produce	n quar	itities	s. The	meximum o	uantity for	llowing, the residence of the constant of the	torage	space i	s requ	ired shou	ld be
mark (*)	in col	lumm *!	5". If	the space	requirement	int varies	for the	ic produ	ct, wr	itc in na	me of
one moner	12 M:11C	odi interes.	Milan 200	i spac	C Is regar	z :	or minus	- Fr /			
		ámen me			many and spirits between the second				يات د المسم راة	a f artiselise variantisetatetitismi.	L.
Product		Qua	antity	Sterage	space	:Product		Quanti	ty :	Space n	eeded
Col,1	Col.2	Unit Col.3	Number Ccl 4	Constant Col.5	Varies Col.6	:Col. 1	Cols2	Unit : N Col.3:0	umber:	Constant:	Varies Col. 6
	(4)			(4):	Months :		(20)	· 3	8	(1)	Months
Butter		lbs			seed to see the see	: Apples	\$ 10 mm	hu			in the second second
Til sta		į.		e de la companya de l			• . • ·		?	*	
Eggs, fresh		doz	ž į		40.00	Pears	State of the	bu		3	والمرواسف بالموسيد والتوا
			•	=	i i						1
Eggs in a	;			Water Control					i d Januaria di		. 4
glass		doz		andioministicana altanoi	-	Corrots	-	hu			-
Mest	,		9				to many	:		<u>.</u>	
fresh	the state of the state of	pieces			· ·	Beets	<u>}</u> :	bu	***************************************		
) (h a d		74.	:	,		410	:		5		
Meat smoked		picos	8			Turnips	.	lbs	0 0 0		
		4:	2		or all other representations		7 \$ &4		ਦੇ ਦ	4	
Lard		gal				Cabbage		lbs	:		e-
						:					
Vinegar		gal				Squash Pumpkin	4		٠ ۽		
23.5						FULLDICIN	}	ccan			ekoninasi (1880-lung) (1881-lung) (1881-lung) (1881-lung) (1881-lung)
Fruit, dried		bu	: 2	1			()				
Beans	V	Da				Potatoes		bu			
and peas					The grant would	Sweet	and the second				
- described and a second		bu			Marian A	Potatocs	2	bu		\$	
7			:	* , :		F .			:		
Honey		lbs				Ontons	1	bu f	:		· · · · · · · · · · · · · · · · · · ·
			:				\$		8.	:	
Nuts		bu			Differ a		•		, t	, , , , , , , , , , , , , , , , , , ,	

gradient finanzier der Gradien der Gradien

- 2

State	Count	У	Cooperator	

2. Enter in column "2" of the following table the number of containers of preserved foods which you have on hand when your supply is at its maximum. If the quantity varies considerably from year to year indicate the range in column "3". Do not include foods put up for sale.

Containers for preserved foods

Glass			Tin			Stonejars, crocks, etc.			
oic : Quantity :Maximum : Range			Can Number :	: Quantity : Maximum: Range		Size	: Quantity :Maximum : Range		
0 1.	· Col.2	: Col.3	Col. 1	Col. 2	Col.3	Col. 1	: Col. 2:	Col. 3	
Callon	No.	No.	No. 3 and smaller	No•	No.	å gal to l gal	No.	No.	
3 quarts	:	: : :	No. 5 and N. 10			2 to 5 gal.	:		
2 quarts	:	:	Larger tins			6 gal and more	:		
l quart	:	: : :				Kegs and barrells (State size)	:		
l pint	:	: : :	: : :			: :	:		
Julicy Masses, Lottles	:	:				: :	:		

3. Check (/) in column "2" the staples which you keep on hand. Enter in column "4" the starty for which storage space is required in kitchen, pantry or other storage room.

cod	Check	Quantity		:Food	Check		
Jol. 1		Unit Col. 3	: Col. 4		Col.2	Unit Col. 3	: Number : Col. 4
hard wheat	(~)	lbs	:	.White sugar	(~)	lbs	:
mest wheat		: lbs	:	: Brown sugar		lbs	
Fahan or whole	•	lbs	:	Syrup molasses		gal	
logrmeal		lbs		: Raisins		lbs	:
Pancake flour	:	lbs	:	Crackers	: 	lbs	:
Utke flour	:	lbs	•	Shortening		lbs	<u>.</u>
Broakfast		lbs	: : :	Salad oil		qts	:
Rice		lbs					:
Macaroni	:	lbs		:			:

.

.

· v

ng ,

. . . .

States					County			Co	opera	tor		
one time:	(a) lo	oaves	of brea	rd	,	(b) co	ing baked g			, (c) C	akes	
quantitie quantity column "5 hand in c	es that which y 5". If column "	it do you ha the o	pes not ave on l quantity	pay to land in sis va	umn "2" to provide n column aries ent	he com specia "4".] er the	al storage If the quan names of t	ich yo facili tity i he mon	u proc ties : s con ths i:	duce for for ther stant, r n which	n. En make a the m	in such small ter the maximum check mark (**) aximum is on
Jormodity	Check:	Ilnit.	Turnher	luanti	ty Varie	S	: :Cormodity	:Check	: : :IImi+	Qu:	antity	Vonica
Col. 1	Col.2	Col3	Col.4	stant Col.5	, , , , , , , , , , , , , , , , , , , ,		:Col, 1	: :Col.2	:	: Manner	stant	. 451.162
nggs	(1/):	Cascs	No.	(4/)	Month		:: ::Peas, ::Beans.drv	: (*/) : :	: : bu	No.	: (~) :	: Month
Cream		gals					:: ::Apples	: :	: :bu		:	
uttor		lbs	,				:Potatoes	: :	bu	•		Varies Month
onev	: :	lhs :				:	Can goods	:	:doz	:	:	
yrups,						:	:	: :	:			
li. FUEL 1. What is the maximum amount for which storage space should be provided on the home place: (a) Wood:(cords), (b) Soft coal:(tons), (c) Hard coal:(tons), (d) Kerosene:(gal), (e) Gasoline:(gals), other (state kind and amount)												
The following information is needed in order to estimate the amount of cupboard space needed												
	the kitchen and dining room: 1. How many cooking utensils do you have now, which will hang? (Sauce pans, skillets, etc.)											
Manage have an observation state a part supported	How many which require shelf space (kettles, baking dishes, etc.)											
low many												
2.	Do you	have	dishes	that	are used	mainly	for compa	ny meal	ls?	Ces_No	· :	If so, how
may pieces that are not usually used for every day meals?												

5 description 1 2 1 2 2 3 5 5 5

\$ 10 mm (1) 10 mm (2) 10 m

en de la companya de

oodpor a voi
V. <u>EQUIPMENT</u> <u>USED</u> IN HOUSEHOLD <u>OPERATION</u>
1. Enter the number of number of each of the following articles of household equipment
for which storage space is required: (a) carpet sweeper, (b) vacuum cleaner,
(c) weighted brush, (d) portable fan, electric, (e portable heater
(1) washing machine, (g) portable electric sewing machine
(h) foot power sewing machine?
2. How many pieces of bedding (blankets, quilts, comforters) are not usually used (a)
in winter, (b) in surmer?
3. How many pieces of bed linen (sheets, spreads, pillow cases, etc.) are not usually used
(a) in winter, (b) in surmer?
VI. OTHER EQUIPMENT
1. How many large pieces of furniture, trunks, etc., do you store away?
2. For how many books is shelf room required in your living room or library?
3. How many articles of clothing are not usually in use (a) in winter,(b) in summer
?
4. What other equipment or personal possessions would need to be considered if you were
planning a house? Give detail as to kind, number, and size.

U → C+ → HTM

9. and the second s

Home Management Specialist

Home Improvement Specialist

District home Demonstration Leader

Could a single farmhouse plan be drawn which would be suitable for all parts of your state? If not, how many plans would be required? How would they differ? To what part of the state would each be suited?

Your answers to these questions will help us materially in the determination of boundaries of areas of the U.S. which differ in housing needs, and in listing the distinguishing characteristics of each.

A simple way of indicating the areas of your state will be to use an outline map, tracing the boundaries, and designating the areas by letters or by descriptive names.

The following information concerning each area will be helpful:

- 1. What counties or parts of counties are included?
- 2. Does the area include other states or parts of states? If so, describe.
- 3. What are the climatic, social, and (or) economic characteristics which distinguish it from other areas?
- 4. In what respects would a houseplan suited to the needs of the average family of this section differ from that of other sections of your state? Note inclusion or omission of specific features, as rooms or porches, points on arrangement of rooms, equipment, etc.



UNITED STATES DEPARTMENT OF AGRICULTURE

BUREAU OF HOME ECONOMICS
WASHINGTON, D. C.

Dear

In Connection with the Farm Housing Survey, a number of low-cost farm house plans are being drawn by architects and engineers which will eventually be made available for use by the Extension Service. We find that we need some information concerning the housing needs of typical farm families in the various areas in the United States in order to make sure that suggested plans for each area are adequate and suitable. Your State Home Demonstration leader has authorized me to write you for this information as it applies to the equaty in which you are now situated.

In considering your replies to the questions on this blank, please keep in mind the fast that we went a description of the family needs and interests of the "cyptical" farm family of your county. Naturally it will be the type you most often meet in your home demonstration work. If you have racial, national or income-level groups so diverse that you have to form separate units—in your home demonstration organization,—then pick the group which includes the largest number of families. We would however, be glad to have you send for more planks if you are willing to take the time to describe the housing needs of more than one group.

1.05

If you are in doubt about the answers to some of the questions, consult some of the farm women in your county who are "typical" in the sense that the habits, standards, and attitudes of their families are much the same as those of the group you are describing.

If studies have been made in your county which afford a factual basis for any of your replies, it will be much appreciated if you will attach copies of the results of your studies to this return.

The section II on, "Storage Requirements" will require some specific data from homes. Please select five farm women in your county and ask each one to supply this information for her own household. The information will be more accurate if you help each woman fill out the blank for her household. The women chosen for this contribution should be those whose households ordinarily include four, five or six persons for meals.

I am enclosing two copies of the blank we should like you to fill out, and ten copies of the section on storage requirements. The duplicates are for your own use if you wish to keep a copy of the information sent us. This information should be sent at the earliest possible date in order to be of the greatest usefulness. The completed questionnaire should be mailed to your State Home Demonstration Leader.

Sincerely yours,

Louise Stanley, Chief

Louise Stonley



UNITED STATES DEPARTMENT OF AGRICULTURE BUREAU OF HOME ECONOMICS FARM HOUSING SURVEY

February 1, 1934

MEMORANDUM TO STATE AND COUNTY CHAIRMEN:

Ful me ...

COUNTY TABULATION SHEETS AND SUMMARIES

We have been examining a few of the schedules and tabulation sheets which have been completed as statisticians of the Civil Works Administration have suggested that tabulations made in the counties will probably contain errors and inconsistencies. We have felt that this work could be done in the counties as carefully and as accurately as it would be done in Washington. Generally we have found that the instructions for tabulations have been followed carefully and that the work has been done accurately.

On one tabulation sheet examined, the clerk who made the entries placed check marks in Column 10 of Section C which should have been placed in Column 11 of Section C. As a result of these errors in tabulation the total showed 16 houses needing new exterior walls. The schedules from which this information was taken showed three houses needed new exterior walls and 13 houses had roofs in good condition. The picture is thus greatly distorted for these houses.

If the survey is to be of value the tabulation sheets and summaries must be absolutely accurate. In tabulating, one person should read from the schedule and a second person should make the entries on a tabulation sheet, using a straight edge to follow both the row and the column on the sheet. Folded paper or a ruler may be used as the straight edge. Two other persons should check the entries made on the tabulation sheet, one reading from the tabulation sheet and the other person looking at the schedule. Be sure that each entry is in the right row and column. Similar precautions should be made in entering the totals at the bottom of the page. For example, on one tabulation sheet a total of 50 is shown for Item 25 under Section G, "laundry equipment, hand machines." The total should have been entered in Column 26 of this section which is "cooking facilities, wood or coal stoves."

Persons tabulating these data and checking the tabulation sheet against the schedules should write their names on the upper left hand corner of the tabulation sheet.

If more than one set of sheets is needed in the tabulation of one township, the letters A, B, and C should be written in ink beside the sheet number and the last sheet of the set should contain the totals for the township.

Sincercly yours,

Louise Stanley Chief

\ * i.*

UNITED STATES DEPARTMENT OF AGRICULTURE BUREAU OF HOME ECONOMICS FARM HOUSING SURVEY

February 3, 1934

BULLETIN FOR STATE CHAIRMEN - NO. III

PAY CUT

We have been delayed in getting definite rulings and interpretations of recent C.W.A. orders because they did not fit our project. We now know that our workers must accept a cut of 9/39ths of their wages, whether they were on a thirty or a thirty-nine hour-week basis. In no case should their hours be cut below thirty. This cut does not apply to travel where it is included in wages paid by the State C.W.A. If you have any difficulty with this, ask your State Administrator to communicate with the Federal C.W.A.

FIELE, SE OF WORKERS

Release your workers as you no longer require their services, notifying us by telegran how many are released on or before the day they are released. Kindly continue to send in your weekly reports until your work is completely closed up in the State office.

PAYMENT OF TRAVEL AND OFFICE EXPENSES

In order to facilitate payment of travel and office expenses we are having our allotments for other than personnel transferred back from the States to our central administrative fund. Additional information on travel will come to you soon, as well as instructions for getting reimbursement for office expenses. We shall do everything in our power to adjust legitimate claims for reimbursement, as soon as we can decide upon the quickest procedure sanctioned by the Department of agriculture. Then you close up your work be careful not to send us duplicate vouchers for bills already submitted to the State auditor, unless he has refused to pay these bills and the claims have been withdrawn. Few of the States have asked to exceed their original budget for other than personnel, and we think we can take care of such requests for additional funds through the arrangement we are now trying to make. In view of the necessity to economize, stick as closely to your original budget as mossible. However legitimate expenses in excess of this amount will be met when accompanied by an adequate explanation. No more definite information regarding your budget will be sent you, as detailed accounting from this office of State budgets is impossible. If your State auditor refuses to pay travel incurred before January 7th and returns the vouchers to you, let us know and we talk send you another letter of authorization correctly dated to cover the period before January 7th.

CONTRUMENTAL OF FYILLD WORK

We have been informed that the enumerators may continue their field work beyond the five weeks' period originally planned if necessary and desirable. The notification sent the State Administrators by the Federal C. .A. placed no limitation of length of employment upon these workers. If your State Administrator requires confirmation of this authority advise him to get in touch with the Federal C.S.A. This decision can, of course, be over-ruled at any time by a Federal order dismissing C.W.A. employees in any given locality.

CLOSING UP OFFICES

Owing to unavoidable delays in the settlement of accounts, you will probably have to close up your county offices with some accounts still outstanding. The workers will be reimbursed at the very earliest possible date.

er Sangar (1997)

Hold the schedules and county tabulation sheets in the State office, forwarding the State summaries to us. Return any excess schedules and tabulation sheets to this office - using the franks we have sent out.

20.13


Please keep us correctly informed of the number of schedules completed, and also the number tabulated. We are expecially interested to know when the field work is completed in each county. This information might well be incorporated in the weekly report.

Mrs. Roosevelt has asked me to give a talk on the Farm Housing Survey next week at the Todhunter School. If you have any photographs of present housing or items of personal experience in connection with the work that might be used to furnish human interest please send them to me by air-mail immediately.

At times the delays in getting our project under way have been baffling, but let me assure you that its success is already being recognized. The cooperation of the Extension Service made it possible for our program to be organized very promptly, and has assured efficient cooperation in the field. The enthusiasm of all our workers has contributed to the success in gathering the data. One of the interesting aspects of the survey has been the interest displayed by the rural people. I am sure we all hope that a constructive program will be based on the needs that have been revealed.

Yours sincerely,

Louise Stanley
Chief



UNITED STATES DEPARTLENT OF AGRICULTURE
BUREAU OF HOME ECONOMICS
FARM HOUSING SURVEY
WASHINGTON, D.C.

Fun 14 - May Sing

February 5, 1934

NOTICE TO STATE AND COUNTY CHAIRMEN:

County Tabulations and Summaries

There are certain items in the schedule which will be found in practically all houses, for example, most houses have foundations, roofs, chimneys, doors, interior walls, exterior walls, etc. If the schedules are complete the tabulation sheet for such an item as walls, exterior, in good, fair, and poor condition, should equal the total number of schedules tabulated.

Before the tabulation sheets are sent from the county to the State office, it would be well to transfer the totals from the tabulation sheet to a blank schedule and add the items which appear in practically all houses in order that you may test your tabulation sheets for consistency. If your tetal of all roofs, for example, is greater than the total number of schedules, it is evident that there is an error in the tabulation of the data.

As preliminary summaries are kept for various townships or counties in your State, I would be glad to have copies of the totals for the various items on the tabulation sheet.

Sincerely yours,

Touise Sta

Man & cleek

Louise Stanley Chief

1.2. Of The Later to the First

subtraction is a position to the bill

and the second of the section of the found to the personal formers and the control of the second of the second of Application of the first of the second of the seco

Company Color (Section for the color of the

no decembración de movembra en como por en como de como La como de com La como de como

Charles Commenced

polonis got

UNITED STATES DEPARTMENT OF AGRICULTURE BUREAU OF HOME ECONOMICS FARM HOUSING SURVEY WASHINGTON, D.C.

February 5, 1934

NOTICE TO STATE CHAIRMEN:

TELEGRAMS

The business office of the Bureau of Home Economics has suggested that the payment of telegraph charges would be simplified if all telegrams from the field to this office were sent "collect." Therefore we recommend that you do this in the future.

REIMBURSEMENT FOR STATIONERY

At the beginning of this project you were notified that the Extension Service would be reimbursed for franked stationery used by the Farm Housing Survey, if necessary. It will not be possible for us to make a cash reimbursement in this instance. However, we can replace the stationery. Wherever such replacement is necessary, kindly send in a memorandum of the amount and kind of stationery used, with careful descriptions, and samples if possible.

DATE OF TERMINATION OF PROJECT

We can still only advise you to go sheed and do the best you can in finishing up the tabulations, as we have no definite information regarding the exact data when the work must be concluded.

We are not in a position as yet to make any commitment beyond February 15th, but feel confident some plan for completion will be possible. The status of this will be determined before the end of this week.

Sincerely yours,

Louise Stanley Chief

the Park

Became to the second of the process of the second of the s The Branch of Sulfin and Common Commo

garante (m. 1914). Por la granda de la granda Recombigação de la granda de la g A CONTROL OF THE CONT

The second secon

podradle Lange C

Feb 1 a 1934

Form young survey

CWHE - 58

UNITED STATES DEPARTMENT OF AGRICULTURE
BULEAU OF HOME ECONOMICS
FARM HOUSING SURVEY
WASHINGTON, D. C.

February 10, 1934

NOTICE TO STATE CHAIRMEN

COMPLETION OF SURVEY

Many inquiries have reached us during the past ten days regarding the date for sending in the State summaries. In a number of instances the entire personnel have been working over-time in an effort to finish schedule taking, tabulations, and summaries by February fifteenth. Until now we have not been able to authorize an extension of time beyond February fifteenth. Now we are assured by the Federal Civil Works Administration that we may have a reasonable time beyond that date in which to close up the work, particularly in those States where agricultural employment has not yet opened up, and our survey has been delayed because of severe weather. It is advisable that the Southern States finish as promptly as possible.

If you have not yet obtained a satisfactory representation of rural areas or an adequate sampling, it is permissible for you to continue the field work according to your original plan. This will also give you an opportunity to check further the county work. We are anxious to have the data complete and valid. While economy is necessary, the C.J.A. will give its support to a careful conclusion of the work. Please keep us informed of your plans and progress. For administrative and statistical purposes we should like to have immediately the information requested on the enclosed blank.

Yours sincerely,

Louise Stanley Chief

Louise Stanley



FARM HOUSING SURVEY

State				Date_		X
		of sche- ules	sched- ules yet to be complet-	sched- ules tabulat- ed	dete of comple- tion of county	Probable date of comple- tion of Jtate summaries
	:					

^{*} If only a part of the county is surveyed please indicate the names, or the numbers of the townships, or subdivisions surveyed.



UNITED STATES DEPARTMENT OF AGRICULTURE BUREAU OF HOME ECONOMICS FARM HOUSING SURVEY WASHINGTON, D.C.

February 10, 1934

NOTICE TO STATE CHAIRMEN

COUNTY TABULATIONS AND SUMMARIES:

Suggestions for the tabulating of the schedules have been requested by a number of county chairmen. The following procedure seems to expedite the tabulating of the summaries:

l. Use a straight-edge (folded sheet of paper or ruler) to follow rows and columns.

2. It is probably quicker to tabulate all of the first page, then all of the second, etc., rather than to attempt to tabulate an entire schedule on the six tabulation sheets.

Reports from some of the counties indicate that the average time for tabulating a schedule is from four to seven minutes.

The sum of certain items in the tabulation sheet should equal the number of schedules tabulated, for example items %13 and 14, Section B., House,—General Information, the number of one story houses plus the number of houses having more than one story should equal the number of schedules tabulated. Under Section C., Condition of House, certain items would probably appear in most houses such as, foundation, walls, roof, etc. It would be well for the counties to check the consistencies of these items.

The following is an example of apparent inconsistencies in a preliminary summary from one of the counties surveyed covering one hundred ninety-seven (197) schedules:

SUMMARY -	C.	COND	IT.	ION OF	· F	ICUSE			
ITEM	:-			nt cor Fair		tion Poor	:	TOTAL	
Foundation ————————————————————————————————————	-:	88 81 95 86 68 76	:	72 55 67 70	: : : :	81 44 45 50 47 60	: : : :	204 197 195 203 185 190	


It is difficult to understand how 197 houses can have 204 foundations. Some of the houses might not have foundations. The above totals might be less than the total number of houses, but they should not be greater.

For example, if part of the foundation is good and a smaller part of it is bad it should be checked as fair, needing repairs. If a large part of the foundation is in such bad condition that it should be entirely replaced and a very small portion is good this item should be checked on the schedule as "Poor", "Replacement or new installation needed."

Yours sincerely,

Louise Stanley Chief

Louise Stanley



UNITED STATES DEPARTMENT OF AGRICULTURE
BUREAU OF MOME ECONOMICS
FARM MOUSING SURVEY
WASHINGTON, D.C.

Feb. 17, 1934

DULLETIN FOR STATE CHAIRMEN: - NO. IV

RETURN OF SCHEDULES AND TABULATION SHEETS

The schedules and tabulation sheets from which the State summaries are made should be sent in to this office as soon as the State offices have finished with them. They should be carefully wrapped with card-board and heavy paper, and mailed first class under frank. While the Post Office of the Department informs us that such packages of first-class mail can weigh as much as seventy pounds, it is of course safer to send valuable material in smaller packages, unless it is packed in boxes. The expenditure for necessary wrapping materials will be reimbursed from this office upon receipt of vouchers filled out according to the directions already given.

ADDING MACHINES

It is permissible for the county offices to use adding machines in the preparation of county summaries. They can be borrowed or rented.

In one State the State vice-chairman in charge of the engineers' survey has prepared the county tabulation sheets entering the side headings and cross rulings for all counties in that State. These county summaries will thus be uniform and present a very pleasing appearance.

It is suggested that the person in the county office who makes the clearest figures be selected to enter the numbers and totals on the county summary sheets.

PERSONNEL

Please do not release the engineers as they will be used to map power lines.

PROGRESS REPORT

We are sending you under separate cover copies of Form 58A for recording progress of the work. Will you kindly send this report in weekly with your report of personnel.

Yours sincerely,

Louise Stanley, Chief



UNITED STATES DEPARTMENT OF AGRICULTUPE BUREAU OF HOME ECONOMICS FARM HOUSING SURVEY

French for

FEB ? - The

February 17, 1934

MEMORANDUM TO STATE CHAIRMEN:

TABULATIONS AND SUMMARIES


Preliminary summaries which have been received from the various sections of the country indicate surprisingly few needs for repairs and new installations under sections D, E, F, and G, although many of these items are checked as desired if \$500 or \$250 were available for repairs and improvements. For example, 300 families had water piped in the dwelling out of a total of 1,000 schedules. Only 6 new installations were indicated as needed in section E; however, under section I, 250 indicated a desire for a water system if \$500 were available. In other words, the needs or desires shown in section I should be reflected in sections D, E, F, and G.

Fractions—In preparing the county summaries for items 6 and 7 under section A, "total acres in farm" and "acres tillable," use the next whole number of acres. That is, when a fractional number of acres is shown for the township, the fraction should be dropped if it is less than ½ acre. The next higher number should be entered if it is ½ acre or more. For item 14, section E, "Water Supply and Sewage Disposal," the same scheme should be followed, showing only whole numbers on the summary sheets. Under section F, "Light and Heat," item 15, the distance from power line should be shown as the next 1/10 of a mile. Items 7 and 11 in section J should be shown as whole numbers; that is, the number of cents should be dropped if less than 50 cents and should be added as a whole number if it is 50 cents or more.

Yours sincerely,

Louise Stanley Chief

AGRICULTURAL ECONOMIOS





U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION

PRESS SERVICE



WASHINGTON D. C

Release - Immediate

February 21, 1934.

FARM HOUSING SURVEY
(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration : project, carried out by the U.S.Department of Agriculture and the : State Agricultural Extension Services. The object is to provide : the basic information necessary for a program of improvement for : farm homes. About 300 counties throughout the country are being : covered by the investigators. This report on Beaver County, Okla,; is the first to be issued.

Preliminary Report for Beaver Co., Oklahoma (Subject to later revision)

Reports on 1,825 farm homes in Beaver County, Oklahoma, have now been tabulated. There were 2,047 farms in this county in 1929 and the farm population was 8,636.

Some of the most significant facts shown by the preliminary totals are as follows:

Condition of Houses

Of the 1,825 houses surveyed, repairs or replacements were needed as follows:

	Complete	
	replacement	Repairing
Painting	974	247
Chimneys	831	349
Roofs	475	528
Screens	608	490
Interior walls and ceiling	s 336	662
Exterior walls	218	424
Doors and windows	349	631
Floors	342	366



Need for Additional Space Space requirements were as follows:

-	Present	Additional
	rooms	rooms needed
Bathrooms	291	547
Bedrooms	1675:.	479
Front or side porch	722	77
Work room	264	103
Water Supply a	and Sewage	Disposal

enter mentilik men samulan sapropropris didi terbis sempera didilik sadi sapropris dipenjeran terbis sebi ente	Have	New installa-
	now	tion needed
Water carried by hand	1340 40	
Hand pump in dwelling	40	3
Running water, cold	377	72
Running water, hot	68	63
Unimproved outdoor toilets	1564	
Improved toilets		482
Tub or shower bath	207	213
Kitchen sink with drain	457	260

Light and Heat

	Have	New installa-
	now	tion needed
Kerosene or gasoline lights	1625	433
Gas light	141	3
Electric light	118	13
Stoves	1401	121
Central heating	337	21

Refrigeration

	Have	Newd
	now	new
Ice boxes	317	300
Mechanical refrigerators	29	3
Washing machines, hand	455	72-
Washing machines, power	557	145

In answer to the question: If you had \$500 to spend improving your home, the following items were mentioned, among others:

Repairing interior walls, ceilings		
and floors	234	houses
Repairing exterior walls	206	ff
Adding an additional room	192	H
Installing water system	187	11
Putting in bathroom equipment	173	ff
Repairing roofs	179	Ħ
Repairing doors, windows, screens	125	p ff

These are all preliminary data, subject to change prior to publication of the data.

-----P-----



INFORMATION FOR THE PRESS



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



Release - Immediate

WASHINGTON, D. C

February 24, 1934.



Carl William

FARM HOUSING SURVEY
(A Civil Works Administration Project)

The Farm Housing Surve is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and the: State Agricultural Extension Services. The object is to provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the country are being covered by the investigators. This report on Rockingham County, Virginia, is the second to be issued.

PRELIMINARY REPORT FOR ROCKINGHAM CO., VIRGINIA (Subject to later revision)

Reports on 3,346 farm houses in Rockingham County, Virginia, have now been tabulated. There were 3,434 farms in the county in 1929 and the farm population was 17,849.

Some of the most significant facts shown by the preliminary totals are as follows:

Condition of House

Of the 3,346 houses surveyed, repairs or replacements and renewals were needed as follows:

Item	Complete replacement or renewals	Repairing
Painting	1167	1115
Chimneys	185	344
Roofs	261	232
Screens	750	781
Interior Walls and Ceilings	517	1334
Exterior Walls	319	768
Doors and Windows	264	858
Floors	317	716

NEED FOR ADDITIONAL SPACE

Space requirements were as follows:

	Present	Additional rooms
.	rooms	needed
Bathrooms	476	554
Bedrooms	12130 rooms	227 rooms
Dining rooms	2388	162
Storage space for		
fruits and vegetables	2718	118
Work rooms	385	63
Front or side porches	2930	58

WATER SUPPLY AND SEWAGE DISPOSAL

		New Percent of		
Item	Have	installa- h	ouses needing	
	now	tion needed	new installations	
Water carried by hand	231+2		•	
Hand pump in dwelling	439	49	1.5	
Running water, cold	641	247	7.4	
Running water, hot	292	153	4.6	
Unimproved outdoor toilets	2718			
Improved toilets	422	1544	46.1	
Tub or shower bath	404	438	13.i	
Kitchen sink with drain	912	2409	72.0	

LIGHT AND HEAT

Item	Have now	New installation
		needed
Kercsene or gasoline lights	2 332	5
Gas lights	51	
Electric light	992	315
Stoves	3 030	22
Central heating	361	66

frequency


REFRIGERATION AND LAUNDRY FACILITIES

Have now	Need .
now	now
1374	140
160	149
761	. 35
779	285
	160 761

In answering the question: If you had \$500 to spend in improving your home, the following items were mentioned, among others:

	No. farms	Percent of total farms
Water system	748	22.4
Interior walls, ceilings, floors	684	20.4
Bath room equipment	6 66	19.8
Exterior Walls	589	17.6
Electricity	505	15.1
Lighting system	449	13.4
Additional rooms	447	13.4
Landscaping	422	12.6
Furnishings	397	11.9
Forches	3 33	9.9
Roofs	231	6.9

These are all preliminary data, subject to change prior to publication of the data.



UNITED STATES DEPARTMENT OF AGRICULTURE BUREAU OF HOME ECONOMICS FARM HOUSING SURVEY WASHINGTON, D.C.

MAN COMMENT

February 26, 1934

CIRCULAR LETTER TO STATE CHAIRMEN AND ASSISTANT STATE CHAIRMEN OF FARM HOUSING SURVEY.

Several inquiries have been received regarding the power line survey. Instructions for this survey will not be ready for several days but will be sent you as soon as possible. In the meantime all engineers who would be qualified to take part in a survey of this kind should be kept at work on the Housing Survey.

Where less than 125 copies per county of the engineers schedules have been filled out the remainder of these may be secured or the engineers may be used to secure information about remodeling work needed in their counties.

We are anxious to secure rather complete information about some good examples of farmhouse remodeling by the owners. If the engineers have not come in contact with good examples during their survey it is probable that county agents, home demonstration agents, or the enumerators who took part in the survey could help them locate satisfactory examples. The information secured should include before and after floor plans drawn to scale, sketches of the exterior, description of changes, and such cost data as are available. A statement of the reasons for making the change and the satisfaction which the changes have given should accompany the other material. Photographs would be helpful if available.


This material should be prepared in duplicate, one set to be sent to the Bureau of Agricultural Engineering, Washington, D. C., and one set to the State survey headquarters.

Yours Sincerely,

Louise Stanley Chief

Jonice Stanley





CWIE - 63

UNITED STATES DEPARTMENT OF AGRICULTURE BUREAU OF HOME ECONOMICS FARM HOUSING SURVEY WASHINGTON, D.C.

Paraphiet Collection

MAR 3 - 1934

SUGGESTED OUTLINE FOR SUMMLRY REPORT OF FARM HOUSING SURVEY.

- I. History of Organization
 - 1. Initial steps in inauguration of State program.

State personnel

- 3. Field personnel names and permanent addresses any records that are available,
- 4. Names of counties or areas surveyed (include map, if only a portion of a county is surveyed the names of the townships or minor subdivisions covered should be given.)
 Dates of beginning of field work in counties.
 Dates of beginning of county tabulations.

- 7. Dates of end of field work in counties.
- 8. Dates of completion of county summaries.
- Date of completion of State sunmary.
- II. Administrative problems encountered.
- III. Interpretation of State figures.
 - 1. Geographic, economic, and sociological description of areas surveyed and their significance in support of weighting of results in relation to farm census of whole State.
 - 2. Possible errors in results.
 - Explanation of apparent inconsistencies.
 - 4. Any unusual definition of terms used in schedules.
- IV. Engineers' interpretation of results and impressions of the kind of work most needed in the State, with suggestions regarding the way to secure these improvements.
 - 1. A brief description of local materials available and a statement of types of constructions that are most desirable for the different regions within the State.
 - 2. A brief statement of types of housing improvements that are most needed.
 - An indication of what type of help would seem to be most practical and acceptable to farmers wishing to improve their housing.

 Any other outstanding facts or impressions that the survey has developed.
- V. Pictures and human interest stories relative to the Farm Housing Survey.
- VI. Publicity.

Include typical examples of publicity prepared by your workers for newspapers, magazines, or radio.

- VII. Inmediate effects observable.
 - Public opinion as evidenced by statements by farmers, farm women, businessmen, educators or other persons.
 - Other results.
- VIII. Suggestions for a practical follow-up home improvement program in the State.







U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C

Release - Immediate

February 27, 1934.

FARM HOUSING SURVEY
(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration:

project, carried out by the U.S. Department of Agriculture and:

the State Agricultural Extension Services. The object is to:

provide the basic information necessary for a program of im
provement for farm homes. About 300 counties throughout the:

country are being covered by the investigators.

Preliminary Report for Fayette Co., Kentucky (Subject to later revision)

Reports of 1,647 farm houses in Fayette County, in the Blue grass section of Kentucky have been tabulated. The survey shows 25 log houses, 2 earth houses, 129 unpainted frame houses, 1,011 painted frame houses, 331 brick houses, 33 stone houses. There are 689 one story houses and 963 which are more than one story. An average of 6 rooms per house is shown. There were 1,704 farms in this county in 1929 and the farm population was 8,583.

Condition of Houses

Of the 1,647 houses surveyed, replacements or renewals and repairs were needed as follows:

	Complete	Repairs	M.B.R.A.F.
	replacement		
	or renewals		BINIL
Paint, exterior	360	262	(AGRIC, IT II
Screens	329	180	1.5
Insulation	146	18	ENTINEVE OF AS
Roofs	145	328	Market Branch and Market Branch
Interior walls, and cei	lings 142	并付了	
Foundations	113	299	
Doors and windows	92	346	
Walls, exterior	89	321	
Floors	73	293	
Chimneys	42	187	
Stairs	25	81	

Of the 1,647 homes surveyed complete replacement of 100 of the houses was desired by the occupants.

1938-34

- 2 -Need for Additional Space

Space	requirements	were as	follows:

bpace requirements were as retrois.		
	Have	Additional
	now	rooms needed
Storage space for fresh	_	
fruits and vegetables	900	296
Bath rooms	510	287
Basements	684	165
Bed rooms	4800 rooms	141 rooms
Wash room for farm help	115	81
Halls	874	79
Work rooms	258	77.

Water Supply and Sewage Disposal

	Have	New installation	Per cent
	now	needed	of houses
•			needing new
,			installation
Water carried by hand	1067		
Hand pump in dwelling	8.7	8	•5
Running water, cold	538	25	1.5
Running water, hot	412	15	•9
Unimproved toilets	914		
Improved toilets, outdoor	209	12	• 7
Improved toilets, indoor	457	60	3.6
Tub or shower baths	566	228	13.8
Kitchen sink with drain	577	187	11.4
Septic tank	172	9	•5
Cess pool	276	58	3.5

Light and Heat

	Have	New installation
	now_	needed
Kerosene or gasoline lamps	1031	· -
Gas light	72	2
Electric light	562	11
Fire places	872	2
Stoves	846	1
Central heating plant	499	8

- 3 - Refrigeration, Laundry and Cooking Facilities

	Have now	New installation needed	Per cent of houses needing new installation
Ice boxes Mechanical refrigerators	1166 180	58 4	3•5 •2
Washing machines, power Washing machines, hand	177 661	3 1	.2 .1
Cooking facilities: Wood or coal stoves	1399	1	.1
Kerosene or gasoline sto Gas stoves Electric stoves	ves 206 131 36	2	.1

Yard

An American strong and principles and a supplication of the suppli	Have	New installation	
	now	needed	
Lawn established	1454	86	
Walks and drives	1144	350	
Fences	1280	256	

In answer to the question: If you had \$500 to spend improving your home, the following items were mentioned, among others:

	Number	Per cent
	of	of
	farms	total farms
Bath room equipment	120	7.3
Electricity .	95	5.8
Additional rooms	93	5.6
Water system	89	5.4
Interior walls, ceilings,	floors82	5.
Roofs	81	4.9
Exterior walls	71	4.3
Foundations	64	3.9
Doors, windows, screens	58	3.5
Porches	47	2.9

These are all preliminary data, subject to revision before the data are published.

. ----P-----



INFORMATION FOR THE PRESS



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



Release - Immediate

WASHINGTON D. C

February 27, 1934.

FARM HOUSING SURVEY
(A Civil Works Administration Project)

Carleya

Pamphlet Collection

The Farm Housing Survey is a Civil Works Administration:
:project, carried out by the U.S. Department of Agriculture and the:
:State Agricultural Extension Services. The object is to provide
:the basic information necessary for a program of improvement for
:farm homes. About 300 counties throughout the country are being
:covered by the investigators.

Preliminary Report for Knott Co. Ky. (Subject to later revision)

Reports on 2,114 farm houses in Knott County, Kentucky have been tabulated. The survey shows 568 log houses, 957 unpainted farm houses, 597 painted farm houses, 2 brick houses and 18 stone or concrete houses. There are 1,886 one-story house and 152 houses which are more than one story. An average of 3 rooms per house is shown. There were 1,951 farms in this county in 1929 and the farm population was 15,510.

Condition of Houses

Of the 2,114 homes surveyed, new installations, replacements, or renewals and repairs were needed as follows:

	Complete	Repairs
	replacement,	34
	New installation	
	or renewals	
Screens	1587	268
Paint, exterior	1200	146
Insulation	925	330
Doors and windows	646	635
Roofs	643	523
Interior walls, and	ceiling 539	678
Floors	443	522
Foundations	44 ⁵	620
Walls, exterior	352	559
Chimneys	295	351

Complete replacement of 468 of the houses surveyed was desired by the occupants.





- 2 -Need for Additional Space

Space requirements were as follows:

	Have May	Yew installation needed	Per cent of houses which need additional rooms
Storage space for fresh fruits and vegetables	269	1332	63.
Basements	128	693	32.8
Dining rooms	876	689	32.8 32.6
Living rooms	240	660	31.2
Bath rooms	2/4	560	26.5
Bed rooms	4286 room:	s 1311 rooms	62.
Work room	114	333	15.8

Water Supply and Sewage Disposal

	Have now	New installation needed	Per cent of houses needing new installation
Water carried by hand	2073		
Hand pump in dwelling	9	5,1	1.1
Running water, cold	14)†9	2.3
Running water, hot	3	6	•3
Unimproved toilets	1826		
Improved toilets, outdoo	r 64	1794	84.9
Improved toilets, indoor	4	25	1.2
Tub or shower bath	10	63	3•
Kitchen sink with drain	29	660	31.2

Light and Heat

	Have now	New installation needed	Per cent of houses needing new installation
Kerosene or gasoline	lamps 1940	143	6.8
Gas lights	35	13	•6
Electric lights	82	217	10.3
Fireplaces	1862	116	5.5
Stoves	.72	5	•2
Central heating system	em 12	ì	

Refrigeration, Laundry and Cooking Facilities

	Have now	New installation needed	Per.cent of houses needing new installation
Ice boxes	54	218	10.3
Mechanical refrigerators	6	28	1.3
Washing machines, power	88	286	13.5
Washing machines, hand	25	13	.6
Wood or coal cook stoves	1932	471	22.3



4 3 -Yard

	Have now	New installation needed	Per Cent of houses needing new installation
Lawn established	7;03	1604	75•9
Walks and drives	321	1688	79.8
Fences	1431	716	33.9

In reply to the question: If you had \$500 to spend improving your home, the following items were mentioned, among others:

	Number	Per cent
	of	of
	farms	total farms
Furnishings	1182	55•9
Interior walls, ceilings, floors	1176	55.6
Doors, windows, screens	1017	48.1
Additional rooms	969	45.8
Roofs	960	45.4
Exterior walls	808	38.2
Water system	755	35•7
Landscaping	636	30.1
Porches	556	26.3
Foundations	527	24.9
Sanitary facilities	369	17.5
Built in equipment	327	15.5
Lighting system	311	14.7
Laundry facilities	287	13.6
Bath room equipment	207	9.8

These are all preliminary data, subject to change prior to publication of the data.

____P___



UNITED STATES DEPARTMENT OF AGRICULTURE BUREAU OF HOME ECONOMICS

WASHINGTON, D. C.

US. Delec Carel Works admin, February 28, 1934

February 28, 1934

February 28, 1934

My dear

It is important that we should have all possible supporting data for the interpretation of the results of the Farm Housing Survey. Therefore I am asking each State Chairman to prepare a written report in addition to the statistical summaries. In order that these reports may be similar we have prepared the enclosed outline. Of course, other points may be included to advantage, and some variation might be advisable. For convenience in filing we should like to have these reports typed on regular letter size paper 8" X $10\frac{1}{2}$ ".

Thanking you in advance for this further cooperation, I am,
Yours sincerely,

Louise Stanley Chief





U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C

Release - Immediate

February 28, 1934.

FARM HOUSING SURVEY
(A Civil Works Administration Project)

tion project, carried out by the U.S.Department of Agriculture: and the State Agricultural Extension Services. The object is: to provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the: country are being covered by the investigators.

Preliminary Report for Bourbon Co., Kentucky (Subject to later revision)

Reports on 1,461 farm houses in Bourbon County, Kentucky, have been tabulated of which 1,165 were painted frame, 173 brick, 23 stone, 30 log houses. There were 1,896 farms in Bourbon County in 1929 and the farm population was 8,394.

Some of the most significant facts shown by the preliminary totals are as follows:

Condition of Houses

Of the 1,461 farm houses surveyed, replacements, renewals and repairs were needed as follows:

	Complete	
	replacement	Repairs
	or renewals	needed
Paint, exterior	271	364
Insulation	237	121
Screens	219	168
Foundation	124	216
Roofs	98	280
Interior walls and ceilings	23	295
Doors and windows	81	275
Floors	67	192
Walls exterior	64	215
•.		



In the 81 of the homes complete replacement of the house was desired by the occupant:

Need for Additional Space

Space requirements were as follows:

	Have	Additional
	now	rooms needed
Storage space for fresh		
fruits and vegetables	748	157
Bathrooms	263	137
Bed rooms	4182(rooms)	167 (rooms)
Back porches	1075	106
Basements	595	43
Dining rooms	1037	141

Water Supply and Sewage Disposal

	Have now	New installa- tion needed	Percent of houses needing new installation
Water carried by hand	1207		
Hand pump in dwelling	45	64	7.7
Running water, cold	252	16	1.1
Running water, hot	212	13	1.0
Unimproved outdoor toilets	1037	_	
Improved toilets	329	312	21.3
Tub or shower bath	239	11	0.8
Kitchen sink with drain	279	90	6.2

Light and Heat

	Have now	New installa- tion needed	
Kerosene or gasoline lamps	1114	1	
Gas lights	Sl	1	
Electric lights	277	156	
Fire places	734	2	
Stoves	626	1	
Central heating system	344	74	

Refrigeration, Laundry and Cooking Facilities


	Have	Need	
	now	new	
Ice boxes	75S	193	
Mechanical refrigerators	136	1,4	
Washing machines, power	226	53	
Washing machines, hand	761	į	
Wood or coal cook stoves	1322	1	
Kerosene or gasoline cook stoves	182	2	
Gas cool: stoves	J+J+	2	
Electric stoves	7	1	

In answer to the question: If you had \$500 to spend improving your home, the following items were mentioned, among others:

	Number of	Percent of
	farms	total farms
Furni shings	250	17.1
Interior walls, ceilings, floo	ors 231	15.8
Water system	154	10.5
Additional room	143	9.8
Exterior walls	119	8.0
Porches	110	7.5
Doors, windows, screens	93	6.4
Roofs	87	5.9
Electricity	පි0	5.5
Bath room	61 61	4.2
Lighting system		4.2
Foundation	147	3.2
Chimneys	43	2.9

These are all preliminary data, subject to change prior to publication of the data.

----P-----



INFORMATION FOR THE PRESS



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



February 28, 1934

WASHINGTON. D. C
FARM HOUSING SURVEY
(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administra:
tion project, carried out by the U.S. Department of Agriculture and the State Agricultural Extension Services. The
object is to provide the basic information necessary for a
program of improvement for farm lones. About 300 counties
throughout the country are being covered by the investigators:

Preliminary Report for Fauquier Co., Virginia (Subject to later revision)

Reports on 2,540 farm houses in Fauquier County, Virginia, have now been tabulated. There were 1,981 farms in the county in 1929 and the farm population was 12,473.

Some of the most significant facts shown by the preliminary totals are as follows:

Condition of House

Of the 2,540 houses surveyed, repairs or replacements and renewals were needed as follows:

Item	Complete	Repairing
	replacement	
	or renewal	
Painting	796	896
Screens	767	479
Interior walls and ceiling	gs 375	1220
Foundations	301	823
Doors and windows	217	848
Roofs	215	719
Floors	206	805
Walls, exterior	193	904
Chimneys	105	472



1946-34

- 2 -Need for Additional Space

Space requirements were as follows:

	Present	Additional rooms		
	rooms	needed		
Bathrooms	356	160		
Bedrooms	7830 rooms	130 rooms		
Basements	606	77		
Storage space for	* * *			
fruits and vegetables	777	221		
Work rooms	245	61		
Front or side porches	1983	142		
Back porches	1568	175		

Water Supply and Sewage Disposal

	Have	New	Percent of houses
	now	installation	needing new
. •	·	needed	installations
Water carried by hand	2030		
Hand pump in dwelling	70	6	•2
Running water, cold	71,10	16	.6
Running water, hot	280	11	• #
Unimproved outdoor toilets	1657		
Improved toileis, outdoor	416	1809	71.2
Improved toilets, indoors	303	8	• 3
Tub or shower bath	364	16	.6
Kitchen sink with drain	396	2143	84.4

Light and Heat

	Have now	New installation needed
Kerosene or gasoline lights Gas lights	2184 76	39
Electric light	324	26
Stoves Central heating	2397 142	60

Refrigeration and Laundry Facilities

	Have now	Mead now
Ice boxes	1044	32
Mechanical refrigerators	85	11
Washing machines, hand	99	8
Washing machines, power	266	41

4.7 . W (.7

In answering the question: If you had \$500 to spend in improving your home, the following items were mentioned, among others:

	No.	farms	Percent of total
			farms
Interior walls, ceilings,	floors	795	31.3
Exterior Walls		588	23.1
Water system		557	1.5
Porches		46i	18.1
Roofs		364	14.3
Doors, windows, screens		315	25.4
Landscaping		286	11.3
Bath room equipment		259	10.5
Additional rooms		266	10.5

These are all preliminary data, subject to change prior to publication of the data.

The state of the s

et (i) , a (i) , a (i)

INFORMATION FOR THE PRESS



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C

Release - Immediate

March 2, 1934.

FARM HOUSING SURVEY
(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration : project, carried out by the U. S. Department of Agriculture and the : State Agricultural Extension Services. The object is to provide : the basic infermation necessary for a program of improvement for : farm homes. About 300 counties throughout the country are being : covered by the investigators.

Preliminary Report for Calloway Co., Kentucky (Subject to later revision)

Reports on 2792 farm houses in Calloway County, Kentucky, have been tabulated. Of these, 1983 are painted frame houses, 715 unpainted frame houses, 78 log houses, and the remainder are brick, stucco, or concrete. There were 2990 farms in Calloway County in 1929 and the farm population was 12,883.

Some of the most significant facts shown by the preliminary totals

are as follows:

Condition of Houses

Of the 2792 farm houses surveyed, replacements or renewals and repairs were needed as follows:

	Complete	
Item	replacement	Repairs
	or renewal	
Paint, exterior	2081	198
Screens	1486	657
Roofs	1090	743
Interior walls and	ceilings 1006	1036
Foundations	675	767
Doors and windows	654	1030
Floors	638	901
Walls, exterior	493	812
Chimneys	402	654



Complete replacement of 317 of the houses surveyed was desired by the occupants.

1993-34

Space Requirements

Space requirements were as follows:

	Have	Additional
	ncw	space needed
Basements	104	1042
Bathrooms	49	824
Dining rocms	913	572
Back porches	1985	526
Work rooms	137	462
Bedrooms	4796 rooms	amcor 8801

Water Supply and Sewage Disposal

	Have now	New in- stallation needed	Percent. needing new installation
Carried by hand	2764		•
Hand pump in dwelling	16	458	1.6.3
Running water, cold	35	1933	37.0
Running water, hot	6	423	15.2
Unimproved toilets	1968	3 5	
Improved toilets, outdoors	31	1407	50.4
Improved toilets, indcors	15	640	22.9
Tub or shower bath	25	1551	55.6
Kitchen sink with drain	· 2	1453	52.0

Light and Heat

	Have now	New in- stallation needed	Percent needing new installa- tion
Kerosene or gasoline lights	2724	214	7.7
Gas lights	6	3	.1
Electric lights, home plant	25	32	1.1
Electric lights, power line	57	1794	64.3
Fire places	2323	135	4.8
Stoves	1006	201	7.2
Central heating system	. 27	396	14.2

Refrigeration, Laundry, and Cooking Facilities

	Have now	Now in- stallation nceded	Percent needing new installa- tion
Ice boxes	326	899	32.2
Mechanical refrigeration	5	328	11.7
Washing machine, hand	2717	124	4.4
Washing machines, power	26	941	33.7
Wood or coal cookstoves	2728	357	12.8
Kerosene or gasoline stoves	202	108	3.9
Electric stoves		228	8.2

In answer to the question: "If you had \$500 for improving your home what would you spend it for?" the following items were mentioned among others:

	No.	Percent of	total
	farms	farms	
Exterior walls	667	23,9	
Interior walls, ceilings, floors	61]	22.2	
Roofs	543	19.4	
Doors, windows, screens	483	17.3	
Additional rooms	475	17.0	
Electricity	382	13.7	
Water system	381	13.6	
Furnishings	319	11.4	
Porches	291	10.4	
Foundations	216	7.7	
Bathroom equipment	206	7.4	

These are all preliminary data and are subject to change prior to publication of the data.

----P------

w , v

INFORMATION FOR THE PRESS



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C

Release - Immediate

March 3, 1934.

FARM HOUSING SURVEY (A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration :project, carried out by the U. S. Department of Agriculture and the: :State Agricultural Extension Services. The object is to provide : the basic information necessary for a program of improvement for :farm homes. About 300 counties throughout the country are being :covered by the investigators.

> Preliminary Report for Knox Co., Tennessee (Subject to later revision)

Reports on 3357 farm houses in Knox County, Tennessee have been tabulated. There were 4039 farms in this county in 1929 and the farm population was 12,689.

Some of the most significant facts shown by the preliminary totals are as follows:

Condition of Houses

Of the 3357 farm houses surveyed, new installations, replacements, or renewals and repairs were needed as follows:

	Complete replacement or renewal	Repairs	
Paint, exterior	1485	774	The second second
Screens	1097	831	BRA
Roofs	740	866	BURTALE
Interior walls and ceilings	584	1469	AGRICULT.
Foundations	434	979	Nis -
Stairs	362	637	DEPARTMENT OF AC
Floors	348	990	



INFORMATION FOR THE PRESS



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C

Release - Immediate

March 5, 1934

FARM HOUSING SURVEY
(A Civil Works Administration Project)

: The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the :country are being covered by the investigators.

Preliminary Report for Shelby Co., Kentucky ISubject to later revision)

Reports on 2,015 farm houses in Shelby County, Kentucky have been tabulated. The Survey shows 66 log houses, 1 earth house, 156 unpainted, 1625 painted, 10 stucco frame houses; 146 brick, 4 stone and 7 concrete houses. There were 569 one story houses and 1446 that were more than one story. An average of 7 rooms per house is shown. There were 2,337 farms in this county in 1929, and the farm population was 11,220.

Of the 2,015 houses surveyed, new installations, replacements, or renewals and repairs were needed as follows;

Complete Replacement	
New Inst_Ilation	Repairs
or renewals	
993	363
435	512
237	594
232	7
125	786
114	622
104	688
47	546
76	431
	New Inst_llation or renewals 993 435 237 232 125 114 104 47

Need for Additional Space Space requirements were as follows:

	Have				Per cent	•
	now	ne	eeded	1	needing additional	room:
Bathrooms	227		827		41.00	•
Sterage space for	1142		728		36.1	
fruits and vegetables	653	,	556		27.6	
Werk room	364		535		26.6	
Basement	479		413		20.5	
Wash room for farm help	1522		372		18.5	
Back porches Bed rooms	5622	(rooms)	270	(rooms)	13.4	,
Dining rooms	1465		248		12,3	

- 2 - Water Supply and Sewage Disposal

1	Have	New installation	Fer cent of
r	1077	needed	houses needing new installation
	1825		
Hand pump in dwelling	109	710	35.2
Running water, cold	167	784	39.9
Running water, hot	137	710	35.2
Tub or shower bath	170	1346	66.8
Kitchen sink with drain	243	1015	50.4
Unimproved toilcts	1695		
Improved toilets	299	967	48,0

Light and Heat

• • • • • • • • • • • • • • • • • • • •	Have New		Per cent needing new installation
Kerosene or gasoline lamps	1697	1	
Gas lights	57	12	. 6
Electric lights	296	996	49.4
Central heating system	103	277	13.7

Refrigeration and Laundry Facilities

	Have now	New installation needed	Fer cent of houses needing new installation
Ice bexes	987	310	15.4
Mechanical refrigerators	74	- 105	5.2
Washing machines, power	427	220	10.9
Washing machines, hand	1328	. 2	

Landscaping of House

	Have	New	installati	on	Per cent of houses	
	now		needed		needing new	
					installation	
Walks and drives	1287		870		43.2	
Lawn established	1842		100		5.0	
Fences	1743		435		21.6	
Surface drainage						
away from house	1850		190		9.4	

In reply to the question: If you had \$500 to spend improving your home, the following items were mentioned, among others:

٠.			
		Number of	Per cent of
_		farms	total farms
	Exterior walls	992	49.2
	Interior walls, ceilings, floors	928	46.1
	Water system	569	29.2
	Roof	515	25.6
	Additional room	416	20.6
	Doors, screens, windows	439	21.8
	Porches	387	19.2
•	Landscaping	357	17.7 ,
	Electricity	348	17.3
,	Bathreom equipment	317	15.7
	Furnishings	259	12.9

These are all preliminary data, subject to revision before the data are published.

FARM HOUSING "SURVEY (A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration : Project, carried out by the U.S. Department of Agriculture and the: State Agricultural Extension Services. The object is to provide : the basic information necessary for a program of improvement for : farm homes. About 300 counties throughout the country are being : covered by the investigators.

Preliminary Report for Hickman Co., Ky. (Subject to later revision)

Reports on 1426 farm houses in Hickman Gounty, Kentucky have been tabulated. The survey shows 37 log houses, 671 unpainted farm houses, 706 painted farm houses, 1 brick house and 1 concrete house and 1 stucce house. There are 1133 one-story houses and 265 houses which are more than one story. An average of 3 rooms per house is shown. There were 1434 farms in this county in 1929 and the farm population was 6,424.

Condition of Houses

Of the 1426 homes surveyed, new installations, replacements, or renewals and repairs were needed as follows:

	Complete Replacement, New installation or renewals	Repairs	and fine and to be
Paint, exterior	87 7	169	
Screens	506	354	
Roofs	444	430	
Insulation	403	509	// V 1) ==
Foundations	312	458	11 15
Interior walls and ceilings	238	583	
Doors and windows	261	538	· · ·
Walls, exterior	255	511	· . DEF2
Floors	210	497	"IMENT OF "
Chimneys	119	305	and the state of t

Need for Additional Space Space requirements were as follows;

	Have N now	ew installation needed	Per cent of houses which need additional rooms
Bathrooms	65	549	38.5
Bedrooms	2849 rooms	549 rooms	38+5
Bascronts	67	460	\$2.3
Work rooms	104	278	19.5
Dining rooms	772	254	1 7.8
Back parches	962	. 240	16.8

Water Supply and Sewage Disposal

new	New installation needed	Per cent of houses needing new installation
1063		
12	91	6.4
61	147	10.3
II	105	7.4
990		
93	588	41.2
19	28	2.0
37	348	24.4
101	520	36.5
	063 12 61 11 990 93 19 37	new needed 1063 12 91 61 147 11 105 990 93 588 19 28 37 348

Light and Heat

	now	installation needed	Por cent of houses needing new : installation
Kerosene or gasoline lamps	1397	39	2.7
Gas lights	-15	-	_*
Electric lights	9	234	16.4
Fireplaces	629	34.	2.4
Stoves	1014	86	, , 6.0
Contral heating system	21	124	8.7

Refrigeration, Laundry and Cooking Facilities

	Have now	New installation needed	Per cent of houses needing new installation
Lce boxes	435	, , 301	21.1
Mechanical refrigerators	1	.3	•2
Washing machines, power	37	350	24.5
Washing machines, hand	1230	6	. •4
Wood or coal cook stoves		59	4.1

Yard

***************************************	Have now	New installation needed	Per cent of houses needing new installation
Lawn established	829	360	25.2
Walks and drives	213	625	43.8
Fences	341	· 365	25.6

In reply to the question: If you had \$500 to spend improving your home, the following items were mentioned, among others:

	Number	Per cent	
	of	of	
	farms	total farms	
Interior walls, ceilings, floors	803	56.3	
Exterior walls	786	55.1	
Roofs	623	43.7	
Porches	552	3 8.7	
Doors, windows, screens	473	33,2	
Water system	418	29.3	
Additional room	402	28,2	
Foundations	382	26.8	
Built in equipment	. 171	12.0	
Laundry equipment	125	8.8	
Chimneys	120	8.4	

These are all preliminary data, subject to change prior to publication of the data.



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C

Release - Immediate

March 7, 1934

FARM HOUSING SURVEY (A Civil Works Administration Project)

: The Farm Housing Survey is a Civil Works Administration: :project, carried out by the U.S. Department of Agriculture and: :the State _gricultural Extension Services. The object is to :provide the basic information necessary for a program of im- :provement for farm homes. About 300 counties throughout the :country are being covered by the investigators.

Preliminary Report for Boyle County., Ky. (Subject to later revision)

Reports on 973 farm houses in Boyle County, Kentucky, have new been tabulated. There were 1251 farms in the county in 1929 and the farm population was 5760.

Some of the most significant facts shown by the preliminary totals are as follows:

Condition of the House

Of the 973 houses surveyed, repairs or replacements and renewals were needed as follows:

· v.	Complete replacement etc. needed	Repairing or alterations needed	`
Foundation Walls, exterior Roofs Doors, Windows, Screens Paint, Exterior Walls, Exterior	102 117 110 349 486 118	235 218 258 231 159 159 279	AGRICHT CONT.
	Need for Additional Space		CPARTMENT OF AGRICULT

Need for Additional Space Space requirements were as follows:

	Have now	Additional rooms needed	Per cont total farms	of
Sterage space for fresh fruits and vegetables Back porches	498 635	243 101	25.0 10.4	
		rooms 80 rooms 65	8.2 6.7 5.5	

Water Supply and Sewage Disposal

	Have	New installation
	now	necded
Water carried by hand	779	-
Hand pump in dwelling	73	1
Running water, cold	8 6	***
Running water, hot	77	_
Unimproved toilets	767	
Improved toilets	123	99
Tub or shower bath	101	1
Kitchen sink with drain	130	4

Light and Heat

	Have	New installation needed
Kerosene or gasoline lamps	845	8
Gas lights	6	_
Electric lights, home plant	21	,
Electric lights, power line	105	1
Fireplaces	494	1
Stoves .	728	10
Central heating plant	95	1

Refrigeration and Laundry Equipment

	Have	New installation
	now	needed
Ice boxes	283	114
Mechanical refrigerators	41	1
Washing machines, power	35	3
Washing machines, hand	62	5

In answer to the question: If you had \$500 to spend improving your home, the following items were mentioned among others:

	Number of farms	Per cent of total
Interior walls, ceilings, floors		35.3
Exterior walls	343 327	33.6
Additional rooms	245	25,2
Doors, windows, screens	228	23.4
Roofs	206	21.2
Porches	199	20.5
Water systems	150	15.4
Landscaping	134	13.8



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C.

Release - Immediate

March 13, 1934.

CORRECTION

In the preliminary report on the Farm Housing Survey for Boyle County, Ky., sent to you from this office March 7, the first table contained two errors. The number of exterior walls that need complete replacement was left blank. The figure should be 86. The last item in the table, Walls, exterior, should be Walls, interior.





U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON D C

Release - Immediate

March 7, 1934

FARM HOUSING SURVEY
(A Civil Works Administration Project)

: The Farm Housing Survey is a Civil Works Administration: :project, carried out by the U.S. Department of Agriculture and: :the State Agricultural Extension Services. The object is to :provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the :country are being covered by the investigators.

Preliminary Report for Washce and Churchill Counties, Nevada. (Subject to later Revision)

Reports on 1056 farm homes in Washoe and Churchill counties, in Nevada have been tabulated. The survey shows four log houses, 23 earth houses, 388 unpainted frame houses, 535 painted frame houses, 29 stucco houses, 37 brick houses, 9 stone houses and 31 concrete houses. There were 865 one story houses and 191 houses having more than one story. An average of four rooms per house is shown. There were 1083 farms in these counties in 1929 and the farm population was 4997.

Condition of Houses

Of the 1055 homes surveyed new installations, replacements or renewals and repairs were needed as follows:

	Complete replacement New installations or Renewals	Repairs
Painted exterior	461	200
Foundations	293	180
Screens	266	208
Insulation	231	104
Floors	197	237
Interior walls and ceilings	185	359
Roofs	160	299

Complete replacement of 246 of the houses surveyed was desired by the occupants.

Need for Additional Space Space requirements were as follows:

	Have	Additional	Per cent of houses
	now	rooms	in which additional
		needed	rooms are needed
Bathrooms	422	339	32.1
Back porches	519	203	19.2
Front or side porches	604	199	18.8
Storage space for fresh	h		//
fruits and vegetables	704	189	17.9 ((AGR
Work rooms	182	174	16.5
Wash rooms for help	757	159	15.1
Dining rooms	560	142	13.4
Bed rooms	2493	rooms 497 rooms	47 1





Water Supply and Sewage Disposal

LE

	Have now	New installation needed	Fer cent of homes needing new installation
Water carried by hand	92	4-4	_
Hand pump in dwelling	99	16	1.5
Running water, cold	498	249	14.1
Running water, hot	367	292	27.7
Unimproved outdoor toilets	734	-	_
Improved toilets out of doors	67	30	2.8
Improved toilets indoors	301	385	36.5
Tub or shower bath	432	649	61.5
Sink with drain in kitchen	664	249	23.6

Light and Heat

	Have	New installation	
	now	necded	
Gasoline or kerosene lamps	317	22	
Gas lights	9	364	
Electric lights	739	138	
Stoves	885	44	
Central heating system	233	243	

Refrigeration, Laundry and Cooking Equipment

	Have	New installation	
	now	needod	
Icc boxes	331 `	68	
Mechanical refrigeration	82	364	
Washing machines, power	315	265	
Washing machines, hand	19	5	
Wood or coal stoves	788	55	
Kerosene or gasoline stoves	80	15	
Gas stoves	28	56	
Electric stoves	78	103	

In answer to the question: If \$500 were available for you to spend in improving your home, the following items were mentioned among others:

	Number of farms	Per cent of total farms
Bath room equipment	395	37.4
Water system	354	33.5
Interior walls, ceilings, floors	327	31.0
Additional rooms	303	28.7
Exterior walls	224	21.2
Roofs	204	19.3
Porches	191	18.1
Furnishings	186	17.6
Sanitary facilities	185	17.5
Foundations	148	14.0
Doors, windows, screens	136	12.9





U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C

Release - Immediate

March 7, 1934

FARM HOUSING SURVEY

(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of imprevement for farm homes. About 300 counties throughout the : country are being covered by the investigators.

Preliminary Report for Providence Co., Rhode Island (Subject to later revision)

Reports on 1139 farm homes in Previdence County, Rhode Island have been tabulated. There are 41 unpainted frame houses, 1082 painted frame houses, 3 stucco houses, 5 brick houses and 8 stone houses. The survey shows 102 one story houses and 1036 houses having more than one story. The houses average 10 reoms. There were 1390 farm homes in this county in 1929 and the farm population was 6281.

Condition of Houses

Of the 1139 houses surveyed replacements, renewals or new installations and repairs were as follows:

A CONTRACTOR OF THE CONTRACTOR	renewa	te repla ls or ne lation n	w .	Repairs
Rocfs		37		 123
	1	36 -		 51
Paint, exterior		2 9		213
Floors		26		 84
Interior walls and ceilings		25		191
Doors and windows		25		 79

Need for Additional Space Space requirements were as follows:

	Hav	e Additional	rooms
	nov	need	ed
Bath rooms	534		72
Bed rooms	4894	rooms	46 rooms
Front or side porches	619		12
Dining rooms	927		11

Water Supply and Sewage Disposal

And the state of t	- 	A CONTRACTOR OF THE PROPERTY O
	Have	New installation
	now	nceded
Water carried by hand	292	-
Hand pump in dwelling	164	16
Running water, cold	734	37
Running water, hot	377	33 ·
Unimproved toilats	3 86	-
Improved toilets, outdoors	270	4
Improved toilets, indoors	521	66
Tub or shower bath	613	104
Kitchen sink with drain	1111	13



Light and Heat

	Have	New installation	
	now	needed	
Keresene or gasoline lamps	184	2	_
Gas lights	16	-	
Electric lights, home plant	22	wah	
Electric lights, power line	93 8	15	
Stoves	815	V., 6	
Central heating plant	575	- Time Kiv3L ()	

a man a second

187 .

Refrigeration, Laundry and Cocking Facilities

lave New installation needed
'87 · 26
250
306
215
383 1 14 1 14 2 1 1 1 1 1 1 1 1 1
353
78 –
13 1 20 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
3

Landscaping of House

	Have	New installation	
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	needed	
Lawns established	1053	44	
Plantings	1017	50 y y	
Walks and drives	1048	37	
Fences	839	25	

In answer to the question: If you had \$500 to spend in improving your home, the following items were mentioned, among others:

		Tumber c	f Per cent of
	n*	formes	total farms
Exterior walls		325	28.5
Interior walls	1::	304	26.7 m
Water systems		2.00	17.6
Bath room equipment		199	17.6 17.5
Roofs		150	13.2
Sanitary facilities		123	10.8
Furnishings		109	9.6

These are all preliminary data, subject to revision before the data are published.

100



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C

Release - Immediate

March 7, 1934

FARM HOUSING SURVEY (A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the : country are being covered by the investigators.

AGRICULT S. DEPARTMENT OF AGRICULT

Preliminary Report for Grange Co., Florida (Subject to later revision)

Reports of 1492 farm homes in Orange County have been tabulated. The survey shows 1094 painted frame houses, 306 unpainted frame houses, 55 stucco houses, 10 log houses, 13 brick houses, 1 stone house and 13 concrete houses. There are 670 houses under 10 years of age and 546 houses between the age of 10 and 24 years. The average size of the houses is 5 rooms. There are 1083 one story houses and 409 houses have more than one story. In 1929 there were 1608 farms in this county and the farm population was 5127.

Condition of Houses

Of the 1492 homes surveyed the replacements, renewals or new installations and repairs were as follows:

	**	Complete replacement needed	Repairs
Insulation	- + -	1290	19
Paint, exterior		664	5 32
Interior walls and	ceilings	- 493	610 .
Screens	ŭ	425	521
Chimneys		351	.142
Roofs		289	518
Foundations		217	344
Doors and windows		199	542
Floors		169	619

Need for Additional Space

	Have	Additional	Per cent of homes
	now	space -	in which additional
·		needed	space is needed
Storage space for fresh	153	467	31.3
fruits and vegetables			· ·
Bathrooms	688	305	20.5
Dining rooms	920	270	16.1
Back porches	1985	223	4.9
Front or side porches	1238	156	10.5
Bed rooms	3719	rooms 530 row	

Water Supply and Sewage Disposal

	Have N	lew installation	Per cent of
	now	necded	homes needing
			new installation
Water carried by hand	636		
Hand pump in dwelling	258	233	15.6
Running water, cold	644	470	31.5
Running water, hot	278	355	23.8
Unimproved toilets	743	- 14.1	_
Improved toilets, outdoors.	172	498	33.4
Improved toilets, indoors	544	392	26.3
Tub or shower bath	685	435	29.2
Kitchen sink with drain	716	599	40.1

Light and Heat

6		.,,
. Have . New installat	Lon	
now needed	1. 1.	
Kerosene or gasoline lamps 855	21 .	
Gas lights 6.		
Electric lights, home plant 86 53		
Electric lights, power line 624 315		
Fire places		
Stoves		
Central heating systems 74 196	,	*

Refrigeration, Laundry Facilities

_		Have	New installation	_
_		now	needed	
-	Lce boxes	744	- 256	
. 1	Mechanical refrigerators	242		
Ţ	Washing machines, power	135	375	
	Vashing machines, hand	12	108	
-				_

Landscaping of House

~
-
* .

In answer to the question: If you had \$500 to spend in improving your home, the following items were mentioned among others:

		Number of	Per cent of
		farm homes	tetal
Interior walls, ceilings, fl	oors	764	51.2
Exterior walls		576	38.6
Water systems		525	35.2
Roofs		495	33.2
Bathroem equipment		474	31.8
Deors, windows, screens		431	28.9
Additional rooms		394	26.4
Porches		369	24.7
Built in equipment		310	20.8
Sanitary facilities		296	19.8
Furnishings		266	17.8
Chimneys		246	16.5
Electricity		220	14.7
Lighting system		207	13.9



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



Release - Immediate

WASHINGTON, D. C

March 9, 1934

FARM HOUSING SURVEY
(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the : country are being covered by the investigators.

Preliminary Report for Hardin County, Kentucky (Subject to later revision)

Reports on 2642 farm houses surveyed in Hardin County, Kentucky have been tabulated. This survey of the county shows 307 log houses, 3 earth houses, 560 unpainted frame houses, 1705 painted frame houses, 61 brick houses, and 6 stucco, stone, or concrete houses. There are 1228 one story houses and 1414 houses which have more than one story. In average of 5 rooms per house is shown. There were 2752 farms in this county in 1929, and the farm population was 3058

Condition of Houses

Of the 2642 farm houses surveyed, replacements, renewals, or new installation, and repairs are needed as follows:

	Complete replacement, new installation, or renewals	Repairs
Paint, exterior	1146	480
Screens	73 6	611
Roofs	.3 79	- 759
Interior walls, ceilings	185	612
Doors, windows	165	706
Foundations	150	700

Complete replacement of 83 farm houses was desired by occupants.

Space requirements were as follows:

Control of the second s				· ·
	Have	Additional	Per cent	of houses
•	now	rooms	in which	additional
		necded	space is	needed
Storage space for fresh				
fruits and vegetables	1097	550	21	•2
Bed rooms .	6287	roams 416 rooms	15	•7
Back porches	1475	383	14	•5
Front or side porches	1594	319	. 12	.1
Dining rooms	1384	25		.9
Living rooms	1941	· 24		. 9

Water Supply and Sewage Disposal

	Have	New installation
	now	needed
Water carried by hand	2425	-
Hand pump in dwelling	143	31
Running water, cold	77	1
Running water, hot	3 9	1
Unimproved toilets, outdoors	2222	-
Improved toilets, outdoors	133	40
Improved toilets, indoors	53	2
Tub or shower bath	69	6
Kitchen sink with drain	178	113

Light and Heat

	Have now	New installation needed
Kerosene or gasoline lamps	2412	
Gas lights	18	_
Electric lights	224	8
Fireplaces	632	1
Stoves	2421	18
Central heating systems	97	38 .

Refrigeration, Laundry, and Cooking equipment

	Have	New installation
	now	needed
Ice boxes	320	17
Mechanical refrigerators	305	1
Washing machines, power	. 193	3
Washing machines, hand	2458	29
Wood or coal cook stoves	2588	14
Kerosene or gasoline stoves	391	25
Gas stoves	6	-
Electric stoves	5	1

Landscaping of House

	Have	New installation
	now	necded
Lawn established	2041	486
Walks and drives	1061	926
Fences	1540	584

In answer to the question: If \$500 were available for you to spend in improving your house, the following items were mentioned, among others:

			1.	
,		Number o	f farm	Per cent of
		houses		total farms
Exterior walls		360		13.6
Water systems		314		11.9
Interior walls, ceilings,	floors	293		11.1
Roofs		284		10.7
Porches		240		9.1
Furnishings		239		9.0
Additional rooms		237		9.0
Electricity, home plant Electricity, power line		223		8.4
Electricity, power line		44		.2



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



Release - Immediate

WASHINGTON, D. C

March 9, 1934

FARM HOUSING SURVEY
(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the : country are being covered by the investigators.

Preliminary Report for Ohio County, Kentucky (Subject to later revision)

Reports on 2610 farm houses surveyd in Ohio County, Kentucky, have been tabulated. There are 220 log houses, I earth house, 958 unpainted frame houses, 1425 painted frame houses, and 8 stucco, brick, stone, or concrete houses. Of the houses surveyed 1755 are one story, and 819 are more than one story. There were 3191 farms in this county in 1929, and the farm population was 14277

Condition of Houses

Of the 2610 houses surveyed, replacements, renewals, or new installation, and repairs were needed as follows:

	lete replacement; no	
inst	allation, or renewal	s Repairs
Paint, exterior	1760	238
Screens	1418	466
Roofs	865	545
Doors and windows	654	685
Interior walls and ceilings	539	707
Floors	491	432
Foundations	454	565
Walls, exterior	431	588
Chimneys	296	442
Stairs	290	190

Complete replacement of 167 houses was desired by the occupants.

Need for Additional Space Space requirements were as follows:

	Hav	e Additio	nal Per cent of	houses
	now	rooms	in which ad	ditional
		needed	rooms are n	eeded.
Bath rooms	63	1756	67.3	
Storage space for fresh	h			
fruits and vegetables	641	1498	57.4	
Basements	87	1292	49.5	
Living rooms	775	1064	49.5 40.8	
Dining rooms	1104	1013	38.8	
Back porches	1241	930	35.6	
Work rooms	1708	761	29.2	
Front or side porches	1577	745	28.5	
Wash room for farm help	p 45	691	26.5	
Bed rooms	6840	rooms 587	rooms 22.5	

Water Supply and Sewage Disposal

	Have now	New installation needed	Per cent of houses in which new installation is needed
Water carried by hand	2512	_	_
Hand pump in dwelling	101	37 9	14.5
Running water, cold	30	1459	55.9
Running water, hot	11	1217	46.6
Unimproved toilets, outdoors	2276		_
Improved toilets, outdoors	38	830	31.8
Improved toilets, indoors	11	1118	42.8
Tub or shower bath	33	2550	97.7
Kitchen sink with drain	227	1820	69.7

Light and Heat

•.	Have now	New installation needed	Per cent of houses in which new installation is needed
Kerosene or gaseline lamps	2528	127	4.9
Gas lights	65	100	3.8
Electric lights, home plant	15	53	2.0.
Electric lights, power line	38	1054	40.4
Fire places	1982	91	3.5
Stoves	934	92	3.5
Central heating system	77	537	20.6

Refrigeration, Laundry, and Cooking Lacilities

· ·	Have now	New installation needed	Per cent of houses in which new installation is needed
Ice boxes	257	853	32.7
Mechanical refrigerators	10	688	26.4
Washing machines, power	85	1039	39.8
Washing machines, hand	2494	164	6.3

Landscaping of House

	Have	New installation
	now	nceded
Lowns established	923	1514
Valks and drives	411	1922
Fences	874	1505

In answer to the question: If \$500 were available for you to spend in improving your house, the following items were mentioned among others:

	Number of farmes	Fer cent of total farms
Exterior walls	940	36.0
Interior wall, ceilings, floors	836	32.0
Doors, windows, screens	747	28.6
Roofs	744	28.5
Porches	666	25.5
Additional rooms	520	19.9
Later systèms	473	18.1
Bath room equipment	351	13.4



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



Release - Immediate

WASHINGTON, D. C

March 9, 1934

FARM HOUSING SURVEY (a Civil Works Administration Project)

: The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the : country are being covered by the investigators.

Freliminary Report for Simpson County, Ky. (Subject to later revision)

Reports of 1749 farm houses surveyed in Simpson County, Kentucky, have been tabulated. There are 108 log houses, 575 unpainted frame houses, 1028 painted frame houses, and 38 brick, stone or stucco houses. The average size of the houses is 5 rooms. There were 1797 farms in this county in 1929, and the farm population was 8144.

Condition of Houses

Of the 1749 houses surveyed, replacements, new installations, or renewals, and repairs, were needed as follows:

	Complete replacement, renewals, or new installations	Repairs
Insulation	908	56
Paint, exterior	905	156
Soreens	517	298
Roofs	330	372
Deors and windows	185 🚾	397
Floors.	124	341

Need for Additional Space Space requirements were as follows:

	Have now			in whi	ent of houses ch additional are needed
Storage space for fresl	1		14-		
fruits and vegetables	661		:1038		59.4
Bath rooms	93		470		26.9
Back porches	1048		295		16.9
Bed rooms	4208	rooms	261	rooms	14.9
Front porches	1280		183	,	10.5
Dining rooms	870		178		10.2
Basements	154		167		9.5

Complete replacement of 141 homes was desired by the occupants.

Water Supply and Sewage Disposal

	Have now	New installation needed	Per cent of houses in which new installation is needed
Water carried by hand	1606	valle.	-
Hand pump in dwelling	108	46	2.6
Running water, cold	93	9 37	53.6
Running water, hot	30	329	18.8
Unimproved toilets, outdoors	3 1316	-	_
Improved toilets, indoors	49	813	46.5
Improved toilets, outdoors	9	368	21.0
Tub or shower bath	66	9 9 1	56.7
Kitchen sink with drain	149	1052	60.1

Light and Heat

to Mariana de la companya della companya della companya de la companya della comp	Have now	New installation needed	Per cent of houses in which new installation is needed
Kerosene or gasoline lamps	1644	Ó .	•3
Gas lights	44	. 18	1.0
Electric lights, home plant	12	20	1.1
Electric lights, power line		771	44.8
Fireplaces	1218	7	• 4
Stoves	1059	13	7.7
Central heating systems .	37	162	9,3

Refrigeration, Laundry, and Cooking Facilities

	Have now	New installation needed	Per cent of houses in which new installation is needed
Ice boxes	707	903	51.6
Mechanical refrigerators	11	178	10.2
Washing machines, power	- 51	564	32 . 2 ·
Washing machine, hand	38	14	8
Wood or coal cook stoves	1717	22	1.3
Kerosene or gasoline stove	s 148	11	•6
Gas stoves	17	65	3.7
Electric stoves	3	58	3.3

In answer to the question: If \$500 were available for you to spend in improving your house, the following items were mentioned, among others:

	Number of Per c	ent of total
	faims farms	
Water systems	7.72	44.1
Interior walls, ceilings,	floors 737	42.1
Exterior walls	717	41.0
Roofs	493	28.4
Doors, windows, screens	486	27.8
Bathroom equipment	485	27.7
Porches	468	26.8
Additional rooms	463	26.5
Electricity	457	26.1
Furnishings	276	15.8
Lighting system	184	10.5
Chimneys	143	8.2
Foundations	140	8.0



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C

Releae - Immediate

harch 10, 1934

FARM HOURTNG SURVEY
(A Civil Works Administration Project)

The Farm Housing Survey is a Civil works dministration: project, carried out by the U.S. Department of Agriculture and: the State agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the : country are being covered by the investigators.

Preliminary Report for Essex County, Virginia (Subject to later revision)

Reports on 1335 farm houses in Essex County, Virginia have been tabulated. The survey shows 19 log houses, 526 unpainted frame houses, 757 painted frame houses, 32 brick houses, and 1 concrete house. There are 242 one story houses, and 1093 houses in which there are more than one story. An average of 5 rooms per house is shown. There were 1181 farms in this county in 1929, and the farm population was 6011.

Condition of Houses

Of the 1335 farm houses surveyed, replacements, renewals, or new installations, and repairs are needed as follows:

	Complete replacement,		
	renewals, or new installation		
Paint, exterior	875	254	
Foundations	614	457	
Screens	560° ''	431	
Insulations	5 3 9	14 •	
Interior walls, ce	ilings 453	619	
Roofs	374	422	

Need for Additional Space Space requirements were as follows:

	Have	Additional	Per cent of houses in
•	now	rooms	which additional
•		needed	rooms are needed .
Storage space for fresh			
fruits and vegetables	291	264	19.8
Back porches	490	130	9.7
Front or side porches	754	119	8.9
Bathrooms ·	66	61	4.6
Bedrooms .	3570	reoms 50 rooms	3.7
Living rooms.	. 751	29	2.2
Dining rooms	890	. 21	1.6



Water Supply and Sewage Disposai

	Have	New	Per cent of houses in
	now	installation	which new installation
		necded	is necded
Water carried by hand	1217	-	
Hand pump in dwelling	13	_	***
Running water, cold	69	. 63	4.7
Running water, hot	3.6 ·	52	3. 9
Unimproved toilets, outdoors	181		***
Improved toilets, outdoors	1033	292	21.9
Improved toilets, outdoors Improved toilets, indoors	63	63	4.7
Tub or shower bath			200 800 0 808 220 2000
Kitchen sink with drain .	78		741 1 69.1
			the state of the s

Light and Heat

	llave now	New installation needed
Kerosene or gasoline lamps	1265 •	3-1, 3-1
Gas lights	25	-
Electric lights	6,0	50
Fireplaces	171	r: 1
Stoves	1307 :	20 .
Central heating systems	15	15

Refrigeration, Laundry, and Cooking Facilities

	Have	New installation
	now	needed ***
Ice boxes	469	91
Mechanical refrigerators	18	27
Washing machines, power	5.	13
Washing machines, hand	· · · 87	3
Wood or coal stoves	1312	87
Kerosene or gasoline stoves	117	5
Electric stoves	8	1

In answer to the question: If \$500 were available for you to spend in improving your house, the following items were mentioned, among others:

	Number of	Per cent of
· · · · · · · · · · · · · · · · · · ·		total farms
Interior walls, ceilings, floors	729	54.6
Exterior walls	589	44.1
Porches	475	35.6
Roofs	436	32.7
Doors, windows, screens	374	28.0
water systems	295	22.2
Additional rooms	213	16.0
Sanitary facilities	124	9.3
Furnishings	121	9.1
Foundations .	•110	8.2
Bath room equipment	104	7.8



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C

Release - Immediate

March 10, 1934

FARM HOUSING SURVEY (A Civil Works Administration Froject)

The Farm Pousing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the : country are being covered by the investigators.

Preliminary Report for Oldam County, Mentucky.
(Subject to later revision)

Reports on 1005 farm houses surveyed in Oldam County, Kentucky, have new been tabulated. There are 76 log houses, 1 earth house, 156 unpainted frame houses, 703 painted frame houses, 10 stucco houses, 44 brick houses, and 15 stone houses. An average of 6 rooms per house is shown. There were 783 farms in this county in 1929 and the farm population was 3776.

Condition of Houses

Of the 1005 houses surveyed, replacements, renewals, or new installations and repairs were needed as follows:

	Complete replacement renewals, or new installation needs	alterations	S
Insulation	511	7-	
Paint, exterior	314	305	
Soreens	292	185	
Roofs .	144	289	
Doors and windows	130	264	
Foundations	121	247	
Interior walls and ceil	lings 118	381	

Complete replacement of 20 houses was desired by the occupants.

Need for Additional Space Space requirements were as follows:

	Have now	rooms needed	are needed	houses in ional rooms
Bedrooms	2734	rooms 136	rooms 13.5	
Storage space for fresh				
fruits and vegetables	528	124	12.3	
Bathrooms	161	115	11.4	
Back porches	708	85	8,5	
Dining rooms	670	60	6.0	
Front porches	800	57	5.7	
Basements	303	57	5.7	
Living rooms	748	40	4.0	



U. S. DEPARTMENT OF AGRICULTURE



Water Supply and Sewage Disposal

	Have	New installation
	now	needed
Water carried by hand	784	•
Hand pump in dwelling	141	43
Running water, cold .	153	7
Running water, hot	83	4
Unimproved outdoor toilets	829	••
Improved toilets, outdoors	93	63
Improved toilets, indoors	108	22 .
Tub or shower baths	134	30
Kitchen sinks with drain	245	91

Light and Heat

	Have	New installation
	now.	needed
Kerosene or gasoline lamps	- 422	24
Gas lights	. 26	4
Electric lights	231	20
Fireplaces	421	11
Stoves	846	40
Central heating system .	168	15

Refrigeration, Laundry, and Cooking Facilities

	Have	. New installation
	now	nceded
Loe boxes	405	43
Mechanical refrigeration	67	7
Washing machines, power	122	27
Washing machines, hand	6 50	35
Wood or coal stoves	906	48
Kerosene or gasoline stoves	552	44
Gas or electric stoves	27	

Landscaping of House

	Have	New installation
	now	needed
Lawns established	900	74
Plantings	737	387
Walks and drives	610	415
Fences	721,	340

In answer to the question: If \$500 were available for you to spend in improving your house, the following items were mentioned, among others:

		Number c	f Fer cent of total
		farms	farm houses
	Interior walls, ceilings, floors	317	31,5
	Exterior walls	317	31.5
	Water system	224	22.3
	Roofs	214	21.3
	Porches	149	14.8
	Landscaping	147	14.6
	Additional rooms	129	12.8
	Bathroom equipment	88	8.8
	Furnishings	75	7.5
41	Foundations	73	7. 3
	Lighting systems	63	6,3
	Chimneys	61	6.1
	Heating systems	51	5.1



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON D C

Release - Immediate

March 12, 1934

FARM HOUSENS SUMMAY
(A Civil Works administration Project)

The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State gricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the : country are being covered by the investigators.

Preliminary Report for Perkins County, Nebraska. (Subject to later revision)

Reports on 834 farm houses surveyed in Perkins County, Nebraska, have been tabulated. There are 14 earth houses, 84 unpainted frame houses, 655 painted frame houses, 34 stucco houses, 12 stone houses, and 43 concrete houses. Of the houses surveyed 211 have been constructed less than 10 years, 416 houses between 10 and 24 years, 98 houses between 25 and 49 years, and 10 houses have been constructed for more than 50 years. There are 577 one story houses, and 257 houses which have more than one story. There is an average of 5 rooms per house. There were 1034 farms in the county in 1929 and the farm population was 3868.

Condition of Houses

Of the 834 farm houses surveyed in Perkins County, Nebraska, replacements, renewals or new installations and repairs were needed as follows:

	Complete replacement,	Repairs or
	renewals, or new	alterations
	installation needed	needed
Paint, exterior	331	177
Interior walls and ceiling	s 190	341
Screens	186	227
Insulation	166	216
Floors .	141	212
Roofs	128	239
Foundations	125	185
Doors and windows	114	252

Need for Additional Space Space requirements were as follows:

	liave now	Additional rooms needed	in which additional rooms are needed
Bedrooms	2078	rooms 408	reoms 40.9
Bathrooms	127	386	45.3
Basements	31.9	136	22.3
Front or side porches	333	146	17.5
Book perches	445	3.38	16.5
Dining rooms	453	137	16.4
Storage space for fresh	}		
fruits and vegetables	658	123	14.7

er and a second second

1

76 7

Water Supply and Sewage Disposal

	Have now	New installation needed	Per cent of farm houses in which new installation is needed
Water carried by hand	454	-	-
Hand pump in dwelling	164	43	5.2
Running water, cold	159	55	6.6
Running water, hot	69	384	46.0
Unimproved outdoor toilets	787	-	<u></u>
Improved indoor toilets	61	482	57.8
Tub or shower baths	121	681	81.7
Kitchen sinks with drain	348	364	43.6

Light and Heat

	Have now	New installation needed	Per cent of houses in which new installation is needed
Kerosene or gasoline lamps	674	22	26.4
Gas lights	35	3	•4
Electricity, home plant	141	157	18.8
Electricity, power line	17	133	15.9
Fire places	2	1	.1
Stoves	519	28	3.4
Central heating systems	280	288	34.5

Refrigeration, Laundry, and Cooking Facilities

	Ha v e now	New installation needed	Per cent of houses in which new installation is needed
Ice boxes	170	69	8.3
Mechanical refrigeration	28	248	29.7
Power washing machines	501	228	27.3
Hand washing machines	165	6	•7
Wood or coal cooking stoves	808	43	5.2
Kerosene or gasoline stoves		42	5.0
Gas stoves	24	3	•4
Electric stoves	1	31	3.7

Landscaping of Rouse

	Have	New	
	now	installation	
		needed	
Lawns established	74	323	
Walks and drives	158	291	
Fences	330	305	

In answer to the question: If \$500 were available for you to spend in improving your house, the following items were mentioned, among others:

Number of Per cent of t	otal
farms farm houses	
Additional rooms 341 40.9	
Water system 329 39.4	
Bathroom equipment 264 31.7	
Interior walls, ceilings, floors 248 29.7	
Exterior walls 176 21.1	
Roofs 144 17.3	
Furnishings 139 16.7	
Doors, windows, screens 112 13.4	

17 - J.

.

(i) (ii) where it is a second of the second

turi, i

•



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C

Release - Immediate

March 13, 1934

FARM HOUSING SURVEY
(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the : country are being covered by the investigators.

Preliminary Report for Knox County, Maine (Subject to Later revision)

Reports on 1000 farm houses in Knox County, Maine, have been tabulated. There are 55 unpainted frame houses, 933 painted frame houses, 12 stucco houses, and 1 stone house. There are 952 of the houses having more than one story and the average size is 8 rooms per house. There were 1845 farms in this county in 1929 and the farm population was 5794.

Condition of Houses

Of the 1000 farm houses surveyed, replacements, remainle, or now installations and repairs were needed as follows:

	Complete replacement, renewals, or new installation needed	Repairs or alterations needed	
Insulation	317	166	
Screens	115	55	IBRA
Paint, exterior	68	359	
Chimneys.	18	111	BUREAU CE
Doors, windows	18	81	(I GRIC JETT P COMMENT
Foundations	11	177	3/6
Roofs	6	252	OFF.
. ,	Need for Additional Space		PARTMENT OF AGRICULIU

Space requirements were as follows:

Have			al		
now	rooms			in which additional	EMDON .
	nee	eded		are needed	
158		60		15.8	
3920	rooms	131	rooms	13.1	
1					
885		5		•5	
563		3		•3	
	now 158 3920 1 885	now rooms 158 3920 rooms 1 885	now rooms needed 158 60 3920 rooms 131 885 5	now rooms needed 158 60 3920 rooms 131 rooms 885 5	now rooms needed in which additional are needed 158 60 15.8 3920 rooms 131 rooms 13.1 885 5 .5

Water Supply and Sewage Disposal

	Have	Now installation
	now	needed
Water carried by hand	338	-
Hand pump in dwelling	374	11
Running water, cold	327	5
Running water, hot	141	-
Unimproved outdoor toilets	655	
Improved outdoor toilets	171	-
Improved indoor toilets	180	_
Tub or shower baths	149	2
Kitchen sinks with drain	979	12
TEL CONON DINING WILLIAM (I CITI	313	١, ٢,

Light and Heat

	Have	New installation	
	now	needed	
Kerosene or gasoline lamps	485	1	
Gas lights	1	-	
Electric, home plant	15		
Electric, power line	503	2	
Fireplacés	35	2	
Stoves	901	3	
Central heating systems	247	-	4

Refrigeration, Laundry, and Cooking Facilities

Have	New installation
now	needed
427	, 39
37	-
244	-
71	1 .
961	6
82	-
. 2	
- 21	
	now 427 37 244 71

Landscaping of House

	llave now	New installation needed
Lawns established	7 94	19
Walks and drives	634	52
Fences	44	11

In answer to the question: If \$500 were available for you to spend in improving your house, the following items were mentioned, among others:

	Number of	For cent of toal
	farms	farm houses
Exterior walls'	333	33.3
Interior walls, ceilings,	floors 272	27.2
Roofs	213	21.3
Water system	. 194	19.4
Bathroom equipment	181	18.1
Foundations :	134	13.4
Lighting systems	84	8.4
Additional rooms	72	7.2



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C

Release - Immediate

_ March 13, 1934

FARM HOUSING SURVEY
(A Civil Works Administration Project)

: The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of im: provement for farm homes. About 300 counties throughout the : country are being covered by the investigators.

Preliminary Report for Snohomish County, Washington (Subject to later revision)

Reports on 2041 farm houses in Snohomish County, Washington, have been tabulated. The survey shows 18 log houses, 475 unpainted frame houses, 1542 painted frame houses, 4 stucce houses, 4 brick houses, 2 stone houses, and 1 concrete house. The average size of the farm houses in this county is 5 rooms. There were 4262 farms in this county in 1929 and the farm population was 13,482.

Condition of Houses

Of the 2041 farm houses surveyed, replacements; renewals, or new installations and repairs were needed as follows:

				•	
		, ·	Complete replacement, renewals, or new installation needed	Repairs or alterations needed	and the state of t
Pa	int, exterior		702	309	## T.
	reens		36 9	153	
Ro	ofs		385	344 //	EUT,
In	terior walls and	ceilings	267	434	IGRICULT.
	oors		233	359	4
Wa	lls, exterior	· · · · · · · · · · · · · · · · · · ·	220	226	5,
	sulation		204	171	EPARTNETH CONCULS OF
-	11				ARTMENT OF AGRICULT
					The state of the s

Need for Additional Space Space requirements were as follows:

	now roo			of farm houses additional rooms
Bedrooms	5426 rooms	598 rooms		29.3
Bathrooms	964	417		20.4
Basements	439	137	المناه يعيب	6.7
Storage space for fresh	•			
fruits and vegetables	1483	124		6.1
Front or side porches	1677	109		5.3
Back porches	1874	87		4.3
Dining rooms	99 5	84		4.1

Snohomish Co. Washington.

_ 2 _

Water Supply and Sewage Disposal

	Have	New installation	
	now	needed	
Water carried by hand	776	-	
Hand pumps in dwelling	87	2	
Running water, cold	1157	11	
Running water, hot	859	11	
Unimproved outdoor toilets	1286	-	
Improved outdoor toilets	120	1	
Improved indoor toilets	659	7	
Tub or shower baths	850	19	
Kitchen sinks with drain	1262	26	
	·		

Light and Heat

	Have	New installation	
	now ·	needed	
Kerosene or gasoline lamps	319	· 4	
Gas lights	3	-	
Electric, home plant	6.		
Electric, power line	1724	3	
Fireplaces	153	19	
Stoves	1491	166	
Central heating system	373	6	

Refrigeration, Laundry, and Cooking Facilities

	Have	New installation
,	now	needed
Ice boxes	54	7
Mechanical refrigeration	44	2
Washing machines, power	977	42
Washing-machines, hand	129	
Wood or coal cacking stoves:	1954	159
Kerosene or gaseline stoves	23	-
Gas stoves	8	· •
Electric stoves	235	1

Landscaping of House

The state of the s	Have now	New installation needed
Lawns established	1123	74
Walks and drives	999	123
Fences	1238	230

In answer to the question: If \$500 were available for you to spend in improving your house, the following items were mentined; among others:

· ·			
.Vi	umber of	Per cent of	total
	nms	farm houses	
Interior walls, ceilings, floors	892	43.7	
Exterior walls	7 99	39.1	
Bathrooms	730	35.8	
Additional rooms	-593	29.1	
Water system	550	26.9	
Foundations.	529	25.9	
Roofs	500	24.5	
Furnishings	257	12.6	
Doors, windows, screens	235	11.5	
Porches	232	11.4	



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C

Release - Immediate

March 13, 1934

FARM HOUSING SURVEY
(A Civil Works Administration Project)

The Farm Mousing Survey is a Givil Works Administration:
project, carried out by the U.S. Pepartment of Agriculture and:
the State Agricultural Extension Services. The object is to
provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the
country are being covered by the investigators.



Preliminary Report for Acadia Parish, Louisiana (Subject to later revision)

Reports on 3575 farm houses surveyed in Leadia Parish, Louisiana, have been tabulated. There are 10 earth houses, 2755 unpainted frame houses, 808 painted frame houses, and 2 stucco or brick houses. The report shows 3280 one story houses and 295 houses having more than one story with an average of 4 rooms per house. There were 3228 farms in this parish in 1929 and the Farm population was 19,813.

Condition of Houses

Of the 3575 farm houses surveyed, replacements, renewals or new installations and repairs were needed as follows:

	Complete replacement,	Fenairs or
	renewals, or new	filterations
* * * * * * * * * * * * * * * * * * * *	installation needed	needed
Screens	1083	727
Roofs	948	1047
Chimneys	871	527
Doors and windows	895	1341
Foundations	- 778	1105
Walls, exterior	. 723	1218
Interior walls and ceiling	607	655
Paint, exterior	446	92
Floors	444	818

Need for idditional Space Space requirements were as follows:

	Have now	Additional rooms		Per ce		houses	
		ne	eded		rooms		
Bedrooms	8432	rooms	1817	rooms		50.8	
Front or side porches	2142		629		•	17.6	
Back porches	1330		474			13.3	
Living rooms	1127		288			8.1	
Dining rooms	1324		210			5.9	

	Have	New installation	
	now.	needed	
Water carried by hand	3136	-	
Hand pumps in dwelling	225	3	
Running water, cold	293	3	
Running water, hot	23	to	121 1
Unimproved outdoor toilets	2705	_	11.1
Improved outdoor toilets	167		
Improved indoor toilets	85	. 1	
Tub or shower baths	217	5	
Kitchen sinks with drain	TRI	Ā	

Light and Heat

	Have New new installation needed	Per cent of farm houses in which new installations are needed
Kerosene or gasoline lamps Gas lights Electric lights Fireplaces Stoves	52 5 127 3 1800 198 1372 134	2.8 .1 .1 5.5 3.7
Central heating plants	52 -	

Refrigeration, Laundry, and Cooking Facilities

	Have	New installation
	now .	needed
	266	6
Mechanical refrigeration	39	
Washing machines, power '	6	in the National State of the St
Washing machines, hand	7	-
Wood or coal stoves	3304	387
Kerosene or gasoline stove		65
Gas or electric stoves	20	1


Landscaping of Houses

	Have	New installation	
	now	needed	
Lawns established	591	2	
Walks and drives	237	18	
Fences	2736	398	

In answer to the question: -If-\$500 were available for you to spend in improving your home, the following items were mentioned, among others:

	and the second of the second	
	Number of	Per cent of total
	farms	farm houses
Windows, doors, and screens	2419	67.7
Exterior walls	1362	52.1
Interior walls, ceilings, flo	prs 1762	49.3
Roofs	1726	48.3
Sanitary facilities	1591	44.5
Additional rooms	1540	43.1
Foundations	1351	37.8
Porches	1266	35.4
Water system	999	27.9
Furnishings	983	27.5

These are all preliminary data subject to revision prior to publication of the data.



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



Release - Immediate

WASHINGTON, D. C

Narch 14, 1934

FIRM HOUSING SURVEY
(A Civil Works Administration Project)

The Farm Housing Survey is a Civil works Administration: project, carried out by the U.S. Department of griculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the : country are being covered by the investigators.



Preliminary Report for Benton County, Indiana (Subject to later revision)

Reports on 1392 farm houses surveyed in Benton County, Indiana, have been tabulated. There are 100 unpainted frame houses, 1241 painted frame houses, 13 stucco houses, 24 brick houses, 2 stone houses, and 5 concrete houses. Of the 1392 houses surveyed 1226 houses have more than one story. In average of 10 rooms per house is shown. There were 1195 farms in this county in 1929 and the farm population was 6225.

Condition of Houses

Of the 1392 farm houses surveyed, replacements, renewals, or new installation and repairs were needed as follows:

	Complete replacement,	Repairs or
•	renewals, or new	alterations
	installation needed	needed
Paint, exterior	564	212
Screens	331	239
Foundations	150	239
Interior walls and ceilings	146	408
Roofs	142	244
Insulation	111	58
Doors and windows	110	365
Floors	102	239

Need for Additional Space Space requirements were as follows:

	Have now	Additi rooms needed		Per cent of farm houses in which additional rooms are needed
Bathrooms	380	11	2	8.0
Storage space for fresh				
	916	7	5	5.5
Bedrooms		rooms 7	5 rooms	5.4
Wash rooms for farm bely	258	6	4	4.6

Water Supply and Sewage Disposal

	Have now	New installation needed	Per cent of farm houses in which new installation is needed
Water carried by hand	982		
Hand pumps in dwelling	377	123	8.8
Running water, cold	415	65	4.7
Running water, hot	211	60	4.3
Unimproved outdoor toilets	721	-	
Improved outdoor toilets	449	6	•4
Improved indoor toilets	231	. 94	6.8
Tub or shower baths	374	121	8.7
Kitchen sinks with drain	889	114	€.2

Light and Heat

	Have	New installation
	now	necded
Kerosene or gasoline lamps	1096	1
Gas lights	66	3
Electricity, home plant	180	13
Electricity, power line	7 8	345
Fireplaces	34	-
Stoves	882	16
Contral heating systems	578	65

Refrigeration, Laundry and Cooking Facilities

	Have now	New installation needed	Per cent of farm houses in which new installation is needed
Ice boxes	258	23	1.7
Mechanical refrigeration	33	73	5.2
Mashing machines, power	635	69	5.0
Washing machines, hand	423	21 -	1.5
Wood or coal cooking stoves	1335	37	2.7
Kerosene or gasoline stoves	406	7	•5
Gas stoves	8	-	* ************************************

Landscaping of Houses

	Have	New installation
	now	needad
Lawns established	1212	62
Walks and drives	1018	257
Fences	1118	384

In answer to the question: If \$500 were available for you to spend in improving your house, the following items were mentioned, among others:

	Number of forms	Per cent of total
Bathrooms equipment	277	19.9
Water systems	238	17.1
Furnishings	195	14.0
Interior walls, ceilings, floors	188	13.5
Exterior walls	181	13.0
Electricity, home plant	72	5.2
Electricity, power line	180	12.9
Heating systems	155	11.1



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



DEPARTMENT OF AGRIC

Release - Immediate

WASHINGTON, D. C.

March 14, 1934

FARM HOUSING SURVEY (A Civil Works Administration Project)

The Farm Housing Survey is a Civil orks Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of im-: provement for farm homes. About 300 counties throughout the : country are being covered by the investigators.

Preliminary Report for Cuming County, Nebraska (Subject to later revision)

Reports on 1770 farm houses in Cuming County, Nebraska, have been tabulated, of which one house was earth, 1719 painted frame, 11 unpainted frame, 24 stucco, 21 brick, 1 stone, and 1 concrete house. There are 129 one story houses and 1641 houses which have more than one story. An average of 7 rooms is shown. There were 1943 farms in this county in 1929 and the farm population was 9562. Some of the most significant facts shown by the preliminary report are as follows:

Condition of Houses

Of the 1770 farm houses surveyed, replacements, renewals, or new installations and repairs were needed as follows:

	Complete replacement,	Repairs or
	renewals, or new	alterations
	installation needed	needed
Paint, exterior	683	255
Screens	219	468
Foundations	147	549
Roofs	142	446
Interior walls and ceilings	104	583
Foundations Roofs	147 142	549 446

Complete replacement of 56 farm houses was desired by the occupants.

Space requirements were as follows:

	Have now	Additional rooms needed	Per cent of farm houses in which additional rooms are needed
Bathrooms Bedrooms Basements Dining rooms	499	345	19.5
	6380 rooms	106 rooms	6.0
	1142	66	3.7
	1384	36	2.0

Water Supply and Sewage Disposal

	Have	New	Per cent of farm h	iouses
	now	installation	in which new insta	llation
		needed	is needed	
Water carried by hand	856			
Hand pump in dwelling	362	35	2.0	
Running water, cold	547	206	11.6	
Running water, hot	284	205	11.6	
Unimproved outdoor toilet	s1479	_	Assa	
Improved outdoor toilets	17	9	•5	
Improved indoor toilets	348	480	27.1	1. 1.
Tub or shower baths	502	527	29.8	2114-34
Kitchen sinks with drain	1078	217	12.3	_

Light and Heat

	Have	New .	Per cent of farm houses
	now	installation	in which new installation
		needed	is needed
Kerosene or gasoline lamps	1215	3	•2
Gas lights	38	2	.1
Electricity, home plant	434	96	5.4
Electricity, power line	114	112	6.3
Fire places	2	-	_
Stoves	1122	3	•2
Central heating systems	726	117	6.6

Refrigeration, Laundry, and Cooling Facilities

	Have	New installation
	now	needed
Ice bexes	155	42
rechanical refrigeration	29	8
Washing machines, power	1382	80
Washing machines, hand	281	10
Wood or coal cooking stoves	1749	22
Kerosene or gasoline stoves	457	44 .
Gas stoves	• 22	1
Electric stoves	8	-

Landscaping of House

	·Have	New installation
	now	needed
Lawns established	1045	267
Walks and drives	1163	² 04
Fences	1277	187 -

In answer to the question: If \$500 were available for you to spend in improving your home, the following items were mentioned, among others:

	Number of farms	Per cent of total farm houses
Bathroom equipment	484	27.3
Water systems	468	26.4
Interior walls, ceilings, floors	419	23.7
Exterior walls	410	23.2
Additional rocms	339	19.2
Foundations	231	13.1
Doors, windows, screens	226	12.8
Roofs	217	12.3
Sanitary facilities	197	11.1
Electricity	148	8.4
Porches	140	7.9
Heating systems	124	7.0

These are all preliminary data, subject to change prior to publication of the data.



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



Release - Immediate

WASHINGTON, D. C

March 15, 1934

FARM BOULING SURMEY

(A Civil Works Administration Project)

The Farm Housing Survey is a Civil works Administration: project, carried out by the U.S. Department of agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the : country are being covered by the investigators.



Preliminary Report for Beauregard Parish, Louisiana (Subject to later revision)

Reports on 1371 farm houses surveyed in Beauregard Parish, Louisiana, have been tabulated. The survey shows 117 log houses, 839 unpainted frome houses, 411 painted frame houses, 2 stucco houses, and 2 brick houses. Of the houses surveyed, 1296 are one story and an average of 4 rooms per house are shown. There were 1374 farms in this parish in 1929 and the farm population was 7056.

Condition of Houses

Of the 1371 houses surveyed, replacements, renewals, or new installations and repairs were needed as follows:

	Complete replacement,	Repairs or
	renewals, or new	alterations
	installation needed	needed
Doors and windows	631	360
Roofs	524	267
Foundations	449	328
Floors	408	446
Chimneys	406	215
Interior walls and ceilings	376	370
Walls, exterior	327	460

Space Requirements were as follows:

	Have	Additional	Per cent of farm houses
	now	rooms	in which additional
		needed	rooms are needed
Storage Space for	fresh fruits		
	454	673	49.1
	115	667	48.7
Dining rooms	659	3 88	28.3
Work rooms	91	357	26.0
Living rooms	606	3 36	24.5
Bedrooms 3	126 rooms	630 rooms	46.0

Water Supply and Sewage Disposal

	Have	New installation
	now	needed
Water carried by hand	1295	-
Hand pump in dwelling	2.1	3
Running water, cold	76	1
Running water, hot	31	-
Unimproved outdoor toilets	836	_
Improved outdoor toilets	175	4
Improved indoor toilets	. 35	3

Heat and Light

	Have	New	Fer cent of farm h	
	now	installation	in which new insta	ullations
<u> </u>		needed	are needed	
Kerosene or gasoline lamps	1289	151	11.0	
Gas lights	27	-	-	
Electricity	. 74	2	.1	
Fireplaces	900	144	10.5	
Stoves	360	3 9	2.8	
Central heating systems	5	1	.1	

Refrigeration, Laundry, and Cooking Facilities

	Have	New installation
Ice boxes	206	8
Mechanical refrigeration	34	<u> </u>
Washing machines, power	5	_
Washing machines, hard	24	· 2
Coal or wood cooking stoves	1349	277
Kerosene or gasoline stoves	99	6 -
Gas or electric stoves	14	1

Landscaping of House

	Have now	New installation needed
Lawns established	274	9
Walks and drives	155	15
Fences	1039	20,9

In answer to the question: If \$500 were available for you to spend in improving your house, the following items were mentioned, among others:

1 What	Number of farm	Per cent of total
	houses	farm houses
Doors, windows, screens	960	70.0
Interior walls, ceilings,	floors 790	57.6
Exterior walls	677	49.4
Roofs '.	655	47.8
Porches	634	46.2
Additional rooms	623	45.4
Chimneys -	592	43.2
Foundations	571	41.6
Water systems	484	35.3
Furnishings	464	33.8
Bathroom equipment	422	30.8
Sanitary facilities	343	25.0

FARM HOUSING SURVEY (A Civil Works Administration Project)

: The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Egricultural Extension Services. The object is to provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the country are being covered by the investigators.

Preliminary Report for Cleveland County, North Carolina (Subject to later revision)

Reports on 2871 farm houses in Cleveland County, North Carolina, have been tabulated. There are 78 log houses, 1899 unpainted frame houses, 843 painted frame houses, 3 stucco houses, 40 brick houses, 2 stone houses, and 6 concrete houses. The survey shows 2399 one story houses and 472 houses which have more than one story. In average of 5 rooms per house is shown. There were 5181 farm houses in this county in 1929 and the farm population was 30,030. Some of the most significant facts—shown by the preliminary report are as follows:

Condition of Houses

Of the 2871 houses surveyed, replacements, renewals, or new installations and repairs were needed as follows:

	Complète replacement,	Repairs or
	renewals, or new	alterations
· · · · · · · · · · · · · · · · · · ·	installation needed	needed
Paint, exterior	2177	155
Screens	1635	547
Interior walls and ceiling	s 531	·747 // E
Roofs	404	821 (AGRIC
Doors and windows	357	1146
Floors	339	959
Foundations	241	854 DEFARIMENT
And the second s		THE WILLIAM

Need for 'dditional Space Space requirements were as follows:

• 5 • 3	now	ndditional rooms needed	in which additional rooms are needed
Redrooms		rooms 1170	
Living rooms	1261	1091	38.0
Dining rooms	1524	975	34.0
Storage Space for fresh			
fruits and vegotables		937	32.6
Work rooms	814	711	24.8
Back porches.	2067	708	24.7

Noter Supply and Sewage Disposal

	now	New installation needed	Far cent of farm house in which new installat is needed	
Water carried by hand	2356			
Hand pump in dwelling	164	447	15.6	
Running water, cold	155	754	26.3	
Running water, hot	71	127	4.4	
Unimproved outdoor toilets	1599	-		
Improved outdoor toilets	·357	2303	80.2	
Improved indoor toilets	63	36	3.0	
Tub or shower baths	98	430	15.0	
Kitcher sinks with drain	233	2472	86.1	

. Light and Heat

			•
	Have	CW .	for cent of farm houses
:	now	installation	in which new installation
Factor of the second of the se		needed	is needed
Kerosene or gasoline lamps	2395	171	6.0
Gas lights	. 24	: =	-
Electricity, home plant	31	14	•5
Electricity, hower line .	400	938	32.7
Fireplaces	2702:	60.	2.1
Stoves	270	14	.5
Central heating systems	43	. 17	.6
		·····	~

Refrigeration, Laundry, and Cooking Facilities

	Have now	New installation needed	Per cent of farm houses in which new installation is needed
Ice boxes	702	1158	40.3
Mechanical refrigeration	41	72	2.5
Washing machines, power	54	106	3.7
Washing machines, hand	33 -	35	1.2
Wood or coal cooking stoves	2788	389	13.5
Kerosene or gasoline stoves	68	12	• • 4
Electric stoves	15	11	.4

In answer to the question: If \$500 were available for you to spend in improving your house, the following items were mentioned, among others:

		The state of the s
Marie Carlos Car	Number of	Per cent of total
	farms	farm houses
Sanitary facilities	2062	71.8
Interior walls, ceilings,	floors 1650	57.5
Doors, windows, screens	1530	53.3
Exterior walls "	1444	50.3
Porches	. 970	33.9
Additional rooms	963	35.5
Roofs	950	33.1
Water systems	912	31.8
Furnishings	620	21.6
Foundations	547	19.1



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



Release - Immediate

WASHINGTON, D. C

March 17, 1934

FARM HOUSING SURVEY (A Civil Works Administration Project)

The Farm Mousing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the :country are being covered by the investigators.

Preliminary Report for Otoe County, Nebraska (Subject to Later Revision)

Reports on 2093 farm houses surveyed in Ttoe County, Nebraska, have been tabulated. The survey shows 344 one story houses and 1749 houses which have more than one story. There is an average of 7 rooms per house. There were 2280 farm houses in this county in 1929 and the farm population was 9617. Some of the most significant facts shown by the preliminary report are as follows:

Condition of Houses

	Complete replacement, renewals, or new installation needed	Repairs or alterations needed	TBP A.D.
Paint, exterior Screens	356 178	302 299	A RERICULTURAL ET
Interior walls, ceilings Roofs	127 126	324 287	100
Foundations Floors	115 101	277 165	DEPARTMENT OF AGRICULT

In 118 of the houses surveyed complete replacement was desired by the occupants.

Space requirements were as follows:

	Have	7.dditional	
	now	rooms	in which additional
		needed	rooms are needed_
Bedrooms	6003	rooms 218	rooms 8.0
Bathrooms	490	102	4.9
Washrooms for farm help	234	59	2.8
Storage space for fresh		;	•
	1560	59	2.8
Dining rooms	1581	57	2.7

Water Supply and Sewage Disposal

	Have now	New installation needed	Per cent of farm houses in which new installation is needed
Water carried by hand	1378		-
Hand pump in dwelling	405	9	•4
Running water, cold	254	627	30.0
Running water, hot	312	175	8.4
Unimproved outdoor toilets	1802	_	_
Improved outdoor toilets	13	2 8	1.3
Improved indoor toilets	340	462	20.1
Tub or shower baths	465	509	24.3
Kitchen sinks with drain	937	425	20.3

Light and Heat

	Havc· ·	New installation	
	now	needed	
Kerosene or gasoline lamps	1543	16	
Gas lights	40	. 1	:
Electricity, home plant	289	112	
Electricity, power line	250	184	
Fireplaces	18	2	
Stoves	1410	7	
Central heating systems	716	162	
Electricity, power line Fireplaces Stoves	18 1410	2 7	

Refrigeration, Laundry, and Cooking Facilities

Have	New installation	
	necaca	
- 522 -	25	
97	9	
1320	85	
552	22	
2039 ·	36	
774	23	
22	2	
16	7	1
	now 522 97 1320 552 2039 774 22	now needed 522 25 97 9 1320 85 552 22 2039 36 774 23 22 2

Landscaping of House

	Have now	New installation needed
Lawns established	1420	232
Walks and drives	1356	2 7 4
Fences	1373	271

In answer to the question: If \$500 were available for you to spend in improving your house, the following items were mentioned, among others:

	Number of	Per cent of total
•	farms	farm houses
Water system	569	27.2
Sanitary facilities	489	23,4
Interior walls, ceilings, floors	461	22.0
Bathroom equipment	453	21.6
Exterior walls	365	17.4
Electricity	331	15.8
Additional rooms	295	14.1
Furnishings	220	10.5
Roofs	216	10.3
Doors, windows, Screens	205	9.8
Porches	199	9.5
Heating systems	188	9,0
		



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C

Release - Immediate

March 17, 1934

FARM HOUSING SURVEY
(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the : country are being covered by the investigators.

Freliminary Report for Duplin County, North Carolina (Subject to later revision)

Reports on 2311 farm houses surveyed in Duplin County, North Carolina, have been tabulated. There are 22 log houses, 1600 unpainted frame houses, 685 painted frame houses, 3 brick houses, and one concrete house. The survey shows 2041 one story houses and 270 houses which have more than one story. In average of 5 rooms per house is shown. There were 4970 farm houses in this county in 1929 and the farm population was 26,210. Some of the most significant facts shown by the preliminary totals are as follows:

Condition of Houses

Of the 23ll farm houses surveyed, replacements, renewals, or new installations and repairs were needed as follows:

		Complete replacement,	Repairs or	
		renewals, or new	alterations	
		installation needed	needed	
Screens		1669	402	D
Paint, exterior		1642	437	15 F-/
Interior walls,	ceilings	358	1714	BUST
Roofs		101	1394	
Foundations		98	1533 (AGRICU	on.
Floors		91	1626	
Chimneys		75	1084	1
Walls, exterior		51	1383	TIMENT OF ASI

Red for Additional Space Space requirements were as follows:

	Have	Additional	Per cent of farm houses
	now	rooms	in which additional
		nceded	rooms are needed
Living rooms	901	531	23.0
Bedrooms	5966 rooms	506 rooms	18.6
Back porches	1273	445	19.3
Dining rooms	917	358	15.5
hork rooms	233	262	11.3
Front porches	1944	25 9	11.2

water Supply and Lewage Disposal

	Have now	New: installation needed	Per cent of farm houses in which new installation is needed
Water carried by hand	1653		
Hand pump in dwelling	660	832	36.0
Running water, cold	26	71	3.1
Running water, hot	10	27	1.2
Unimproved outdoor toilets	1473	-	
Improved outdoor toilets	134	1987	86.0
Improved indoor tailets	39	36	1.6
Tub or shower baths	26	92	4.0
Kitchen sinks with drain	185	1010	43.7

d Light and Heat

- Committee of the second seco	Have	.vew	For cent of farm houses
	now	installation	in which new installation
		necded	is needed
Kerosene or gasoline lamps	2191	141	6.1
Gas lights	35	3	.1
Electricity, home plant	20	43	1.9
Electricity, power line	6 8	324	14.0
Fireplaces	2052	44	19.0
Etoves	374	31	1.3
Central Heating systems	3	3	• 1
	~		

Refrigeration, Laundry, and Cooking Facilities

	Have now	Yew installation needed
lce boxes	142	115
Mechanical refrigeration	10	13
Washing machines, power	4	7
Washing machines, hand	26	224
Wood or coal cooking stoves	2122	328
Kerosene or gasoline stoves	152	6

Landscaping of House

	Have now	New installation needed
Lawns established	42	272
Walks and drives	155	2୨0
Fences	100	3 87

In answer to the question: If \$500 were available for you to spend in improving your home, the following items were mentioned, among others:

	Number of	Per cent of total
	farms	farm houses
Interior walls, ceilings,	floors 1661	71.9
Doors, windows, screens	1451	62.8
Exterior walls	1276	55.2
Roofs	1.032	44.7
Foundations	871	37.7
Porches	834	36.1
Sanitary facilities	790	34.2
Additional rooms	509	25.9
Water systems	592	2 5.6
Chimneys	481	20.8
Furnishings	407	17.5



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE




Release - Immediate

WASHINGTON, D. C

March 19, 1934

FARM HOUSING SURVEY

The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the : country are being covered by the investigators.



Reports on 2631 farm houses surveyed in Arkansas County, Arkansas, have now been tabulated. There are 118 log houses, 1583 unpainted frame houses, 927 painted frame houses, 2 stucco houses, and 1 brick house. The survey shows 1970 one story houses and 661 houses which have more than one story. The average size is 4 rooms per house. There were 25.1 farms in this county in 1929 and the farm population was 12,973. Some of the most significant facts shown by the preliminary reports are as follows:

Condition of Houses

Of the 2631 farm houses surveyed, replacements, renewals, or new installations and repairs were needed as follows:

7	Complete replacement,	Repairs or
· A	renewals, or new	alterations
	installation needed	needed
Paint, exterior	1426	266
Paint, exterior Interior walls and ceilings	795	597
Foundations	652	409
Roofs	63 9	583
Chimneys	582	225
Windows and doors	494	661
Walls, exterior	383	518
Floors	3 68	393

Need for Additional Space Space requirements were as follows:

		4.	1,0
	Have	Additional	
	now	rooms	in which additional
<u> </u>		needed	rooms are needed
Bedrooms	6049	rocms 337 roc	ms 10.5
Storage space for fresh			
fruits and vegetables	380	190	7.2
Back porches	1257	177	6.7
Living rooms	1254	146	5.5
Front or side porches	1977	123	4.7
Wash rooms for help	56	101	3.8

Water Supply and Sewage Disposal

	Har o	New installation
	new	needod
Water carried by hand	2492	-
Hand pump in dwelling	30 .	66
Running water, cold	171	57
Running water, hot	6 2	51
Unimproved outdoor toilets	1948	
Improved indoor toilets	⁻ 62	56
Improved outdoor toilets	107	979
Tub or shower baths	129	132
Kitchen sinks with drain	196 .	78

Light and Heat

	Have	New installation
	now	needed
Kerosene or gasoline lamps	2429	-4
Gas lights	25	2
Electricity, home plant	80	7.7···
Electricity, power line.	149	75
Fireplaces .	234	64.
Stoves .	2437	98
Central heating system	26	

Refrigeration, Laundry, and Cooking Facilities

	Have	New installation
	now	needed
Ice boxes	611	30
Mechanical refrigeration	59	38
Washing machines, power	295	72
Washing machines, hand	105	20
Wood or coal cooking stoves	2494	84
Kerosene or gasoline stoves	474	13
Gas stoves	12	44
Electric stoves	10	12

Landscaping of House

now needed Lawns established 1256 516 Walks and drives 296 943 Fences 1822 648		Have	New installation	
Walks and drives 296 943	<u> </u>	now	needed	
	Lawns established	1256	516	
Fences 1822 648	Walks and drives		943	
2022	Fences	1822	648	

In answer to the question: If \$500 were available for you to spend in improving your home, the following items were mentioned, among others:

the state of the s			
	Number farms	of	Per cent of total farm houses
Trat and an evalla and lands		675	
Interior walls, ceilings,	ITOOLS	672	25.5
Doors, windows, screens		617	23.5
Exterior walls	t^* .	583	22.2
Roofs	6.4	550	20.9
Porches		546	- 20.8
Foundations .	7, 1	471	« 17. 9
Additional rooms		387	14.7
Water systems	•	359	13.6
Bathroom equipment		300	11.4
Chimneys		270	10.3
Furnishings		252	9.6



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



March 21, 1934

WASHINGTON, D. C.

Release - Immediate

FARM HOUSING SURVEY (A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration:

project, carried out by the U.S. Department of Agriculture and:

the State Agricultural Extension Services. The object is to

provide the basic information necessary for a program of im
provement for farm homes. About 300 counties throughout the

country are being covered by the investigators.

Preliminary Report for Fleming County, Ky. (Subject to later revision)

Reports on 1907 farm houses in Fleming County, Kentucky have been tabulated. There were 261 log houses, 380 unpainted frame houses, 1217 painted frame houses, and 49 brick. There were 2642 farms in the county reported in 1929 and the farm population was 9329. Some of the most significant facts shown by the preliminary totals are as follows:


Condition of Houses

Of the 1907 houses surveyed, new installations, replacements, and repairs or alterations were needed as follows:

	Complete replacement	
	or renewal	Repairs
Paint, exterior	498	380
Screens	3 84	352
Roofs	207	387
Insulation	259	255
Interior walls and ceilings	121	355
Floors	117	301
Doors and windows	111	442
Chimneys	103	186

Need for Additional Space Space requirements were as follows:

	Have		Per cent	
	now	installat	tion in which	additional
		needed	rooms are	needed
Storage space for fresh	_			
fruits and vegetables	867	450	23.6	
Back porches	1225	224	11.7	
Front or side porches	1461	205	10.7	
Work rooms	374	175	9.2	
Dining rooms	1480	70	3.7	
Bed rooms	5018	rooms 183	rooms 7.1	



Water Supply and Sewage Disposal

	Have now	New installation needed	Per cent of houses in which new installation is needed
Water carried by hand	1785		-
Hand pump in dwelling	101	88	4,6
Running water cold	59	6	•3
Unimproved toilets	1656	-	-
Improved toilets, outdoor	20	547	28.7
Improved toilets, indoor	38	7	• 4
Tub or shower bath	47	14	•7
Kitchen sink with drain	139	83	4.4

Light and Heat

	Fave now	New installation needed	
Kerosene or gasoline lamps	1789	37	
Gas lights	19	2	
Electricity, home plant	7 8	4	
Electricity, power line	34	5	
Fireplaces	985	4	
Stoves	1324	48	
Central heating systems	151	-	

Refrigeration, Laundry, and Cooking Facilities

	Have now	New installation
Ice boxes	492	59
Mechanical refrigeration	5	-
Washing machines, pawer	99	5
Washing machines, hand	1737	9

Landscaping of House

	Have	New installation	
	now	needed	
Lawms established	1569	183	
Walks and drives	747	511	
Fences	1397	521	

In answer to the question: If \$500 were available for you to spend in improving your house, the following items were mentioned, among others:

	Number of	Per cent of total
	farms	fam. houses
Additional rooms	102	5.3
Exterior walls	78	4.1
Porches	72	3.8
Water systems	68	3.6
Electricity	60	3.1
Interior walls, ceilings, floors	58	3.0
Doors, windows, screens	53	2.8
Roofs	47	2.5
Sanitary facilities	40	2.1
Bathroom equipment	40	2.1



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C.

Release - Immediate

March 21, 1934

FARM HOUSING SURVEY
(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to: provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the: country are being covered by the investigators.



Preliminary Report for Faulker County, Arkansas (Subject to later revision)

Reports on 3370 farm houses in Faulkner County, Arkansas, have now been tabulated. There are 153 log houses, 2211 unpainted frame houses, 979 painted frame houses, 5 stucco houses, 7 brick houses, 14 stone houses, and 1 concrete house. There are 3236 one story houses and 134 houses which have more than one story. There were 4204 farms in this county in 1929 and the farm population was 21,467. Some of the most significant facts shown by the preliminary totals are as follows:

Condition of Houses

Of the 3370 farm houses surveyed, replacements, renewals, or new installations and repairs were needed as follows:

	Complete replacement	
	renewals, or new	alterations
	installation needed	needed
Paint, exterior	2099	437
Screens	1388	928
Interior walls and ceilings	1454	801
Roofs	714	1253
Foundations	576	1521
Doors and windows	530	1452
Chimneys	523	1177
Floors	429	1540
Walls, exterior	. 361	1628

Need for Additional Space Space requirements were as follows:

	Have			Per cent of farm houses
	now	roo	ms	in which additional
		nee	ded	rooms are needed
Storage space for fresh				
fruits and vegetables	764		1449	43.0
Bedrooms	6643	rooms	1374 rooms	30.4
Back porches	1887		594	17.6
Dining rocms	1237		550 1	16.3
Work rooms	292		402	11.9
Living rocas	1172		396	11.8



Water Supply and Sewage Disposal

6			
	Have	New installation	
	now	needed	
Water carried by hand	3282		
Hand pump in dwelling	106	2	
Running water, cold	34	10	
Running water, hot	16	3	
Unimproved outdoor toilets	2 3 56		
Improved outdoor toilets	135		
Improved indoor trilets	56	1	
Tub or shower baths	39	55	
Kitchen sinks with drain	148	335	

Light and Heat

	Have now	New installation needed
Kerosene or gasoline lamps	3236	271
Gas lights	2	_
Electricity	166	4
Fireplaces	1702	78
Stoves	1766	5 3
Central Heating systems	7	5

Refrigeration, Laundry, and Cooking Facilities

	Have	New installation
	now	needed
Ice boxes	331	1000
Mechanical refrigeration	128	58
Washing machines, power	28	_
Washing machines, hand	14	119

Landscaping of House

	Have	New installation
	now	needed
Lawns established	1213	1968
Walks and drives	442	2465
Fences	1032	2044

In answer to the question: If \$500 were available for you to spend in improving your house, the following items were mentioned:

	Number of	Per cent of total
	farms	farm houses
Interior walls, ceilings,	floors 1423	42.2
Exterior walls	1044	31.0
Roofs	1037	30.8
Furnishings	951	28.2
Doors, windows, screens	868	25.8
Additional rooms	864	25.6
Porches	555	15.9
Foundations	522	15.5
Water systems	292	8.7
Bathroom equipment	269	8.0
Laundry facilities	221	6.6
Sanitary facilities	203	6.0





U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C.

Release - Immediate

March 22, 1934

-34

FARM HOUSING SURVEY
(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the : country are being covered by the investigators.

Preliminary Report for Stevens County, Minnesota (Subject to later revision)

Reports on 1250 farm houses surveyed in Stevens County, Minnesota, have now been tabulated. There were 1292 farms in this county in 1929 and the farm population was 6355. Some of the most significant facts shown by the preliminary totals are as follows:

Condition of Houses

Of the 1250 farm houses surveyed, new installations, replacements, or renewals and repairs were needed as follows:

	Complete replacement,	Repairs or
	renewals or new	alterations
	installation needed	needed
Screens	409	172
Paint, exterior	3 68	225
Foundations	206	266
Floors	183	163
Doors and windows	180	283

Need for Additional Space Space requirements were as follows:

	Have	Additional	Per cent of farm houses
	new	rooms	in which additional
		needed	rooms are needed
Bedrooms	4374 r	ooms 99 rooms	5.5
Basements	615	66	5.3
Dining rooms	738	26	2,1

mater Supply and Sewage Disposal

	Have now	New installation needed	Fer cent of farm houses in which new installation is needed
Water carried by hand	1142	-	-
Hand pump in dwelling	670	118	9.4
Running water, cold	90	55	4.4
Running water, hot	38	24	1.9
Improved outdoor toilets	247	44	3.5
Unimproved outdoor toilets	949		-
Improved indoor toilets	73	67	5.4
Tub or shower baths	91	200	16.0
Kitchen sinks with drain	374	577	46.2 218



Light and Heat

	Have	New installation	
	now	needed	
Kerosene or gasoline lamps	1130	30	
Gas lights	17	_	
Electricity, home plant	82	12	
Electricity, power line	43	112	
Stoves	801	28	
Central heating system	449	39	

Refrigeration, Laundry, and Cooking Facilities

	llave	New installation
	now	needed
Ice boxes	56	45
Mechanical refrigeration	11	18
Washing machines, power	609	208
Washing machines, hand	256	12
Wood or coal cooking stoves	1194	45
Merosene or gas stoves	536	90
Gas or electric stoves	9	1

Landscaping of House

	Rave	New installation
	now	needed
Lawns established	707	528
Walks and drives	217	273
Fences	342	362

In answer to the question: If \$500 were available for you to spend in improving your house, the following items were mentioned among others:

	Number of farms	Per cent of total farm houses
Interior walls, ceilings, floor	s 303	24.2
hater systems	290	23.2
Furnishings	232	18.6
Additional rooms	200	16.0
Laundry facilities	197	15.8
Laterior walls	165	13.2
Foundations	164	13.1





U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



Release - Immediate

WASHINGTON, D. C

March 29, 1934

FARM HOUSING SURVEY
(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the : country are being covered by the investigators.

AGRICATION, CE AS

Preliminary Report for Izard County, Arkansas (Subject to later revision)

Reports on 2175 farm houses in Izard County, Arkansas, have now been tabulated. The survey shows 263 log houses, I earth house, 1482 unpainted frame houses, 401 painted frame houses and the remainder brick, stone, concrete, or stucco houses. In average of 4 rooms per house is shown. There were 2377 farms in this county in 1929 and the farm population was 19334. Some of the most significant facts shown by the preliminary totals are as follows:

Condition of Houses

Of the 2175 farm houses surveyed, replacements, renewals, cr new installations and repairs were needed as follows:

	Complete replacement,	Repairs or
	renewals, or new	alterations
	installation needed	needed
Screens	1109	451
Paint, exterior	952	260
Foundations	907	450
Roofs	422	667
Doors and windows	404	776
Interior walls	402	908
Chimneys	387	522
Walls, exterior	329	911
Floors	318	850

Need for Additional Space Space requirements were as follows:.

	Have now	Addi- room: neede		in whi	nt of farm ch addition are needed	
Storage space for fresh		,	7.000		450 0	
fruits and vegetables Bedrooms		rooms	1023	rooms	47.0 17.4	*
Front or side porches	1789	rooms	221	rooms	10.2	
Living rooms	572		191		8.8	
Dining rocms	601		121		5.6	
Bathrooms	14		101		4.6	

- 2 -Water Supply and Sewage Dispesal

	Have	New installation
	now	needed
Water carried by hand	1221	
Hand pump in dwelling	4	7
Running water	5	4
Unimproved outdoor toilets	549	_
Improved outdoor toilets	41	_
Improved indoor toilets	1	2
Tub or shower baths	4	17
Kitchen sinks with drain	11	50

Light and Heat

	Have now	New installation needed
Gasoline or kerosene lamps	2083	4
Gaslights	3.	1 '
Electric lights	14	-
Fireplaces	1145	11
Stoves .	1897	40
Central heating system	2	

Refrigeration, Laundry, and Cooking Facilities

	Have	New installation
	now	needed
Ice boxes	24	-
Mechanical refrigeration	1	***
Washing machines, power	2 .	***
Washing machines, hand	44	77
Wood or coal stoves	2121	41
Kerosene or gasoline stoves	19	-
Gas or electric stoves	0	0

Landscaping of House

g · · ·	Have	New installation
	now	needed
Lawns established	493	1420
Walks and drives	84	1740
Fences	995	928

In answer to the question: If \$500 were available for you to spend in improving your house, the following items were mentioned, among others:

	Number of	Per cent of total
	farms	form houses
Interior walls, ceilings, floo	ors 672	30.9
Exterior walls	614	28.2
Doors, windows, soreens	612	28.1
Roofs	545	25.1
Foundations	482	22.2
Porchus	427	19.6
Additional rooms	372	17.1
Chimneys	246	11.3
Water systems	223	10.3
The state of the s		



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



Release - Immediate

WASHINGTON, D. C

April 4, 1934

FARM HOWSING SURVEY (A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to: provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the: country are being covered by the investigators.



Preliminary Report for Adams County, Indiana (Subject to later revision)

Reports on 2180 farm houses surveyed in Adams County, Indiana, have now been tabulated. There are 1360 of the farm houses occupied by the owners and 320 occupied by non-owners. The survey shows 21 log houses, 132, unpainted frame houses, 1732 painted frame houses, 135 stucco houses, 135 brick houses, and the remainder stone or concrete. In average of eight rooms per house is shown. There were 2140 farms in this county in 1929 and the farm population was 10473. Some of the most significant facts shown by the survey are as follows:

Condition of Houses

Of the 2180 farm houses surveyed, complete replacement, renewals, or new installations and repairs were needed as follows:

	Complete replacement,	Repairs or
	renewals, or new	alterations
	installation needed	needed
Paint, exterior	930	280
Screens	408	597
Insulation	330	143
Roofs	245	353
Foundations	221	446

Need for Additional Space Space requirements were as follows:

	Have now	Additional rooms needed
Storage space for fresh fruits and vegetables Bathrooms Bedrooms	1625 319 8541 r o <i>o</i> ms	115 67 s 36 rcoms
Basements	1363	42.

Water Supply and Sewage Disposal

	Have	New installation
	now	needed
Water carried by hand	855	
Hand pump in dwelling	948	227
Running water, cold	377	19
Running water, hot	119	1
Unimproved outdoor toilets	1637	
Improved outdoor toilets	381	4
Improved indoor toilets	163	111
Tub or shower baths	289	104
Kitchen sinks with drain	1135	56

Light and Heat

	Have now	New installation needed
Kerosene or gasoline lamps	1374	1
Gas Lights	27	2
Electric lights, home plant	148	-
Lectric lights, power line	628	5
Pireplaces.	7	_
Stoves	1296	50
Central heating system	909	32 (

Refrigeration, Laundry, and Cooking Facilities

	Have	New installation
	now	needed
Ice boxes	91	6
Mechanical refrigeration	29	18 .
Power washing machines	994	38
Hand washing machines	867	22
Wood or coal cook stoves	1926	44
Kerosene or gasoline stoves	1605	87
Gas stoves	71.	. 1
Electric stoves .	10	11

Landscaping of House

	Have	New installation
	now	needed
Lawns established	2133	35
Walks and drives	1719	604
Fences	1744	585


In answer to the question: If \$500, \$250, \$100 were available for you to spend in improving your home, the following items were mentioned:

Relative Importance of Repairs and Improvements Wanted

	\$500	\$250	\$100
House repairs and improvements:			
Foundation	221	138	83
Exterior walls	616	460	435
Roof	281	223	178
Chimneys	91	62	43
Doors, windows, screens	298	179	151
Porches	206	129	85
Interior walls, ceilings, floors	390	254	217
Additional room	303	129	72
Water system	493	287	150
Sanitary facilities	100	28	11
Lighting system	221	120	126
Heating system	282	131	42
Bathroom equipment	455	303	86
Laundry facilities	108	82	93
Cooking facilities	61	40	65
Landscaping	118	71	44
Electricity:		0	
Home plant	16	6	6
Power line	2 66	125	61
Built-in equipment	73	43	54
Furnishings	307	240	369

New Construction and Financing

Is construction of new house contemplated		
within next 3 years?		
Number of entries	8	
If so, number of rooms	20	
Number of entries	0	
Estimated expenditure	V2224800	
Number of entries	J.	
Give value of repairs or improvements made		
on the present house during the last 3 years	:	
Less than \$100		
Number of entries	1,140	
\$100 to \$499	·	
Number of entries	367	
\$500 and over		
Number of entries	58	
Expenditure for repairs or improvements		
contemplated within next 12 months	\$24,442	
Number of entries	213	
Is money available from local credit sources		
to finance house construction, repairs, or		
improvements?		
Number of entries	206	
Would you be interested in borrowing money to		
finance construction, repairs, or improve-		
ments provided interest rate is satisfactory		
and repayments can be distributed over a per		
of 10 years?		
Yes		
Number of entries	128	
No		
Number of entries	247	
How much would you desire to borrow?	\$31,275	
Number of entries	72	





U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



Release - Immediate

WASHINGTON, D. C

April H, 1934.

FARM HOUSING SURVEY
(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the : country are being covered by the investigators.

Preliminary Report for Pulaski County, Indiana

(Subject to later revision)

Reports on 1738 farm houses surveyed in Fulaski County, Indiana, have now been tabulated. There are 7 log houses, 200 unpainted frame houses, 1474 painted frame houses, 22 stucco houses, 16 brick houses, 5 stone houses, and 14 concrete houses. The survey shows 342 houses which have one story and 1396 houses which have more than one story. An average number of seven rooms per house is shown. There were 1499 farms in the county in 1929 and the farm population was 7104. Some of the most significant figures shown by the survey are as follows:

Condition of Houses

Of the 1738 farm houses surveyed, replacements, renewals, or new installations and repairs were needed as follows:

	Complete replacement, renewals, or new installation needed	Repairs or alterations needed
Paint, exterior	. 713	258
Screens	. 494	401
Insulation	324	50
Foundations	212	301
Roofs	207	3 52
Interior walls and ceilings	154	593

Need for Additional Space Space requirements were as follows:

		Have now	Addit: rocms neede			in who	ent of ich add are ne	lition	
Bedrooms		5542	rooms	236	rooms		10.0		
Dining rooms		1078		100			5.8		
Basements		ó04		167			9.6		
"Storage space	for fresh			· . 🖵			•		
fruits and ve	egetables	740		151			8.7		

Water Supply and Sewage Disposal

	Have	New installation	
	now	needed	
Water carried by hand	1163		
Hand pump in dwelling	510	280	
Running water, cold	189	281	
Running water, hot	107	265	
Unimproved outdoor toilets	1604		
Improved outdoor toilets	35	20	
Improved indoor toilets	128	432	
Tub or shower baths	216	720	
Kitchen sinks with drain	734	557	

Light and Heat.

	Have now	New installation needed
Kerosene and gasoline lamps	1500	23
Gas lights Electricity, home plant	56 90	7
Electricity, power line	141	
Fireplaces Stoves	23 1407	44 31
Central heating system	421	180

Refrigeration, Laundry, and Cooking Facilities

	Have	New installation	
	_ now .	needed	
Ice boxes	210	13	
Mechanical refrigeration	31	96-	
Washing machines, power	504	316	
Washing machines, hand	716	37	
Wood or coal cook stoves	1655 · -	32	
Kerosene or gas stoves	869.	39	
Gas stoves	41	2	
Electric stoves	- 28	13	

Landscaping of House

	Have	New installation	•
	now	needed	
Lawns established	1201	447	
Walks and drives	565	978	
Fences	1040	601	

In answer to the question: If \$500, \$250, or \$100 were available for you to spend in improving your home, the following items were mentioned:

Relative Importance of Repairs	and Impro	vements nant	ted
•	\$500	\$250	\$100
House repairs and improvements: Foundation Exterior walls Roof Chimneys Doors, windows, screens Porches Interior walls, ceilings, floors Additional room Water system Sanitary facilities Lighting system Heating system Bathroom equipment Laundry facilities Cooking facilities Landscaping Electricity, home plant Electricity, power line Built-in equipment Furnishings	235 489 299 103 290 292 557 391 602 236 181 198 525 276 137 79 34 363 89 390	177 379 254 69 193 184 402 226 328 83 71 76 238 223 117 33 9 255 39	122 267 202 35 99 100 267 121 154 24 34 29 99 187 65 22 3 199 23 301

> 11 11

Questions regarding new construction and availability of local credit sources to finance construction contained on the questionnaire were answered by the occupants as follows:

New Construction and Financing

Number of persons reporting contemplated construction of new house within next 3 years Number of rooms to be constructed Estimated expenditure Number of entries	58 311 \$84 ,7 00 58
Value of repairs or improvements ande on the present house during the last 3 years: Less than \$100	
Number of entries	1367
\$100 to \$499 Number of entries \$500 and over	. 295
Number of entries	76
Expenditure for repairs or improvements contemplated within next 12 months Number of entries	\$42 , 138 . 50 457
Number of persons reporting that money is available from local credit sources to finance house construction, repairs, or improvements	509
Number of persons interested in borrowing money to finance construction, repairs, or improvements provided interest rate is satisfactory and repayments can be distributed over a period of 10 years Not interested	890 848
Total sum desired Number of entries	\$350,285 890





U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



Release Immediate.

WASHINGTON, D. C

April 9, 1934

FARM HOUSING SURVEY
(A Civil Works Administration Project)

: The Farm Housing Survey is a Civil Works Administration: :project, carried out by the U.S. Department of Agriculture and: :the State Agricultural Extension Services. The object is to :provide the basic information necessary for a program of im-.: :provement for farm homes. About 300 counties throughout the :country are being covered by the investigators. This report :on the State of Kentucky is the first State Summary to be :issued.

PRELICIALRY REPORT FOR THE STATE OF REMINCRY

(Subject to later revision)

Approximately ten percent of the counties in each State except New York and Pennsylvania have been surveyed. Reports on 22,341 farm houses surveyed in Bourbon, Boyle, Calloway, Fayette, Fleming, Hardin, Hickman; Knott, Ohio, Oldham, Shelby, and Simpson Counties, Kentucky have been tabulated. Appropriate weights have been applied to the results of each of the counties surveyed in order that figures may be projected to the State as a whole. There were 237,395 farms owned or operated by white occupants and 9,104 farms owned or operated by non-white occupants in 1929 an and the farm population was 1,176,524. The total value of farm dwellings, as reported in the 1929 Census of Agriculture, was \$163,757,651, covering 224,232 farms reported in Kentucky.

Section A

	FARMENG GROUP	LIOUNTAIN GROUP	TOTAL FOR KENTUCKY
Total number of occupants Number of white occupants Number of non-white occupants Number of owners Number of non-owners Total acres in farm Number of entries Average acres per farm Total acres tillable in farm Number of entries Average acres tillable per far	: 97,000 : 71,000 : 16,319,000 : 159,600 : 102 : 12,306,000 : 159,600	65,300 65,000 300 37,000 28,300 25,496,000 4,800 393 21,017,000 64,900 324	233,300 225,000 8,300 134,000 99,300 41,815,000 224,400 186 33,323,000 224,400 148

. man almost as a second control of the control of

	FARLING GROUP	MOUNTAIN GROUP	TOTAL FOR KENTUCK
Kind of house		•	
Log	11,200	: 17,400	28,600
Earth \ :	50	60	: 110
Frame		:	:
Unpainted	38,300	29,400	: 67,700
Painted	102,000	18,300	120,300
Stucco Brick	670	- :	670
Stone	6,390	60	6,950
Concrete	1,110	490	1,600
Age of house	640	60	700
Under 10 years	17 700	24 200	. 43 000
10 to 24 years	17,700 44,500	24,300 20,600	. 42,000 65,100
25 to 49 years	52,700	14,300	67,000
50 and over years	50,000	5,000	55,000
One story house	73,000	58,000	131,000
More than 1 story	97.000	5,000	102,000
Total number of rooms	904,000	235,000	: 1,139,000
Number of entries	168,000	67,000	235,000
verage number of rooms per house	- 5 . 4	3.5	4.8
Total number of rooms not in use at		:	:
any time of year	39,000	: 6,000	: 45,000
Number of entries	18,500	2,700	: 21,200
Average number of rooms per house			
not in use	2.1	2.2	2.1
Tetal number of regular occupants Number of entries	743,000	337,000	: 1,080,000
Average number of occupants per house	168,000	60,000	: 228,000
Average number of occupants per nouse		5,6	4.7
Transe marner or begabance ber Local	.8	1.4	

C. COMDITION OF HOUSE

FAREING GROUF (Number of schedules)						
	Pres	Present Condition			Replacement or new installa-	
	Good	Fair	Poor	· alterations needed	tion needed	
Foundation Walls, exterior Roof Chimneys Doors and windows Screens Paint, exterior Interior walls and ceiling Floors Stairs Insulation	94,000 99,500 84,000 126,000 88,000 65,100 39,000 2,000 100,400 73,600 43,700	45,500 : 46,000 : 55,000 : 36,600 : 40,100 : 57,000 : 46,100 : 13,200 : 46,000 : 13,200 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,000 : 46,	38,000 : 14,000 : 24,700 : 37,400 : 49,000 : 29,000 : 20,500 : 7,800 : 7,800 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,000 : 38,00	38,800 41,600 21,200 43,500 31,200 28,200 47,900 31,400 8,700	: 27,600 : 14,100 : 28,700 : 9,800 : 19,800 : 54,000 : 77,400 : 20,200 : 18,700 : 6,900 : 32,200	

C. CONDITION OF HOUSE (Continued)

	MOUNTAIN GROUP (Number of schedules)							
,	:	Prese	nt Conditi		: : Repairs or	: : Replacement or		
	:-	Good	Fair	Poor	: alterations : needed :	: new installa- : tion needed		
Foundation Walls, exterior Roof Chimneys Doors and windows Screens Paint, exterior Interior walls and ceiling Floors Stairs Insulation	:	25,000 : 28,200 : 24,200 : 36,000 : 20,000 : 4,000 : 4,000 : 18,200 : 21,100 : 5,400 : 3,800 :	17,200 19,000 14,000 11,300 19,000 5,400 3,900 23,100 19,400 1,300 14,000	18,100 27,100 12,500 26,300 10,100 11,500 24,000 22,500 1,700	17,100 16,000 10,800 19,500 8,200 4,500 20,800 16,000 1,100	13,600 10,800 19,700 9,000 19,800 48,700 36,800 16,500 13,600 1,400 28,400		

<u> </u>		TOTAL F	OR KENTUCKY (Numi	ber of schedules)
	: Present Cond	lition	: : : Repairs or	: Replacement or
	Good Fair	Poor	: alterations : needed	: new installa- : tion needed
Foundation Walls, exterior Roof Chimneys Doors and windows Screens Paint, exterior Interior walls and ceiling Floors Stairs Insulation	110,000 : 61,000 127,700 : 64,500 108,200 : 60,000 162,000 : 37,500 103,000 : 74,000 71,500 : 42,000 43,000 : 44,000 100,200 : 80,100 121,500 : 65,500 79,000 : 14,500 47,500 : 37,000	1,100 65,100 26,500 51,000 47,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500 60,500	55,900 57,600 32,000 63,000 39,400 32,700 68,700 47,400 9,800	41,200 24,900 48,400 18,800 39,600 102,700 114,200 36,700 32,300 8,300 60,600

D. SHACE REQUIREMENTS

	FAR HAG GROUP		MOUNT	LIN GROUP	TOTAL FOR KENTUCKY	
	:Have	: .dditional :	Have	: Additional	Have	Additional
	:now	: rooms needed:	now	: rooms needed:	now :	rooms needed
	:	:		:		
Bedrooms	: 427,000	: 25,600 :	132,000	: 40,200	: 559,000 :	65,800
Number of entries	: 165,000		47,000		212,000 :	42,000
Living room	: 111,000		7,000		: 118,000 :	
Dining roca	99,000		27,000 :	: 21,000 :	126,000 :	
Kitchen	: 165,000		60,000		226,000 :	
Work room	34,000	16,000	3,500		37,500	
Wash room for	:	: :	·	:	:	
farm help	: 10,600	: 11,500 :	900	9,600	11,500 :	21,100
Bathrooms	: 14,000		700		14,700 :	
Halls	62,000	6,000	4,000	3,000	66,000 :	
Basement	: 30,000		4,000		34,000 :	,
Closets	: 309,000	: 85,000 :	47,000		356,000 :	
Fumber of entries	: 123,000	: 47,000	31,000		154,000 :	
Front or side porch	: 127,000		54,000		181,000 :	
Back porch	: 108,200		22,000		130,200 :	•
Storage space for fresh		: :	: .			
fruits and vegetables	: 74 , 700	49,500	8 , 250 .	40 , 850	82,950	90,350

Kentucky Summary	E. WATER	R SUPPLY AND	SEWAGE DISH	POSAL		Page 4
		MING GROUP .			CUPTAIN GROU.	
		Repairs or	New insta-	Have	:Repairs or	
;		alterations	:llation;	now	:alterations	:llation
		needed	needed :	•	:needed	needed
Source of water:		email (iii)		•	:	:
mell, drilled or driven:		620	1,440	5,700	460	: 1,380
Well, dug or bored	: 73,700 :		3,100	: 35,600	: 5,150	: 6,410
Spring :	36,400	1,880	390		: 650	: 1,470
Cistern :	60,150:		5,230 :	: :150	: -	• ••
Stream	8,780:	' 	- :	: 770	: -	: -
Water supply for house:		the first transfer of	· j	•	:	:
Carried :	105 105 000	1.7			:	:
Distance (total feet):	25,186,000:	-	: - :	:5,637,000	: -	: -
Number carrying water:	- 145,400 :		:	: 63,600	: -	:
Hand pump in dwelling	9,800:	520	: 11,900		: 30	: 740
Piped, cold	12,660:	410	29,200		: 30	1,500
Piped, hot Sanitary facilities:	9,000	290	18,400	: 100	: -	: 200
Outdoor toilet					:	:
			£ ;	•	:	
(privy): Improved	7,820	200	30,500	1.960	300	: 55 000
Unimproved	127,000		30,300	56,000	: 300	55,000
Indoor:	127,000		_	30,000	: -	: -
Chemical	230-	4	1,040		:	30
Flush	9,400		24,030	100	: -	770
Bathroom fixtures:	9,400	230	24,030	100	: -	: 770
Tub	11,225	260	31,600	275	:	1,700
Shower	1,130:		12,600	30	: <u> </u>	200
Lavatory	10,650		27,000	150	-	800
Kitchen sink with drain	19,800		41,000	900	180	20,200
Disposal of sewage:	10,000	, 20	-11,000		: 100	. 20,200
Septic tank	2,900	220	25,900		:	2,200
Cesspool	4,030		5,320	90		60
Stream	2,140		1,200	770	-	2,100
Surface	- 9 - 10 -					

E. LATER SUPPLY AND SEMAGE DISPOSEL (continued)

	PCTAL FOR KENTUCKY					
	Have now	Repairs or alterations, needed	Few installation needed			
Source of water: Well, drilled or driven Well dug or bored Spring Cistern Stream Water supply for house: Carried	29,200 112,300 53,450 60,300 9,550	1,080 12,000 2,530 4,900	2,820 9,570 1,860 5,230			
Distance (total feet) Number carrying water Hand pump in dwelling Piped, cold Piped, hot Sanitary facilities: Outdoor toilet (privy):	30,353,000 209,000 10,100 13,090 9,100	550 440 290	12,640 30,700 18,600			
Improved Unimproved Indoor:	9,780 183,000	500	85,500 -			
Chemical Flush Bathroom fixtures:	230 9,500	4 . 230 .	1,070 24,800			
Tub Shower Lavatory Kitchen sink with drain	11,500 1,160 10,800 20,700	260 190 530	33,300 12,800 27,800 61,200			
Disposal of sewage: Septic tank Cesspool Stream Surface	2,900 4,120 2,910 13,410	220 20 25	28,100 5,380 3,300			

Have		1									
Inow		FAI	RATING GRO	UP		MOUNTAIN GROUP			TOTAL FOR KENTUCKY		
Lighting: Kerosene or gasoline lamps 143,400: - 2,880 59,500: - 4,390 202,900: - 7,27 Acetylene 2,100: 360 100 60: - 30 2,160: 360 13 Piped gas 1,140: 25 950 1,000: 180 370: 2,140: 205: 1,32 Electric: Home plant 4,520: 480 1,470: 520: 60: 310: 5,040: 540: 1,78 Power line 13,170: 65 30,400: 1,990: 30: 6,300: 15,160: 95: 36,70 Miles 586,600: 902,000: 888,600: - Number of entries:159,400: 52,100: 211,500: Heating: Fireplaces 91,000: 4,300: 1,670: 57,100: 9,600: 3,560: 148,100: 13,900: 5,23 Stoves 110,000: 2,260: 3,600: 2,200: 90: 150: 112,200: 2,350: 3,75 Circulating heater 9,400: 60: 5,200: 340: 9,740: 60: 5,20 Pipeless furnace 1,320: 140: 1,030: 30: 1,350: 140: 1,030 Fiped warm air, steam, or water		:now :	or alter-	:stalla-:	now :	or alter-	:stalla-	:now :	or alter-	:stalla	
Kerosene or gasoline lamps :143,400: - :2,880: 59,500: - :4,390: 202,900: - :7,27 Acetylene :2,100: 360: 100: 60: - :30: 2,160: 360: 13 Piped gas :1,140: 25: 950: 1,000: 180: 370: 2,140: 205: 1,32 Electric: .						• • • • • • • • • • • • • • • • • • • •		-		:t10n <u>:nee</u> ded	
Kerosene or gasoline lamps 143,400: - 2,880: 59,500: - 4,390: 202,900: - 7,27 Acetylene 2,100: 360: 100: 60: - 30: 2,160: 360: 13 Piped gas 1,140: 25: 950: 1,000: 180: 370: 2,140: 205: 1,32 Electric: Home plant 4,520: 480: 1,470: 520: 60: 310: 5,040: 540: 1,78 Prwer line 13,170: 65: 30,400: 1,990: 30: 6,300: 15,160: 95: 36,70 Miles 586,600: - - -902,000: - - 888,600: - Number of entries: 159,400: - - 52,100: - - 211,500: - Heating: Fireplaces 91,000: 4,300: 1,670: 57,100: 9,600: 3,560: 148,100: 13,900: 5,23 Stoves 110,000: 2,260: 3,600: 2,200: 90: 150: 112,200: 2,350: 3,75	Lighting:	: :		•17			:	: :		:	
Acetylene		: :		: ' :	:		:	: :		: ,	
Acetylene	gasoline lamps	:143,400:	-	: 2.880 :	.59,500:	_	: 4,390	:202,900:	_	:7,270	
Electric: Home plant	Acetylene ·	: 2.100:	360						360		
Home plant : 4,520: 480 : 1,470 : 520: 60 : 310 : 5,040: 540 : 1,78 Power line : 13,170: 65 : 30,400 : 1,990: 30 : 6,300 : 15,160: 95 : 36,70 Miles : 586,600: - : - : 902,000: - : - : 888,600: - : Number of entries: 159,400: - : - : 52,100: - : - : 211,500: - : Heating: Fireplaces : 91,000: 4,300 : 1,670 : 57,100: 9,600 : 3,560 : 148,100: 13,900 : 5,23 Stoves : 110,000: 2,260 : 3,600 : 2,200: 90 : 150 : 112,200: 2,350 : 3,75 Girculating heater : 9,400: 60 : 5,200 : 340: - : - : 9,740: 60 : 5,20 Pipeless furnace : 1,320: 140 : 1,030 : 30: - : - : 1,350: 140 : 1,03 Fiped warm air, : : : : : : : : : : : : : : : : : : :	Piped gas	: 1,140:	25.	950	1,000:	180	: 370	: 2,140:	205	:1,320	
Prover line : 13,170: 65 :30,400 : 1,990: 30 : 6,300 : 15,160: 95 :36,70 Miles : 586,600: - : - :902,000: - : - :888,600: - : Number of entries:159,400: - : - :52,100: - : - :211,500: - : Heating: : : : : : : : : : : : : : : : : : :	Electric:	: :	•	:			:	:		:	
Prover line : 13,170: 65 :30,400 : 1,990: 30 : 6,300 : 15,160: 95 :36,70 Miles : 586,600: - : - :902,000: - : - :888,600: - : Number of entries:159,400: - : - :52,100: - : - :211,500: - : Heating: : : : : : : : : : : : : : : : : : :		: 4,520:	480	: 1,470 :	520:	.60	: 310	: 5,040:	540	:1,780	
Miles	Prwer line					30	: 6,300	: 15,160:	95	:36,700	
Heating: Fireplaces : 91,000: 4,300 : 1,670 : 57,100: 9,600 : 3,560 : 148,100: 13,900 : 5,23 Stoves : 110,000: 2,260 : 3,600 : 2,200: 90 : 150 : 112,200: 2,350 : 3,75 Circulating heater : 9,400: 60 : 5,200 : 340: : 9,740: 60 : 5,20 Pipeless furnace : 1,320: 140 : 1,030 : 30: : 1,350: 140 : 1,030 Piped warm air, : : : : : : : : : : : : : : : : : : :		:586.600:	_	:	:202,000:	_				: -	
Heating: Fireplaces : 91,000: 4,300 : 1,670 : 57,100: 9,600 : 3,560 : 148,100: 13,900 : 5,23 Stoves : 110,000: 2,260 : 3,600 : 2,200: 90 : 150 : 112,200: 2,350 : 3,75 Circulating heater : 9,400: 60 : 5,200 : 340: : 9,740: 60 : 5,20 Pipeless furnace : 1,320: 140 : 1,030 : 30: : 1,350: 140 : 1,030 Piped warm air, : : : : : : : : : : : : : : : : : : :	Number of entrie	s:159,400:	_	: - :	: 52,100:	_	: -	:211,500:	_	: -	
Stoves :110,000: 2,260: 3,600: 2,200: 90: 150:112,200: 2,350: 3,75 Circulating heater : 9,400: 60: 5,200: 340: - : - : 9,740: 60: 5,20 Pipeless furnace : 1,320: 140: 1,030: 30: - : - : 1,350: 140: 1,03 Piped warm air, : : : : : : : : : : : : : : : : : : :			-	:	:		:	: :		:	
Stoves :110,000: 2,260 : 3,600 : 2,200: 90 : 150 :112,200: 2,350 :3,75 Circulating heater :9,400: 60 : 5,200 : 340: - : - : 9,740: 60 : 5,20 Pipeless furnace :1,320: 140 : 1,030 : 30: - : - : 1,350: 140 : 1,03 Piped warm air, : : : : : : : : : : : : : : : : : : :	Fireplaces	: 91,000:	4.300	: 1.670 :	57.100:	9,600	: 3,560	:148,100:	13,900	:5,230	
Circulating heater : 9,400: 60 : 5,200 : 340: - : - : 9,740: 60 : 5,200 Pipeless furnace : 1,320: 140 : 1,030 : 30: - : - : 1,350: 140 : 1,030 Piped warm air, : : : : : : : : : : : : : : : : : : :	Stoves						: 150	:112,200:	2,350	:3,750	
Pipeless furnace : 1,320: 140 : 1,030 : 30: - : - : 1,350: 140 : 1,03 Piped warm air, : : : : : : : : : : : : : : : : : : :	Circulating heater	: 9,400:		: 5,200			: -				
steam, or water : : : : : : : : : : : : : : : : : : :		: 1,320:	140	: 1,030	30:		: -	: 1,350:			
		: :		:	:		:	: :		:	
furnace : 4,835: 130 : 4,350 ; -: - : 30 : 4,835: 180 .4,38	steam, or water	:		:	:		:	:	7.00	:	
		: 4,835:	130	: 4,350			30_	: 4,835:	180	<u>.4,380</u>	

G. REFRIGHRATION, LAUNDRY, AND COOKING FACILITIES (Number of farm houses)

:									
1	F/A	NAING GROU	P	hi	MOUNTAIN GROUP			L FOR KEN	TUCKY
	now	or alter- ations	New in- stalla- tion needed	now	Repairs or alter- ations needed	:New in- :stalla- :tion :needed	now	Repairs or alter- ations needed	:New in- :stalla- :tion :needed
Refrigeration: Ice Niechanical Laundry: Where done:	50,900 5,300		29,300 8,800	1,600 200		6,700 800	52,500 5,500		36,000 9,600
Cut-of-doors In kitchen In basement In special room		100	160 5,940	46,500 19,600 310	280	490	119,000 151,100 1,950		650 5,970
on same level : with kitchen	7,700	230	7,300	1,200	60	6,630	8,900	290	13,930
Equipment: Fixed tubs Power machine Hand machine Cooking facilities: Wood or coal	4,580 11,400 92,600	240	1,370 20,000 2,800	30 2,700 800	250	90 8,800 400	4,610 14,100 93,400	490	1,460 28,800 3,200
		- 1		59,300 1,470 30		14,500 : 300	2,6,300 3,120 940	250	: 21,000 : 2,600 : 1,900
	34,500	1,530	3,800	120	: 	: .:	34,620	1,530	3,800

H. LANDSCAPING OF HOUSE (Number of Farm Houses)

**************************************	FA	FARMING GROUF			OUNTALN G	ROUP	TOTA	TOTAL FOR KENTUCKY		
				now	or alterations	:New in- :stalla- tions :needed	now:	:or alter	:New in:stalla- :tions	
Yard: Surface drainage:	149,500	•	•	: -:	-	22,800	:	:	34,800	
away from house Lawn established Plantings	125,400	25,000	:30,000					: 34,400	79,000	
Walks and drives	: 68,100	25,200	75,300	: 9,900:		:51,800	: 78,000	31,000 35,400 65,100	82,500 127,100 65,600	

I. RELATIVE EXPORTANCE OF REPAIRS AND EMPROVEMENTS MANTED (Number of Farm Houses)

Were the following specified amounts available for improving your home, what would you spend them f

				· · · · · · · · · · · · · · · · · · ·						
•	FLR	MING GROU	P	MOU	MTAIN GRO	UP	TOTAL	FOR KENT	UCKY	
	\$500	\$250	\$100	\$500	\$250	\$100	\$500	\$250	\$100	
House repairs and	y					•		•	•	
improvements:	: :				•	:	:	:	:	
Foundation :	: 14,100 :	: 13,200 :	: 12,000	: 16,200 :	: 14,500	: 12,400	30,300	: 27,700	: 24,400	
Exterior walls :	47,000	: 51,600 :	45,400	24,800	21,000	14,900	71,800	72,600	. 60,300	
Roof.	32,100	36,000	86,600	29,500	23,500	23,500	61,600		110,100	
Chimneys	9,000	8,000	6,600	9,500	8,200	4,000	18,500	16,200	10,600	
Doors, windows,:	: 30,600 :	31,000	23,800	31.200	25,800	15,900	61,800	57,800	39,700	
screens	: ;		ĺ		,					
Porches	28,200 :	23,100	16,800	: 17,000	13,200	4,900	45,200	36,300	21,700	
Interior walls,					:	•	,		,	
ceilings,				•	•	•	•			
floors	47.300	46,600	38,000	36,100	31,200	17,800	83,400	77.800	55.800	
Additional					, , ,					
room	29,600	22,100	12,200	29.800	21,800	9.300	59,400	43,900	21,500	
Water system	: 300 ر 31	19,800		23,100	11,200	3.800	54,200	31,000	12,800	
Sanitary facili-		_,,	,	:			,			
ties	9,000	5,700	2,500	11.300	0,100	1,600	20,300	11,800	4,100	
Lighting system	8,700	4,400	2,000					7,400	2,600	
Heating system	5,500	2,500	1,000					3,400	1,200	
Bathroom equipment:		-8,500		•			24.050	10.500	2,800	
Laundry facilities:						1.700	7 1 600	7.600	3,400	
Cooking facilities:			1.800	. ,	12,000	7,200	21,200	14,600	9,000	
Landscaping	14.800		6.300	.19,500	12,200		34,300	21,700	11,850	
Electricity:		. , 5					,	,	11,000	
Home plant	1.700	600	250	600 :	100	150	2,300	700	400	
Power line	12,300		1.900	2,450			14.750		2,300	
								6,000	2,200	
Furnishings				. ,					23,400	
Built-in-equipment: Furnishings		3,800	1,600		2,200	600	16,400 56,200	6,000 33,700	2,	

J. NEW CONSTRUCTION AND FINANCING

	FARMING GROUP	LOUNTAIN GROUP	TOTAL FOR KENTUCKY
Is construction of new house contemplated within next 3 years?	: :		
Yes (Number of houses) No (Number of houses)	5,000	12,300	17,300
If so, Number of rooms Number of entries	17,300	51,200	68,500 15,700
Estimated expenditure Number of entries	4,100 :\$3,231,000 : 4,100	11,600 : \$5,354,000 : 11,600	\$8,585,000 15,700
Value of repairs and improvements made on present house during the past 3 yrs.	: :		-
Under \$100 (Number of farm houses) \$100 to \$499 (Number of farm houses) \$500 and over (Number of farm houses)	95,000 29,000 5,200	29,400 8,500 2,000	124,400 37,500 7,200
Expenditure for repairs or improvements contemplated within next 12 months	::		
Total value Number of entries	\$3,677,000 34,000	\$2,798,000 18,000	\$6,475,000 52,000
Is money available from local credit sources to finance house construction, repairs or improvements?	: :		
Yes (Number of farm houses)	41,800	4,900	45,700
Would you be interested in borrowing money to finance construction, repairs, or improvements,	: :		
provided interest rate is satisfactory and payments can be distributed over a period of 10 yrs?	: ઢક		
Yes (Number of farm houses) No (Number of farm houses)	21,800	30,300 35,800	52,100 175,100
How much would you desire to borrow? Number of entries (Farm houses)	\$8,815,000 17,500	\$8,600,000 26, 7 00	\$17,415,000 44,200

These are all preliminary data, subject to revision before the data are published.

* -

INFORMATION FOR THE PRESS



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



Release - Immediate

WASHINGTON, D. C

April 10, 1934

DEPARTMENT OF AGR

FARM HOUSING SURVEY (A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the country are being covered by the investigators.

Freliminary Report for Winona County, Minnesota (Subject to later revision)

Reports on 1927 farm houses surveyed in Winona County, Minnesota, have now been tabulated. The survey shows that 1241 of the farm houses are occupied by the owners and 686 of the houses are occupied by non-owners. There are 9 log houses, 62 unpainted frame houses, 1642 painted frame houses, 33 stucco houses, 155 brick houses, 20 stone houses and 6 concrete houses. An average of 7 rooms per house is shown. There were 2158 farm houses in this county in 1929 and the farm population was 10409. Some of the most significant figures shown by the survey are as follows:

Condition of Houses

Of the 1927 farm houses surveyed, complete replacements, renewals, or new installations and repairs were needed as follows:

	Complete replacement,	Repairs or
	renewals or new	alterations
	installation needed	needed
Screens	469	240
Roofs	3 99	168
Paint, exterior	389	524
Insulation	330	167
Floors	163	254
Interior walls and ceilings	153	464
Foundations	1.49	374

Need for Additional Space Space requirements were as follows:

	Have now	Additional rooms needed
Bedrooms		rooms 111 rooms
Bathrooms	320	107
Front or side porches	1522	82
Back porches	1160	81
Dining rooms	1316	24

Water Supply and Sewage Disposal

	Have	New	Per cent of farm ho	uses
•	now	installation	in which new instal	lation
		needed	is needed	
Water carried by hand	1007	t-m	-	
Hand pump in dwelling	663	8	•4	
Running water, cold	424	. 56	2.9	
Running water, hot	172	15	.8	
improved outdoor toilets			-	
Improved outdoor toilets	128	5	•3	
Improved indoor toilets	226	100	5.2	
Tub or shower baths	254	115	6.0	
Kitchen sinks with drain	798	1130	58.6	2323-34
				

Light and Heat

	Have now	New installation needed
Kerosene or gasoline lamps	1364	4
Gas lights	68	2
Electricity, home plant	240	36
Electricity, power line	319	43
Central heating system	804	41

Refrigeration, Laundry, and Cooking Facilities

è	Have now	New installation needed	Per cent of farm houses in which new installa- tion is needed
Ice boxes	171	5	•3
Mechanical refrigeration	82	7	•4
Washing machines, power	1084	124	6.4
Washing machines, hand	269	48	2.5
Wood or coal cook stoves	1879	25	1.3
Kerosene or gasoline stove	s 770	45	2.3
Gas stoves	43	3	.2
Electric stoves	21	: 1	.1

Landscaping of House

	Have . now	New installation needed
Lawns established	1744	183
Walks and drives	891	97 7
Fences	720	264

Relative Importance of Repairs and Improvements Wanted


In answer to the question. If \$500, \$250, or \$100 were available for you to spend in improving your home, the following items were mentioned:

*	\$500	\$250	\$100
House repairs and improvements: Foundation Exterior walls Roof Chimneys Doors, windows, screens Porches Interior walls, ceilings, floors Additional room Water system Sanitary facilities Lighting system Heating system Bathroom equipment Laundry facilities Cooking facilities Landscaping	181 534 315 130 217 299 610 188 454 158 107 183 333 83 36 35	143 483 292 105 189 223 530 127 311 104 47 100 145 62 23 21	102 351 222 76 108 117 364 64 152 36 22 44 48 38 17
Electricity: Home plant Power line Built-in equipment Furnishings	56 65 42 175	19 18 26 129	6 5 15 134

New Construction and Financing

Number of persons reporting contemplated	
construction of new house within next 3 years	13
Number of rooms to be constructed	63
Number of entries	12
Estimated expenditure Number of entries	\$20,500 10
Number of Citation	20
Value of repairs or improvements made on	1 056
the present house during the last 3 years Less than \$100	1,056 309
\$100 to \$499	65
\$500 and over	
Expenditure for repairs or improvements con-	
templated within next 12 months	\$29,811
Number of entries	352
Number of persons reporting that money is avail-	
able from local credit sources to finance house	
construction, repairs, or improvements	215
Number of persons interested in borrowing money to	
finance construction, repairs, or improvements	
provided interest rate is satisfactory and re-	
payments can be distributed over a period of 10 years	288
y cars	200
Not interested	1,639
Total sum desired	\$91,675
Number of entries	204

These are all preliminary data, subject to revision before the data are published.





U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C

Release - Immediate

April 27, 1934

FARM HOUSING SURVEY

(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the : country are being covered by the investigators. This report : on the State of Florida is the second State Summary to be :issued.



PRELIDIANARY REPORT FOR THE STATE OF FLORIDA

(Subject to later revision)

Approximately 10 per cent of the counties in each State, except New York and Pennsylvania have been surveyed. Of the 67 counties in Florida 8 were surveyed. Reports on 13071 farm houses in Alachua, Dade, Escombia, Gadsdon, Leon, Hillsboro, Orange, and Polk counties have been tabulated. There were 58,966 farms in Florida in 1929 and the farm population was 278,981. The total value of \$47,557,616 covering 47,479 farm houses in Florida was reported in the 1930 Census of Agriculture Appropriate weights have been applied to the data of each county surveyed in order that the results may be projected over the State as a whole.

Section A

	WHI	re	NON-WHITE		TOTAL FOR
	Owner	Non-owner	Owner	Non-owner	STATE
Total number of farm houses	31,000	15,300	6,200	4,700	57,200
Total acres in farm	2,416,000	2,751,500	189,500	263,000	5,620,000
Number of entries	31,000	14,100	6,200	4,100	55,400
Average acres per farm	78	195	31	64	101
Total acres tillable in farm	1,170,000	964,000	106,000	129,000	2,369,000
Number of entries	31,000	14,050	6,200	4,150	55,400
Average acres tillable per farm	38	69	17	31	43

- 2 -

B. HOUSE - GENERAL INFORMATION

	WHT	TE	NON	-WHTTE	TOTAL FOR STATE	
	Owner	Non-owner	Owner	Non-owner	TOTAL FOR STATE	
Kind of house	mai Agitoria				/	
Log	405	200	40	20	660	
Earth		_	-	-	-	
Frame						
Unpainted	12,100	6,900	4,475	3,400	26,875	
Painted	16,800	7,600	1,615	1,250	27,265	
Stucco	900	350	40	10	1,300	
Brick	200	50	10	-	260	
Stone	100	50	20		170	
Concrete	500	150		2 0	670	
Age of house						
Under 10 years	12,100	4,800	2,200	1,500	20,600	
10 to 24 years	10,200	5,600	2,300	2,100	20,200	
25 to 49 years	7,000	4,000	1,500	1,000	13,500	
50 and over years	1,700	900	200	100	2,900	
One story house	26,200	13,200	5,900	4,400	49,700	
wore than 1 story	4,800	2,100	300	300	7,500	
Total number of rooms	164,700	68,600	27,800	16,300	277,400	
Number of entries	31,100	15,300	6,200	4,600	57,200	
Average number of						
Rooms per house	5.3	4.5	` 4.5	3.5	4.8	
Total number of rooms						
not in use at any time						
of year	2,400	2,400	220	400	5,420	
Number of entries	1,128	1,000	90	190	2,408	
Total number of regular						
occupants	132,000	68,700	29,400	21,300	251,400	
Number of entries	31,000	15,200	6,200	4,700	57,100	
Average number of						
occupants per house	4.3	4.5	4.7 .	4.5	4.4	
Average number of						
occupants per room	0.8	1.0	1.1	1.3	0.9	

C. CONDITION OF HOUSE

	WHITE NON-OWNERS						
	Pres	ent Conditi	on	Repairs or	Replacement or		
	Good	Fair	Poor	alterations needed	new installation needed		
Foundation Walls, exterior Roof Chimneys Doors and windows Screens Paint, exterior Interior walls, and ceiling Floors Stairs Insulation	3,400 4,300 4,400 4,900 4,400 3,000 1,400 1,500 1,700 800 500	3,800 5,100 4,700 3,200 4,200 3,200 2,500 4,100 5,400 650 300	8,100 5,900 6,200 3,900 6,700 4,600 4,300 8,800 8,200 800 600	5,100 5,600 4,700 3,500 6,000 3,600 2,800 5,400 8,000 650 100	4,100 2,100 3,700 3,200 3,300 6,100 7,800 6,100 2,800 400 4,200		


- 3 -

C. CONDITION OF HOUSE (Continued)

	WHITE OWNERS							
	Presen	nt Condition		Repairs or	Replacement or			
	Good	Fair	Poor	alterations needed	new installation needed			
Foundation Walls, exterior Roof Chimneys Doors and windows Screens Paint, exterior Interior walls and ceiling Floors Stairs Insulation	9,700 12,300 11,200 13,600 13,200 9,800 4,700 5,800 6,600 2,600 2,000	7,700 9,900 8,400 6,500 8,400 7,000 6,500 9,600 11,300 1,600	13,600 8,800 11,400 5,700 9,400 7,000 7,300 14,400 13,100 1,100 1,200	9,600 9,000 8,700 5,500 9,600 7,300 5,900 10,900 13,700 1,250	5,500 2,800 6,100 4,600 3,900 8,900 13,800 8,900 4,000 500 7,300			

	NON-WHITE OWNERS (Number of schedules)							
	Pre	sent Condit	ion	Repairs or	Replacement or			
	Good	Fair	Poor	alterations needed	new installation needed			
Foundation Walls, exterior Roof Chimneys Doors and windows Screens Paint, exterior Interior walls and ceiling Floors Stairs Insulation	500 700 800 800 625 200 200 500 400 100	1,000 1,800 1,100 1,300 1,350 400 500 1,300 1,750 200	4,700 3,700 4,300 2,800 4,225 1,900 1,300 3,400 4,050 400 600	2,000 2,600 1,700 1,400 2,400 600 500 2,300 3,000 200 50	3,000 1,900 3,000 2,700 2,600 4,000 3,700 2,800 2,000 300 1,800			

		Ĭ <u>v</u> O	N-WHITE NON	-OWNERS (Number	of schedules)
	Frç	sont Condition	n	Don-ing	
	Good	Fair	Poor	Repairs or alterations needed	Replacement or new installation needed
Foundation Walls, exterior Roof Chimneys Doors and windows Screens Paint, exterior Interior walls and ceiling Floors Stairs Insulation	600 600 700 600 300 200 100 200 225 100	700 1,200 900 600 1,000 500 600 1,525 50	3,400 2,900 3,100 2,100 3,400 1,600 900 2,500 2,950 200	1,300 1,700 1,100 800 1,600 600 450 900 2,300 100 50	2,600 2,000 2,500 2,500 2,500 3,300 3,400 3,200 1,900 200



C. CONDITION OF HOUSE (Concluded)

TOTAL FOR STATE								
	Prese	ent Conditio	on	Repairs or	Replacement or			
	Good	Fair	Poor	alterations needed	new installation needed			
Foundation Walls, exterior Roof Chimneys Doors and windows Screens Paint, exterior Interior walls and ceiling Floors Stairs Insulation	14,200 17,900 17,100 19,900 18,525 13,200 6,400 8,000 8,925 3,800 2,750	13,200 18,000 15,100 11,600 14,950 11,100 10,000 15,600 19,975 2,500 1,450	29,800 21,300 25,000 14,500 23,725 15,100 13,800 29,100 28,300 2,500 2,600	18,000 18,900 16,200 11,200 19,600 12,100 9,650 19,500 27,000 2,200 500	15,200 8,800 15,300 13,000 12,300 22,300 28,700 21,000 10,700 1,400 16,000			

D. SPACE REQUIREMENTS

		WHITE		
		Owner	Non-owne	r
	Have	Additional	Have	Additional
	now	room needed	now	room needed
Bedrooms	85,500	11,400	39,100	7,300
Number of entries	30,700	7,300	15,100	4,400
Living room	22,900	5,400	8,900	4,000
Dining room	21,350	5,400	8,650	3,700
Kitchen	30,100	850	14,600	300
Nork room	3,300	3,150	1,000	1,500
lash room for				
farm help	900	1,000	200	500
Bathrooms	10,400	9,400	3,700	5,100
Malls	9,800	300	4,000	160
Basement	700	150	200	50
Closets	41,050	40,500	14,750	25,100
Number of entries	16,800	17,400	6,400	9,000
ront or side porch	26,800	2,400	13,200	1,400
Back porch	21,900	4,700	10,000	2,800
Storage space for fresh				
fruits and vegetables	6.700	6,900	2,400	3,500

D. SPACE REQUIREMENTS (Concluded)

		NON-WI			I momar	TIOD ON I MIT
	Ow	ner		n-owner	TOTAL FOR STATE	
	Have	Additional	Have	Additional	Have	Additional
	now	room needed	now	room needed	lnow	room needed
Bedrooms	15,500	3,500	9,000	3,000	149,100	25,200
Number of entries	6,200	1,900	4,600	1,800	56,600	15,400
Living room	3,000	1,300	1,500	1,900	36,300	12,600
Dining room	2,900	1,300	1,100	1,900	34,000	12,300
Kitchen	5,900	100	4,350	1,500	54.950	2,750
Work room	300	1,600	200	1,100	4.800	7,350
Wash room for		1			,,,,,,	,,050
farm help	80	600	20	300	1.200	2,400
Bathrooms	400	2,300	100	1,900	14,600	18,700
Halls	1,000	50	300	10	15,100	520
Basement	10	50	10	_	920	250
Closets	1,550	11,400	650	8,400	58,000	85,400
Number of entries	900	3,600	400	3,200	24,500	33,200
Front or side porch	4,700	800	3,000	1,100	47,700	5,700
Back porch	2,900	1,900	1,500	1,900	36,300	11,300
Storage space for fresh			_,500		30,500	22,000
fruits and vegetables	400	1,500	100	1,400	9.600	13.300

the state of the s

	* * * * * * * * * * * * * * * * * * * *	13141 4	- 1		
	*	1		1	
			10 mm		
ž.	. 1				
4 .	•				

*** ***		A Comment of the second of the	
**		A compared to the second	
		The second second second second	

		enger te construction	process on the contract of
ķ.			
•			
•			
			,
•	*		

• (i) = - - • (i) = - - • (ii)

•

E. WATER SUPPLY AND SEWAGE DISPOSAL

			WHI	TE		
		Owner			Non-owner	
	now	Repairs or alterations needed	New instal lation needed	Have now	Repairs or alterations needed	New instal ation needed
Source of water: Well, drilled or driven Well, dug or bored Spring Cistern Stream Water supply for house: Carried	18,900 10,400 1,300 350 200	800 1,400 30 20	600 600 30 10	8,800 5,100 1,000 70 250	500 1,400 30 -	400 800 - 10 -
Distance (total feet) Number carrying water Hand pump in dwelling Piped, cold Piped, hot Sanitary facilities: Outdoor toilet (privy):	3,429,000 17,000 5,200 9,600 3,900	100 150 100	1,600 5,000 5,700	2,909,000 9,900 2,000 3,800 1,100	40 130 60	1,100 2,700 3,100
Improved Unimproved Indoor:	2,600 22,300	250	9,000	1,300	100	5,200
Chemical Flush Bathroom fixtures:	110 7,200	50	30 5,900	30 2,700	120	5 2 , 700
Tub Shower Lavatory Kitchen sink with drain Disposal of sewage:	8,000 2,200 7,200 9,800	100 30 50 250	6,100 1,300 5,600 7,000	2,600 700 2,400 3,550	40 40 50 120	3,200 630 2,700 4,000
Septic tank Cesspool Stream Surface	5,800 2,000 350 6,300	70 50 -	5,300 3,400 50	1,900 850 200 2,800	10;	2,300 1,900 30

E. WATER SUPPLY AND SEWAGE DISPOSAL (Continued)

			NON-	-WHITE		
		Owner			-Owner	
	Have now	Repairs or alterations needed	New insta	l Have	Repairs or alterations	New install - lation needed
Source of water Well, drilled or driven Well dug or bored Spring Cistern Stream Water supply for house: Carried	3,400 1,900 700 10 100	300 300 30 - -	200 200 10 - -	3,200 1,000 300 - 100	100 200 60 -	400 100 10 - -
Distance (total feet) Number carrying water Hand pump in dwelling Piped, cold Piped, hot Sanitary facilities: Outdoor toilet (privy):	2,279,000 5,600 300 400 20	50 40 10	1,750 1,900	1,854,000 4,000 200 10	19 10 -	800 1,500 1,700
Improved Unimproved Indoor:	400 4,800	110	1,600	200 3,700	30	1,700
Chemical Flush Bathroom fixtures:	250	5 0	1,800	200	-	1,600
Tub Shower Lavatory Kitchen sink with drain Disposal of sewage:	150 5 160 200	- - 30	1,900 150 1,850 2,300	50 100 100 150	- - - -	1,600 200 1,500 2,400
Septic tank Cesspool Stream Surface	150 5 100 3,200	5	1,800 200	150 5 40 2,700		1,500 800 30

•

- 6 -

E. WATER SUPPLY AND SEWAGE DISPOSAL (Concluded)

		TOTAL FOR STATE	
	Have now	Repairs or alter- ations needed	New installation needed
Source of water: Well, drilled or driven Well dug or bored Spring Cistern Stream Water supply for house:	34,300 18,400 3,300 430 650	1,700 3,300 150 20	1,600 1,700 50 20
Carried Distance (total feet) Number carrying water Hand pump in dwelling Piped, cold Piped, hot Sanitary facilities: Outdoor toilet (privy):	10,471,000 36,500 7,800 14,200 5,030	200 330 170	3,850 10,900 12,400
Improved Unimproved Indoor:	4,500 41,200	490 -	17 , 500
Chemical Flush Bathroom fixtures:	140 10,350	220	35 12,000
Tub Shower Lavatory Kitchen sink with drain Disposal of sewage:	10,800 3,005 9,860 13,700	140 70 100 400	12,800 2,280 11,650 15,700
Septic tank Cesspool Stream Surface	8,000 2,860 690 15,000	85 80 	10,900 6,300 110

F. LIGHT AND HEAT (Number of farm houses)


					,	
			WHITE			
		Owner			Mon-owner	
	Have	Repairs or	New instal	Have	Repairs or	New instal
	now	alterations		now	alterations	Antion
7 - 27		needed	needed		needed	needed
Lighting:						
Kerosene or	00 000		200	70 660		7.000
gasoline lamps	22,000	7.00	900	12,660	-	1,000
Acetylene Piped gas	500	100	25	100	50	_
Electric:	120	20	10	10	10	_
Home plant	1,900	300	1 000	400	40	330
Power line .		50	1,000		80	330
Distance from	7,300	30	2,300	2,700	00	1,440
power line(miles)	155,000	_		77,400		_
Number of entries	25,500	_		12.900		
Heating:	23,300			12,500		
Fireplaces	21,900	4,300	2.950	10,400	2,800	2,000
Stoves	8,200	220	2,950 900	3,700	100	800
Circulating heater	700	30,	1,000	80	20	350
Pipeless furnace	80		40	10	150	10
Piped warm air,						
steam, or water						
furnace	130		40	30	-	20

F. LIGHT AND HEAT (Concluded)

				NON-V	WHITE			TOTAL FOR		
		Own	er		Non-ov	mer		STATE		
	Have	Repairs	New in-	Have	Repairs	New in	Have		New in-	
	now .	or alter-	stal	now	cr alter-	stal	now	or alter-		
		ations	lation		ations	Intion			Lowing	
		needed	needed		needed	needed		needed	needed	
Lighting:		•				·				
Kerosene or										
gasoline lamps	5,800	-	200	4,450	-	2900	44,910	-	2,300	
Acetylene	-	-	-	-	-	-	600	150	25	
Piped gas		- 1	-	-	-		130	30	10	
Electric:										
Home plant	15	_	290	30	-	580	2,345	340	2,200	
Power line	490	60	1,300	230		1,150	10,720	200	6,190	
Distance from						,	}			
power line(miles)	29.200	_	_	15,200	-	_	276,800	-	_	
Number of entries		_	_	4,460		_	48,600	-	i -	
Heating:	, , , , ,			.,						
Fireplaces	3,700	1,150	2,400	2,040	700	2,000	38,040	8,950	9,350	
Stoves	500	50	140	870		270	13,270	400	2,110	
Circulating heater	_		5	_	_	20	780	5Ω	1,375	
Pipeless furnace	_		_	_	_	_	90	_	50	
Piped warm air,										
steam, or water	i									
furnace	_	_	_	5	_	5	165	_	65	
2 00 11000		<u> </u>	. 		<u> </u>		1 100			

G. REFRIGERATION, LAUNDRY, AND COOKING FACILITIES (Number of farm houses)

1						
			WHI	TE		
		Owner			Non-cwmer	
	now	Repairs or alterations needed	New instal - lation needed	Have now	Repairs or alterations needed	New instal 4 - Intion needed
Refrigeration: Ice Mechanical Laundry: Where done:	14,950 2,700	600 300	4,800 1,100	6,100 400	300	3,800 300
Out-of-doors In kitchen In basement In special room on same level	25,600 800 70	- - -	25 20	13,500 400 -	- -	25 10
with kitchen Equipment:	2,100	20	5,200	600	20	2,850
Fixed tubs Power machine Hand machine Cooking facilities:	600 1,800 530	70 190	6,900 1,500 2,300	100 380 200	25 10	3,000 1,550 1,600
Wood or coal stoves	22,300	1,600	2,100	11,600	800	1,400
Kernsene or gas stoves Gas stoves	11,000	350 - 40	1,900	4,600 90	150	1,100
Electric stoves	1 200	1	400	200	100	80



G. REFRIGERATION, LAUNDRY, AND COOKING FACILITIES (Concluded)

					NON-WHITE		T.C.	TAL FOR S	T.TE
		Cwner			Non-cymer.				
•	Have	Repairs	New in-		Repairs	rew in-		Repairs or alter-	New in-
	now	or alter-	stal	now	or alter-				
		ations	lation		ations	lation		ations	lation
D-0-1-		needed	needed		needed	needed		needed	needed
Refrigeration:	0.000	100	7 600	1 450	7.00	7 000	24.700	1,400	12,000
Ice	2,200	400	1,600	1,450	100	1,800 30			
Mechanical	10	-	70	-	_	30	3,110	300	1,500
Laundry: Where done:									
Out-of-doors	6,000			4,500			49,600	_	
In kitchen	400	_	-	100	_	_	1,700	1 -	50
In basement	400	-	_	100	_	10	70		40
In special room	_	-	_	_	_	1	/	_	40
on same level						į			
with kitchen	70	_	300	30	_	1,150	2,800	40	9,500
/Equipment:	/ /		300	30	_	1,150	2,000	1	3,500
Fixed tubs	10	_	2,000	20	_	1,600	730	_	13,500
Fower machine	20	5	50	_		200	2,200		3,300
Hand machine	20		200	50	_	300	800		4,400
Cooking facilities:		1				1			
Wood or coal									
stoves	5,500	900	1,100	4,000	300	800	43,400	3,600	5,400
Kerosene or gas	1			•					
stoves	700	200	300	500	100	300	16,800	800	3,600
Gas stoves	-	-	10	10	_	-	600		40
Electric stoves			20			-	1,400	50	500

H. LANDSCAPING OF HOUSE (Number of farm houses)

	WHITE								
		Owner			Non-owner				
	Have now	Repairs or alterations needed	New install lation needed		Repairs or alterations needed	New installation			
Vard: Surface drainage away from house Lawn established Plantings Walks and drives Fences	27,800 12,000 19,000 9,000 17,300	1,800 3,900 6,000 3,100 8,300	1,300 10,800 7,300 12,500 5,300	13,600 4,600 6,750 3,200 7,500	1,300 2,300 3,000 1,300 4,050	1,100 6,700 5,700 7,300 3,000			

H. LANDSCAPING OF HOUSE (Number of farm houses) (Concluded)

		MON-AHITE							
	Owner				non-ov	mer			
ŀ	lave	Repairs	New in-	Have	Repairs	new in-	Have	Repairs	New in-
r	now	or alter-	stal	now	or alter-	stal~	now	or alter-	stal
		ations	lation		ations	lation		ations	lation
	1	needed	needed		needed	needed		needed	needed
Yard:									
Surface drainage									
away from house 5.	200	600	500	3.800	500	600	50,400	4,200	3,500
Lawn establishedl.	400	700	2,500	900	i 500	2,800	18,900		22,800
Plantings 3.	050	1,200	1.700	1.500	500	2,400		10,700	17,100
Walks and drivesl,		500	3.000	800	400	2,700	14,000		25,500
	700	1,800	1,200	1,100		800		14,850	10,300

_ 9 _ State of Florida

I. RELATIVE EMPORTANCE OF REPAIRS AND EMPROVEMENTS WANTED
(Number of farm houses)

			WHITE			
	0	wmer		Non-	-owner	
	\$500	\$250	\$100	\$500	\$250	; \$100
House repairs and		1				
improvements:				0.700	7 750	000
Foundation	4,400	2,400	2,000	2,100	1,150	900 -
Exterior walls	9,800	6,300	4,000	3,700	2,200	1,600
Roof	9,100	7,600	6,700	3,650	3,100	2,700
Chimneys	3,500	1,900	1,300	1,900	1,140	870
Doors, windows,	0.050	6 000	4 500	4 650	2 520	2 050
screens	8,850	6,000	4,500	4,650	3,520	2,850
Perches	5,000	2,900	1,800	2,400	1,400	900
Interior walls,						
ceilings,	77 000	0 400	5 200	5 500	2 000	2 700
floors	11,900	8,400	5,200	5,500	3,900	2,700
Additional	6,500	4 300	2,650	2 600	2,000	1,350
room	9,400	4,300 5,500		2,600 3,600	2,200	1,400
Water system	5,100	3,100	3,400 1,800	2,100	1,400	1,000
Sanitary facilities	3,100	1,300	570	1,500	600	300
Lighting system Heating system	650	380	170	300	150	100
Bathroom equipment	7,600	3,700	1,850	2,900	1,600	870
Laundry facilities	850	300	150	540	200	180
Cooking facilities	900	580	320	330	370	570
Landscaping	1,600	850	470	600	270	170
Electricity:	1,000		470		2,70	1,0
Home plant	1,030	300	240	300	100	50
Power line	2,150	1.100	680	950	480	320
Built-in-equipment	1,600	640	290	680	320	160
Furnishings	2,550	1,550	1.000	1.200	920	1,000
				 		

I RELATIVE EMFORTINGE OF REPAIRS AND EMPROVEMENTS WANTED (Concluded)

		Owner			NON-WHI		1 1 marka	L FOR STA	opaci
		1	·		Non-owne		 		
	\$500	\$250	\$100	\$500	\$250	\$100	\$500	\$250	\$100
House repairs and									
improvements:	0.000	3 500							
Foundation	2,000	1,500	1,300	750	520	500	9,250	5,570	4,700
Exterior walls	2,000	1,500	1,000	730	560	500	16,230	10,560	7,100
Roof	2,600	2,350 900	2,350	1,000	870	960	16,350	13,920	12,710
Chimneys Doors, windows,	1,250	900	600	590	360	440	7,240	4,300	3,210
screens	2,350	1,800	1,060	1,100	750	630	16,950	12 070	0.040
Porches	1,600	1,000	800	700	380	250	9,700	12,070 5,680	9,040
Interior walls,	1,000	1,000	1 000	700	300	230	9,700	3,000	3,750
ceilings,							İ		
floors	2,300	1,600	900	1,300	920	580	21,000	14,820	9,380
Additional		1		_,			,	,	3,300
room	1,500	800	400	780	450	260	11,380	7,550	4,660
Water system	1,100	650	600	570	350	300	14,670	8,700	5,700
Sanitary facilities	750	450	500	360	200	150	8,310	5,150	3,450
Lighting system	150	30	40	220	120	80	4,970	2,050	990
Heating system	70	30	30	120	90	60	1,140	650	360
Bathroom equipment	1,400	590	130	560	270	60	12,460	6,160	2,910
Laundry facilities	170	30	10	100	30	20	1,660	560	360
Cooking facilities Landscaping	170	80	110	70	50	20	1,470	1,080	1,020
	180	50	40	40	- 1	10	2,420	1,170	690
Electricity: Home plant	140	40	40	20	20				
Power line	900	40 210	40 70	30 280	20 60	20	1,500	460	330
Built-in-equipment	70	30	20	80	50	20 60	4,280	1,850	1,090
Furnishings	350	130	100	140	10	40	2,430 4,240	1,040	530
		130	, 100	1-40	10		4,240	2,010	2.140


. **V**= . . .

- 10 -

J. NEW CONSTRUCTION AND FINANCING

	THITTE		3109	-WHITE	TOTAL FOR
	Owner	Mon-owner	Owner	Non-owne	
Is construction of new house contemplated within next 3 years? Yes (Number of houses)	4,900	2,600	500	1,100	9,100
Fo (Number of houses)	-	-	-	-	
If so, Number of rooms	6,400	3,100	700	900	11,100
umber of entries	1,400	600	160	200	2,360
Stimated expenditure	1,274,300	634,900	58,050	113,450	2,080,700
Number of entries	1,000	500	100	200	1,800
Value of repairs and improvements made on present house during the past 3 yrs. Under \$100 (Mumber of farm houses)	9,400	4,900	1,300	700	16,300
\$100 to \$499 (Number of farm houses)	4,900	1,300	300	100	6,600
\$500 and over(Number of farm houses)	2,000	300	70	30	2,400
Expenditure for repairs or improvements con- templated within next 12 months Total value	1,088,800	449,800	169,300	38,600	1,746,500
Number of entries	4,800	1,400	1,300	400	7,900
Is money available from local credit sources to finance house construction, repairs or improvements? Yes (Number of farm houses) Would you be interested in borrowing money to finance construction, repairs, or improvements, provided interest rate is satisfactory and pay-	4,200	1,700	400	700	7,000
ments can be distributed over a period of 10 yrs Yes (Number of farm houses)	11,000	2,500			18,400
No (Number of farm houses)	15,400	9,350			29,150
How much would you desire to borrow? Number of entries (Farm houses)	7,220,600	1,695,400 2,250	3,600	555,300	13,178,300 17,350

These are all preliminary data, subject to revision before the data are published.





U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C

Release - Immediate

April 28, 1934

FARM HOUSING SURVEY
(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Norks Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the : country are being covered by the investigators.

Preliminary Report for Randolph County, West Virginia (Subject to Later Revision)

Reports on 1908 farm houses surveyed in Randolph County, West Virginia, have now been tabulated. There are 210 log houses, 1 earth house, 763 unpainted frame houses, 900 painted frame houses, 8 stucco houses, 22 brick houses, 1 stone house, and 3 concrete houses. There are 1323 houses which have more than one story. An average of 6 rooms per house is shown. There were 1755 houses in this county in 1929 and the farm population was 10,099. Some of the most significant figures shown by the survey are as follows:

Condition of House

Of the 1908 houses surveyed, replacements, renewals, or new installations and repairs were needed as follows:

	Complete replacement,	Repairs or	
	renewals, or new	alterations	
	installation needed	needed	
Screens	970	277	ED F
Paint, exterior	825	244	101-
Chimneys	437	126	Di
Roofs	38 8 °	483	e ought
Interior walls and ceiling	s 3 69	571	Julia j
Foundations	3.47	417	.0
Insulation	328	19	DEFARE
Floors	321	374	EFARTMENT OF AGRICU

Need for Additional Space Space requirements were as follows:

	Have	Additional	Per cent of farm
	now	rooms needed	houses in which
			additional rooms
		٠.	are needed
Bedrooms	5510	rooms 899 rooms	27.7
Storage space for fresh			
fruits and vegetables	1052	735	38.5
Back porches	983	589	30.9
Front or side porches	1295	448	-23.5
Dining rooms	852	241	12.6
Bathrooms	130	351	18.4

2442-34

Water Supply and Sewage Disposal

	Have now	New installati needed	on Per cent
water carried by hand	1496		
Hand pump in dwelling	196	810	42.5
Running water, cold	245	442	23.2
Running water, hot	74	356	18.7
Unimproved outdoor toilets	1595	-	
Improved outdoor toilets	43	1442	75.6
Improved indoor toilets	93	417	21.9
Tub or shower baths	112	423	22.2
Kitchen sink with drain	425	1079	56.6

Light and Teat

And a series and a large contract to the series and the series are the series and the series are the series and the series and the series are the series and the series and the series are the series and the series are the series and		
1	Have now	New installation
		needed
Kerosene or gasoline lamps -	1692	81
Gas lights	94	13
Electric lights:		
Home plant	65	37
Fower line	92	_ 146
Fireplaces	327	4
Stoves	1685	239
Central heating system	113	164
		

Refrigeration, Laundry, and Cooking Facilities

	Have now	New installation needed	
Icc boxes .	74	8	
Mechanical refrigeration	19	94	
Washing machines, power	148	419	
Washing machines, hard	199	438	
wood or coal cook stoves	1792	213	
Kerosene or gasoline steves	2.7	2	
Gas stoves	110	. 8	
Electric stoves	l	1	

Landscaping of House

	Have now	New installation needed
Lawms established	1555	300
Walks and drives	425	1039
Fences	1258	677

Relative Importance of Repairs and Improvements Wanted

	\$500	\$250	\$100
House repairs and improvements:			
Foundation	. 386	318	261
Exterior wells	808	66 7	492
₹00 f	565	497	461
Chimneys	230	165	92
Doors, windows, screens	397	307	206
Porches	505	353	197
Interior walls, coilings, floors	697		409
Additional room	390	269	146
Water system	490	' 294	135
Sanitary facilities	162	. 69	31
Lighting system	71	37	19
Heating system	7 5	33	15
	309	132	37
Laundry facilities	182		32
Cooking facilities	85	50	31
Landscaping	225	126	81
Electricity:			
Home plant	58	10	4
Power line	124	41	14
Built-in-equipment	90	53	28
Furnishings	238	119	74

Questions regarding new construction and availability of local credit sources to finance construction contained on the questionnaire were answered by the occupants as follows:

New Construction and Financing

Number of persons reporting contemplated construction		
Number of persons reporting contemplated construction of new house within next 3 years	73	
Number of rooms to be constructed	352	
Number of entries Estimated expenditure	68 \$62,285	
Number of entries	71	
Value of repairs or improvements made on the present		
house during the last 3 years:		
Less than \$100	1568	
\$100 to \$499 \$500 and over	252 38	
9300 and 0701	36	
Expenditure for repairs or improvements contemplated		
within next 12 months Number of entries	\$5 3, 452 434	
Number of entries	454	
Number of persons reporting that money is available		
from local credit sources to finance house construction, repairs, or improvements	435	
odiloti dovicity i opazi by of znipi ovomorivi	-133	
Number of persons interested in borrowing money to		
finance construction, repairs, or improvements provided interest rate is satisfactory and		
repayments can be distributed over a period of 10 years	370	
Not interested	1,501	
Total sum desired	\$152 , 585	
Number of entries	355	

These are all preliminary data, subject to revision before the data are published.

INFORMATION FOR THE PRESS



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



Release - Immediate

WASHINGTON, D. C.

April 28, 1934

FARM HOUSING SURVEY
(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to : provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the : country are being covered by the investigators.

Preliminary Report for Monongalia County, West Virginia (Subject to later revision)

Reports on 2041 farm houses surveyed in Monongalia County, West Virginia, have now been tabulated. There are 111 log houses, 459 unpainted frame houses, 1389 painted frame houses, 6 stucco houses, 51 brick houses, 8 stone houses, and 17 concrete houses. The reports shew 580 houses which have one story and 1461 houses which have more than one story. An average of 5 rooms per house is shown. There were 1584 farms in this county in 1929 and the farm population was 3417. Some of the most significant figures shown by the survey are as follows:

Condition of House

Of the 2041 farm houses surveyed, replacements, renewals, or new installations and repairs were needed as follows:

	Complete replacement,	
	renewals or new	alterations
	installation needed	needed
Screens	944	361
Paint, exterior	902	290
Foundations	779	500 582
Roofs	272	582
Interior walls and ceilings	169	811 .
Floors	162	482
Doors and windows	182	682

Need for Additional Space Space requirements were as follows:

	Have	Addi	tions	al Po	ercent of farm	houses in
	now	room			nich additional	
		need			e needed	. I Comb
Bedrooms	5527	rooms			29.3	
Storage space for fi	3321	1 0 91112	911	T.OOMS	29.3	1
prorage space for I	resn					1/2
fruits and vegetable	Les 1639		377		18.5	#/
Work rooms	332		263		12.9	# AGRIC
Living rooms	1737		235		11.5	18
Front or side porch			232			Mis. c
					11.4	DE. DE
Dining rooms	1056	7.	178		; 1 8 _• 7 ;	TO E.
Back porches	1384		166		8.1	-04

Water Supply and Sewage Disposal

	Have		Ter cent of houses in which
	now	needed	new installation is needed
Water carried by hand	1418	4	
Hand pump in dwelling	292	944	46.3
Running water, cold	414	190	9.3
Running water, hot	222	223	10.9
Unimproved outdoor toilets	1748		e e
Improved outdoor toilets	65	1656	81.1
Improved indoor toilets	222	122	6,0
Tub or shower baths.	252	96	4.7
Kitchen sinks with drain	930	977	47.9

Light and Heat

				
		Have now	New installati	.on
	A 7	10000 1000	needed	· · · · · · · · · · · · · · · · · · ·
Kerosene or gasol	ine lamps	957	1 1 1	
Con 7: db+-	_	F04		
Electric lights:		an area part of the state of th	per progress of the control of	* * *
Home plant		36	3	
Power line		487	117	
Fireplaces"		1173	5	
Steves *	, ,	1072	7	
Central heating s	ystem	323	1365	

Refrigeration, Laundry, and Cooking Facilities

	Have now	New installation	
		needed	. ນ
Ice boxes	254	27	
Mechanical refrigeration	79	7	
Washing machines, nower	679	708	
Washing machines, hand	155	286	
Wood or coal cook stoves	1634	34	
Kerosene or gasoline stoves	63	1	
Gas stoves	64ō	5	
Electric stoves	17	-	

Landscaping of House

	Have now	New installation needed	
Lawns established	1641	339	
Walks and drives	881	1070	
Fences	1208_	469	

Relative Importance of Repairs and Improvements Wanted

	\$500	\$250	\$100
House repairs and improvements:			
Foundations	289	210	168
Exterior walls	677	561	413
Roof	457	400	355
Chimneys	129	98	73
Doors, windows, screens	282	200	168
Porches	402	272	177
Interior walls, ceilings, floors	456	364	296
Additional room	428	263	151
Water system	452	306	174
Sanitary facilities	92 ;	62	··· ·47
Lighting system	77	32	10
Heating system	110	73	27
Bathroom equipment	299	196	68
Laundry facilities	94	65	54
Cooking facilities	39	24	18
Landscaping	168	95	110
Electricity:			
Home plant	13	6	1
Power line	171	70	26
Built-in-equipment	53	32	22
Furnishings	137	88	15‡

Questions regarding new construction and availability of local credit sources to finance construction contained on the questionnaire were answered by the occupants as follows:

New Construction and Financing

		·
Number of persons reporting contemplated construction of new house within next 3 years Number of rooms to be constructed Number of entries	37 168 35	
Value of repairs or improvements made on the present house during the last 3 years: Less than \$100 \$100 to \$499 \$500 and over	1635 331	
Expenditure for repairs or improvements contemplated within next 12 months Number of entries	75 \$38 , 263 234	
Number of persons reporting that money is available from local credit sources to finance house construction, repairs, or improvements	. 32	
Number of persons interested in borrowing money to finance construction, repairs, or improvements provided interest rate is satisfactory and repayments can be distributed over a period of 10 years Not interested	263 1 ; 778	
Total sun desired Number of entries	\$126,840 254	

These are all proliminary data, subject to revision before the data are published.



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



Release - Immediate

WASHINGTON, D. C

FAMM HOUSING SURVEY (A Civil Works Administration Project)

May 4, 1934

The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the country are being covered by the investigators. This report on the State of Maryland is the third State Swamary to be issued.

PRELIMINARY REPORT FOR THE STATE OF MARYLAND

(Subject to later revision)

BRAR BUREAU O. AGRICULTERAL ECOMENTO S. DEPARTMENT OF AGRICULTE

Approximately ten per cent of the counties in each State, except New York and Pennsylvania, have been surveyed. Reports on 7,558 occupied farm houses in Caroline, Carroll, and Talbot Counties, Maryland, have now been tabulated. There were 6184 farms in these three counties in 1929. Appropriate weights have been applied to the summarized data for each county surveyed in projecting the figures over the State as a whole.

There were 43,203 farms in Baryland in 1929 and the farm population was 237,456. The total value of farm dwellings was \$88,617,433, covering 41,447 farms in Maryland.

	WHITE	NON-WHITE		TOTAL FOR STATE	
	Ovmer	Owner Non-owner		Non-owner	TOTAL DEFORE STATE
Total number of farm houses	28,600	15,200	3,200	6,700	53,700
Total acres in farm	2,057,000	1,436,000	61,000	250,000	3,804,000
Number of entries	28,300	12,200	3,200	3,000	46,700
Average acres per farm	73	118	19	83	81
Total acres tillable in farm	1,507,000	1,057,000	42,000	179,000	2,785,000
Number of entries	28,200	12,200	3,200	3,000	46,600
Average acros tillable per farm	53	87	13	60	60

*Census of Agriculture, 1930

2495-34



B. HOUSE - GENERAL INFORMATION

	WHITE		NON-WHITE		MOMAT MOD COLUMN
	Owner	Non-owner	Owner	Non-owner	TOTAL FOR STATE
Kind of house (Number)	i				
Log	l 265	140	155	60	620
Earth	15	5	_	_	20
Frame					
Unpainted	1,550	875	560	830	3,815
Painted	22,700	11,670	2,335	5,630	42,335
Stucco	560	200	130	50	940
Brick	2,800	1,900	-	80	4,780
Stone	520	370		20	910
Concrete	190	40	20	30	280
Age of house (Number)	Į				
Under 10 years	2,400	760	240	420	3,820
10 to 24 years	4,170	1,500	580	780	7,030
25 to 49 years	8,390	4,350	1,360	2,540	16,640
50 and over years	13,640	8,590	1,020	2,960	26,210
One story house (Number)	1,070	350	160	180	1,760
More than 1 story (Number)	27,530	14,850	3,040	6,520	51,940
Total number of rooms	250,400	128,500	17,700	36,100	432,700
Number of entries	28,600	15,200	3,200	6,700	53,700
Average number of					0.7
rooms per house	8.8	8.5	5.5	5.4	8.1
Total number of rooms		į			
not in use at any time of year	2.060	7 600	200	7 000	12 060
Number of entries	3,960	7,620	200	1,080	12,860
Manual, or curres	1,500	2,500	100	300	4,480
			ł		
."			,		
Total number of regular	•				• 2
occupants	117,300	71,800	13,100	33,100	235,300
Number of entries	28,550	15,200	3,180	6,700	53,630
Average number of	20,000	13,200	3,100	0,700	33,030
occupants per house	4.1	4.7	4.1	4.9	4.4
Average number of		7.	701	7.9	7.7
occupants per room	0.5	0.6	0.7	0.9	0.5

C. CONDITION OF HOUSE

	· WHITE OWNERS (Number of Entries)								
	Pre	sent Conditio	n	Repairs or	Replacement or				
	Good	Fair	Poor	alterations needed	new instal- lation needed				
Foundation	22,550	5,070	980	4,300	700				
Walls, exterior	20,700	6,600	1,300	5,700	880				
Roof	19,550	6,600	2,450	5,780	2,420				
Chimneys	24,250	3,740	600	3,180	460				
Doors and windows	19,900	7,700	1,000	6,800	820				
Screens	18,600	7,880	1,400	3,400	5,750				
Paint, exterior	9,200	10,100	8,340	2,650	15,200				
Interior walls and ceiling	17,000	9,700	1,900	8,200	~2,350				
Floors	21,500	6,300	800	4,850	960				
Stairs	24,000	3,500	300	2,500	300				
Insulation	9.230	15,900	2,800	11,300	2,640				



- 3 - C. COMDITION OF HOUSE (continued)

WHITE NON-OWNERS (Number of Entries)									
	Pres	ent Conditio	n	Repairs or	Replacement or				
	Good	Fair	Poor	alterations needed	new instal- lation needed				
Foundation Walls, exterior Roof Chimneys Doors and windows	10,200 9,050 9,150 11,425 8,000	3,700 4,625 4,150 2,850 5,800	1,300 1,525 1,900 925 1,400	2,770 3,800 3,700 2,160 4,800	930 1,030 1,570 700 1,200				
Screens Paint, exterior Interior walls and ceiling Floors Stairs Tnsulation	7,650 3,450 6,400 9,200 11,350 3,660	5,075 5,200 6,450 4,750 3,000 9,250	1,500 6,000 2,350 1,250 620 1,800	2,040 2,000 5,500 3,470 1,800 5,600	4,230 8,700 2,300 1,200 530 1,620				

C. COMDITION OF HOUSE

NON-WHITE OWNERS (Number of Entries)									
	Prese	nt Condition	n	Repairs or	Replacement or				
	Good	Fair	Poor	alterations needed	new instal- lation needed				
Foundation Walls, exterior Roof	1,400	1,070	700	840	530				
	1,050	1,300	850	1,240	560				
Chimneys Doors and windows	1,200	1,100	900	1,030	750				
	2,100	770	270	490	250				
	1,150	1,400	650	1,220	520				
Screens Paint, exterior	850 290	1,100	700 1,900	520 460	1,550 2,100				
Interior walls and ceiling Floors	700	1,500	1,000	1,530	770				
	1,460	1,200	540	770	460				
Stairs	1,960	830	290	430	240				
Insulation	440	2,000	570	940	470				

C. CONDITION OF HOUSE

NON-WHITE NON-OWNERS (Number of Entries)									
	Pres	sent Conditio	n	Repairs or	Replacement or new instal- lation needed				
	Good	Fair	Poor	alterations needed					
Foundation Walls, exterior Roof Chimneys Doors and windows Screens Paint, exterior Interior walls and ceiling Floors Stairs Insulation	2,720 2,000 2,470 3,400 1,760 1,400 870 1,330 2,550 3,150 1,200	2,400 2,875 2,300 2,350 3,040 2,300 1,900 2,790 2,800 2,500 3,700	1,560 1,825 1,930 930 1,900 1,600 3,700 2,580 1,350 1,000 1,500	1,580 2,170 1,820 1,200 2,150 1,000 1,400 2,800 1,570 1,000 1,140	1,040 1,110 1,450 670 1,420 2,900 3,400 1,550 900 730 1,000				

- 4 C. CONDITION OF HOUSE (Concluded)

TOTAL FOR STATE (Number of Entries)									
	Prese	ent Condition	1	Repairs or	Replacement or				
	Good	Fair	Poor	alterations needed	new instal- lation needed				
Foundation	36,870	12,240	4,540	9,490	3,200				
Walls, exterior	32,800	15,400	5,500	12,910	3,580				
Roof	32,370	14,150	7,180	12,330	6,190				
Chimneys	41,175	9,710	2,725	7,030	2,080				
Decre and windows	30,810	17,940	4,950	14,970	3,960				
Screens	28,500	16,355	5,200	6,960	14,430				
Paint, exterior	13,810	17,830	19,940	6,510	29,400				
Interior walls and ceiling	25,430	20,440	7,830	18,030	6,970				
Floors	34,710	15,050	3,940	10,660	3,520				
Stairs	40,460	9,830	2,210	5,730	1,800				
Insulation	14,530	30,350	6,670	18,980	5,730				

D. SPACE REQUIREMENTS *

		WHITE		
	Own	ner	Non-	-owner
	Have now	Additional room needed	Have	Additional room needed
Bedrooms ** Number of entries Living room Dining room Kitchen Wark room Wash room for	111,400 28,600 28,200 26,300 28,500 7,700	1,270 870 100 290 70 370	58,800 15,200 14,900 13,500 15,150 3,480	590 430 40 140 80 140
farm help Bathrooms Halls Barement Closets *** Number of entries Frent or side porch Back porch Styrage space for fresh	980 7,460 15,800 17,500 81,300 24,500 25,400 24,200	60 4,660 50 600 8,000 3,450 430 350	480 2,200 8,300 7,150 39,400 13,350 12,800 11,900	40 2,000 10 500 6,260 2,540 290 270
fruits and vegetables	20,700	_ 300	9,300	180

D. SPACE REQUIRE E.TS *

(Concluded)								
		Owner	Non-c	wmer	TOTAL FOR STATE			
	Mave	additional	Have	Additional	Have	Additional		
	now	room needed	now	proom needed	new	room needed		
Bedrooms **	3,180	520	17,600	750	195,980	3,130		
Number of entries	3,170	340	6,700	530	53,670	2,170		
Living room	2,900	30	5,700	30	51,700	200		
Dining room	2,200	100	4,100	150	46,100	680		
Kitchen	3,110	20	6,600	20	53,360	190		
Work room	໌ 23ົ	10	320	_	11,730	520		
Wash room for			1					
farm help	10	10	30	20	1,500	130		
Bathrooms	60	290	100	140	9,820	7,090		
Halls	700	_	1,450		26,250	60		
Basement	950	10	860	60	26,460	1,170		
Closets ***	4,260	1,000	9,960	1,430	134,920	16,690		
Number of entries	2,460	530	5,590	800	45,900	7,320		
Frent or side porch	1,730	120	2,900	100	42,830	940		
Baok porch	1,180	100	2,100	60	3 9,380	780		
Storage space for fresh			1		23,300	,00		
fruits and vegetables	1,180	240	1.380	130	32.560	850		

^{*} Number of entries, except where otherwise indicated.

** Number of bedrooms.

** Number of closets.



- 5 - State of Maryland E. WATER SUPPLY AND SEWAGE DISPOSAL *

WHITE							
		Owner			Non-owner		
	Have now	Repairs or alterations needed	New instal- lation needed	Have now	Repairs cr alterations needed	New instal- lation needed	
Source of water: Well, drilled or driven Well, dug or bored Spring Cistern Stream ater supply for house: Carried	14,100 10,300 5,300 900 40	200 180 20 15	150 60 10 30	7,200 5,600 2,780 590 10	50 80 30 5	200 80 - - -	
Distance (total feet) Number carrying water Hand pump in dwelling Fiped, cold Piped, hot Sanitary facilities: Outdoor toilet	785,700 16,600 3,200 9,480 6,200	- 60 200 100	3,500 6,700 5,900	497,700 10,000 1,700 3,400 1,500	85 280 100	3,300 2,900 2,720	
(privy): Improved Unimproved	6,800 17,450	60	6 , 250	4,200 9,800	40	5,270	
Indoor: Chemical Flush	110 5,825	70	20 7 , 900	30 1,525	_ 150	3,300	
Bathrocm fixtures: Tub Shower Lavatory Kitchen sink with drain	6,300 1,730 6,000 11,600	100 25 75 100	7,650 400 7,600 8,620	1,650 400 1,500 4,700	120 25 115 80	3,300 200 3,250 5,780	
Disposal of sewage: Septic tank Cesspool Stream Surface	1,800 3,600 925 4,200	25 40 - -	2,700 5,170 80	520 950 350 2,300	30 10	1,050 2,330 20	

E. WATER SUPPLY AND SEWIGE DISPOSAL * (Continued)

(Continued)									
NON-WHITE									
		Owner		Non-owner					
	Have now	Repairs or alterations needed		Have now	Repairs or alterations needed	New instal- lation needed			
Source of water: Well, drilled or driven Well dug or bored Spring Cistern Stream Water supply for house: Carried	1,900 800 470 - -	200 60 - - -	150 10 - - -	3,500 2,600 500 10	300 160 - -	300 160 - - -			
Distance (total feet) Number carrying water Hand pump in dwelling Piped, cold Piped, hot Sanitary facilities: Outdoor toilet (privy):	358,300 3,100 100 20 10	10 20	1,200 400 230	519,300 6,200 300 300 90	30 - -	3,100 200 250			
Improved ; Unimproved ; Indcor: Chemical	200 2,800 -	10 -	1,830	700 5,650	10	5,200			
Flush Bathroom fixtures:	20	-	400	80	30	200			
Tub Shower Lavatory Kitchen sink with drain	30 10 10 10	- - 10	400 - 400 1,590	70 10 50 500	10 10	200 10 250 3,410			
Disposal of sewage: Softic tank Cesspool Stream Surface	10 - - 50	-	50 330 - -	40 50 25 150	= = =	100			

Number of entries except where otherwise indicated.



	TOTAL FOR STATE							
	Have now	Repairs or alter- ations needed	New installation needed					
Source of water:								
Well, drilled or driven	26,700	750	800					
Well dug or bored	19,300	480	310					
Spring	9,050	50	10					
Cistern	1,500	20	30					
Stream	50	_	-					
Water supply for house:		•						
Carried	0.000							
Distance (total feet)	2,161,000	-	_					
Number carrying water	35,900	3.05	77.700					
Hand pump in dwelling	5,300	185	11,100					
Piped, cold	13,200	500	10,200					
Piped, hot	7,800	200	9,100					
Sanitary facilities: Outdoor toilet								
(privy):								
Improved	11,900	120	18,550					
Unimproved	35,700	120	10,330					
Indoor:	33,700							
Chemical	140	_	20					
Flush	7,450	250	11,800					
Bathroom fixtures:	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,							
Tub	8,050	220	11,550					
Chower	2,150	50	610					
Lavatory	7,560	200	11,500					
Kitchen sink with drain	16,900	200	19,400					
Disposal of sewage:								
Septic tank	2,370	25	3,900					
Cesspool	4,600	70	8,000					
Stream	1,300	10	100					
Surface	6,700							

F. LIGHT AND HEAT (Number of farm houses)

			TATTOR			
***************************************			WHITE			
		Owner			Non-owner	
	Have Repairs or 1 alterations 1 needed			Rave now	Repairs or alterations needed	New instal- lation needed
Lighting: Kerosene or						
gasoline lamps Acetylene Piped gas Electric:	17,550 960 130	140 20	20 20 -	12,350 190 20	80	30 10 -
Home plant Power line Miles Aunber of entries	2,160 8,300 37,850 20,200	130 20 -	350 3,800	560 2,300 24,420 12,800	50 40 -	130 2,200
Heating: Fireplaces Stores	1,500	15 30	15	600	10	-
Circulating heater Pipeless furnace	25,000 2,250 3,000	50	100 120 330	14,500 1,100 650	20	50 20 180
Piped warm air, steam, or water furnace	2,500	35	1,450	590	65	450

- 7 F. LIGHT AND HEAT (Number of Entries)
(Concluded)

				M	OM-WHITE			 	
		Owne	er		Nonown	er	TOTAL FOR STATE		
	Have now	Repairs or alter- ations needed	New in- stal- lation needed	Have now	Repairs or alter- ations needed	New in- stal- lation needed	now	Repairs or alter- ations needed	New in- stal- lation needed
Lighting: Kerosene or									
gasoline lamps Acetylene Piped gas Electric:	2,950	-		6,450 40 10	10	10	39,300 1,200 160	220	60 30 -
Home plant Power line Liles Number of entries Heating:	200 5,880 2,900	- - -	30 200 - -	60 200 13,550 6,400		. ,300 - -	2,800 11,000 81,700 42,300	60	510 6,500 -
Fireplaces Stoves Circulating heater Pipeless furnace Piped warm air, steam, or water	3,100 125 30	20 - -	20 20 20	100 6,650 125 20	10 200 - -	50 - 20	2,200 49,250 3,600 3,700	350 –	15 200 160 600
furnace			75	10	_	25	3,100	100	2,000

G. REFRIGERATION, LAUNDRY, AND COOKING FACILITIES (Number of DEntries)

			WHITE				
		Owner		Non-owner			
	Have now	Repairs or alterations needed	New instal- lation needed	Have now	Repairs or alterations needed	New instal- lation needed	
Refrigeration: Loe Mechanical Laundry:	11,900 1,750	15 -	250 750	6,500 250	25 -	250 150	
Where done: Out-of-doors In kitchen In basement In special rcom on same level	10,300 14,500 2,800	- - -	 - 5 -	5,600 9,400 1,100	- - -	- 25 5	
with kitchen Equipment:	4,300	10	50	2,000	10	20	
Fixed tubs Power machine Hand machine Cooking facilities: Wood or ccal	500 8,500 4,300	15 100 85	25 1,300 140	100 3,200 2,400	50 40	20 800 160	
stoves Kerosene or gas	27,000	40	50	14,700	100	100	
stoves Gascline stoves Electric stoves	13,600 840 700	125 35 10	550 75 250	6,300 150 50	125 - -	250 10 50	

G.	REFRIGER	RATION, LAU	NDRY, ANI			IES (Conc.	luded) (1	Tumber of	entries)
				NCN-W	HITE		mo.		A mus
		Owner			Non-own	ner	10	TAL FOR SI	ATL
	77 170 1 177								
	Have	Repairs	New in-	f .	Repairs	New in-	Have	Repairs	New in-
	now	or alter- ations	stalla- tion	now	or alterations	tion	now	or alter- ations	stalla- tion
		needed.	needed		needed	needed		needed	needed
Refrigeration:		1							
Ice	1,285	10	40	2,615	-	100	22,300		640
Mechanical	-	-	25	_	-	-	2,000		925
Laundry: Where done:									
Out-of-doors	1,300	_		2,400		_	19,600		_
In kitchen	3,000	-		6,300	_	-	33,200	_	30
In basement	50	_	-	50	-	-	4,000		5
In special room									
on same level with kitchen	75			7 5			6,450	20	70
Equipment:	75	_	_	75		-	0,450	20	70
Fixed tubs	_	- 0	_	10	-		610		45
Power machine	130	10	100	60	-	100	11,890		2,300
Hand machine	100	-)	- 1	160	20	20	6,960	145	320
Cooking facilities: Wood or coal									
stoves	3,150		_ 20	6,650	150	130	51,500	290	300
Kerosene or gas	į		, 20	·	100		Ť	0	
stoves	700	50	50	1,500	30	50	22,100		900
Gasoline stoves	10	-	-	-	-	-	1,000	35	85
Electric stoves	25		-			-	775	10	300

H. LANDSCAPING OF HOUSE (Number of Entries)

(Number of Entries)												
		WHITE										
		Owner		Non-owner								
	Have now	Repairs or alterations needed	New instal- lation needed	Have now	Repairs or alterations needed	New instal- lation needed						
Yard: Surface drainage away from house Lawn established Plantings Walks and drives Fences	27,500 19,500 22,525 13,850 9,475	1,050 2,050 550 2,350 1,900	425 2,500 3,550 5,100 1,930	14,100 10,900 10,900 5,375 4,900	900 1,100 350 1,600 1,125	525 1,500 2,000 3,550 1,470						

H. LANDSCAPING OF HOUSE (Number of Entries) (Concluded)

	(Concluded)												
				MON-WI	HITE		TOTAL FOR STATE						
	(Owner			Non-owner			101111 1011 01111					
	Have now	or alter ations	New in- stalla- tion needed	Have now	Repairs or alter- ations needed	New in- stalla- tion needed		Repairs or alter- tions needed	New in- stalla- tion needed				
Yard: Surface drainage away from house	2,800	200	250	5,700	450	450	50,100	2,600	1,650				
Lawn established Plantings	1,400	200	250 550 550	3,650 3,710	325 250	850 1,050	35,450 38,950	3,675	5,400 7,150				
Walks and drives Fences	800 575	525 150	775 225	925 1,150	825 100	1,875 1,125	20,950 16,100		11,300 4,750				

1. 4

erak Santa ayan da

I. RELATIVE IMPORTANCE OF REPAIRS AND IMPROVEMENTS WANTED (Number of Entries)

			WHIT	E	, , , , ,		
		Owner			Non-owner		
	\$500	\$250	\$100	\$500	\$250	\$100	
House repairs and improvements: Foundation Exterior walls Roof Chimneys Doors, windows, screens Porches	940 11,550 5,550 880 3,200 4,350	750 10,750 5,200 770 2,300 3,360	620 9,180 4,400 560 1,500 1,954	820 6,140 2,930 850 2,700 2,320	600 5,340 2,600 630 2,000 1,670	500 4,400 2,250 450 1,300 1,100	
Interior walls, cailings, floors Additional room Water system Sanitary facilities Lighting system Heating system Bathroom equipment Laurdry facilities Cooking facilities Landscaping	9,120 2,400 6,780 3,900 3,600 2,460 6,660 900 900 1,200	7,380 1,600 4,230 1,350 1,760 1,140 2,900 550 570 740	5,270 1,000 2,630 500 800 550 1,350 400 320 600	6,530 1,170 3,880 1,700 2,040 1,100 2,750 660 520 530	5,400 800 2,560 860 1,030 400 1,220 470 360 360		
Home plant Power line Built in equipment Furnishings	480 2,280 560 2,150	300 1,250 320 1,530	220 800 200 1,350	150 1,400 300 1,400	70 700 180 1,200	50 420 100 1,040	


I. RELATIVE IMPORTANCE OF REPAIRS AND IMPROVEMENTS WANTED (Number of Entries) (Concluded)

The same of the sa	(Olio Lauca)									
				NON-WHITE	G	,	, TOTA	L FOR SI	ATE ,	
	(wner	-	No	n-owner	1				
	\$500	\$250	\$100	\$500	\$250	\$100	\$500	\$250	\$100	
House repairs and improvements: Foundation Exterior walls Roof Chimneys	370 1,650 1,150 200	300 1,470 1,040 150	240 1,240 930 130	450 2,830 1,960 440	350 2,300 1,740 320	320 1,970 1,640 190	22,170 11,590	2,000 19,860 10,580 1,870	1,680 16,790 9,220 1,330	
Doors, windows screens Porches Interior walls, ceilings,	800 7 80	580 460	430 300	1,950 11,100	1,430 630	1,080 330	8,650 8,550	6,310 6,120	4,310 3,684	
floors Additional room Water system Sanitary facilities Lighting system Heating system Bathroom equipment Laundry facilities Corking facilities Landscaping Mectricity:	1,550 490 600 350 170 30 300 30	1,180 300 260 50 20 40 80 -	660 200 160 10 10 10 70 10	3,170 670 1,160 660 300 30 250 110 100 80	2,600 430 960 470 100 30 100 60 30 40	1,930 290 740 360 80 30 70 20 40	4,730 12,420 6,610 6,110 3,620 9,960 1,700	16,560 3,130 8,010 2,730 2,910 1,610 4,300 1,080 970 1,140	11,860 2,060 5,300 1,370 1,340 790 2,020 760 570 880	
Home plant Fower line Suilt-in-equipment Furnishings	20 80 40 120	10 100 40 40	10 50 30 60	20 120 150 380	10 70 90 250	10 70 80 200	670 3,880 1,050 4,050	390 2,120 630 3,020	290 1,340 410 2,650	

J. NEW CONSTRUCTION AND FINANCING

	W	HITE	NON-	WHITE	TOTAL
	Owner	Non-owner	Owner	NonHowner	STATE
Number of persons reporting contemplated construction of new house within next 3 years Number of rooms to be constructed Number of entries Estimated expenditure Number of entries	370 2,250 360 \$675,000 330	130 750 130 \$170,400 100	60 230 60 \$22,100 40	30 200 30 \$34,600 30	590 3,430 580 \$902,100 500
Value of repairs or improvements made on the present house during the last 3 yrs: Less than \$100 \$100 to \$499 \$500 and over	12,330 6,880 2,340	7,550 2,620 610	1,600 400 70	2,430 300 150	10,200
Expenditure for repairs or improvements contemplated within next 12 months (total amount) Number of entries	\$674,000 5,530	\$192,000 1,860	\$50,700 570	\$24,400 380	\$941,100 8,340
Number of persons reporting that money is available from local credit sources to finance house construction, repairs, or improvements	4,650	1,470	200	110	6,430
Number of persons interested in borrowing money to finance construction, repairs, or improvements provided interest rate is satisfactory and repayments can be distributed over a period of 10 years Not interested	4,900 20,500	2,210 11,270	1,180 1,860	1,570 4,840	
Total sum desired Number of entries	\$1,842,000 3,160	\$689,000 1,280	\$366,000 890	\$323,000 1,020	\$3,220,000 6,350

These are all preliminary data, subject to revision before publication.



INFORMATION FOR THE PRESS



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



Release - Immediate

WASHINGTON, D. C FARM HOUSING SURVEY

May 14, 1934

(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration: project, carried out by the U.S. Department of Agriculture and: the State Agricultural Extension Services. The object is to provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the country are being covered by the investigators. This report on the State of Delaware is the fourth State Summary to be issued.



PRELIMINARY REPORT FOR THE STATE OF DILY. RE (Subject to later revision)

The Farm Housing Survey covered approximately ten per cent of the counties in each State except New York and Pennsylvania. Only one of the three counties of Delaware, Sussex, was surveyed. Reports on 2,000 farm houses in this county have been tabulated.

In each State the counties to be surveyed were selected as representative of typical farming areas, in order that the results of the surveyed counties might be projected over the whole State by applying appropriate multiplying factors. The number of farms in each area as reported in the 1930 Agricultural Census is used as the basis of this projection.

Since the housing conditions in Sussex County, Delaware, are considered typical of the rural housing conditions of the whole State, appropriate multiplying factors were derived by dividing the number of farm houses covered in the survey of Sussex County into the number of farms in the whole State as reported for 1929 in the Agricultural Census of 1930. This method was applied to each of the four classifications of occupancy (white owners, white non-owners, non-white non-owners) as well as to the total number of farm houses. The factors were applied to each item included in the survey except those covering number of farms and acreage.

The figures for these items, on number of farms and acreage, were taken directly from the Census of Agriculture of 1930, because it was found that the number of acres per farm in Sussex County was substantially less than for the other two counties in the State. The figures taken from the Agricultural Census were these on Total Acres in the Farm, Acres of Crop Land, Harvested, and Acres of Plowable Pasture Land. These figures are probably somewhat low, as a total of 504,259 acres of crop land (as against crop land harvested) and 82,855 acres of plowable pasture 2576-34



State of Delaware land, or a total of 537,114 seres of tillable land, were reported in the Census of Agriculture, making an average of 60 acres of tillable land per farm. However, because the figures on Total Crop Land were not available in the classifications of tenure and color used in the Farm Housing Survey, only those on Crop Land Harvested were included in this summary.

There were 9,707 farms in Delaware in 1929, of which 9,180 farms were reported to have a total value of farm dwellings of \$7,360,169. The farm population in Delaware was 46,530 in 1929.

_	N	HITE	NON-W	HITE	TOTAL
	Owner	Non-owner	Owner	Non-owner	STATE
Total number of farm houses	5,890	3 ,0 10	37 5	435	9,710
Total acres in farm *	466,704	379,355	13,781	40,975	900,815
Number of farms *	5,887	3,013	373	434	9,707
Average acres per farm *	7 9	126	37	94	93
Total acres of crop land harvested and plowable pasture land in farms *	246,087	218,240	7,170	18,967	490,464
Number of farms *	5,887	3,013	373	434	9,707
Average acres tillable per farm *	42	72	19	44	51

^{*} Census of Agriculture 1930



B. HOUSE - GENERAL INFORMATION

	····				
	WH	ITE	NON-WHI	TE	TOTAL
	Owner	Non-owner	Owner	Non-owner	STATE
Kind of house (Number)					_
Log	5	-	-	-	5
Earth	-	-	-	-	-
Frame		222	200	3.00	0.040
Unpainted	950	800	100	190	2,040
Painted	4,850	2,195	275	245	7,565
Stucco	30	10	-	-	40
Brick	20	5	-	-	25
Stone	10	-	-	-	10
Concrete	25	-	-	-	25
Age of house (Number)	0.40	7.00		00	700
Under 10 years	640	100	20	20	780
10 to 24 years	1,350	400	80	35	1,865
25 to 49 years	2,350	1,090	160	205	3,805
50 and over years	1,550	1,420	115	175	3,260
One story houses (Number)	235	90	10	30	365
More than 1 story	5,655	2,920	365	405	9,345
Total number of rooms	41,200	20,000	2,250	2,360	65,810
Number of entries	5,890	3,010	375	435	9,710
Averge number of	70	CO	6.0	5.4	6.8
rooms per house	7.0	6.0	6.0	5.4	0.0
Total number of rooms		,			
not in use at any time	830	940	10	60	1 0/0
of year	400	400	10	35	1,840 845
Number of entries	400	400	10	35	045
Total number of regular	23,000	14 000	1,700	2,300	41,000
occupants		14,000	375	435	9,710
Number of entries	5,890	3,010	3/5	450	3,710
Average number of	3.9	4.7	4.5	5.3	4.2
occupants per house	3.3	, T • 1	4.5	5.5	T. 6
Average number of	0.6	0.7	0.8	1.0	0.6
occupants per room	0.0	1 0.7	0.0	1 1.0	0.0

C. CONDITION OF HOUSE

	WHITE OWNERS (Number of Entries)							
	Presc	nt Condition	Ropairs or	Replacement or				
	Good	Fair	Poor	alterations needed	new instal- lation needed			
Foundation Walls, exterior Roof Chimneys Doors and windows Screens	3,570 3,970 2,925 4,710 4,140 3,320	1,870 1,600 2,105 890 1,550 1,850	450 320 860 240 200 650	1,870 1,580 1,870 870 1,500 1,850	450 320 870 230 190 650			
Paint, exterior Interior walls and ceiling Floors Stairs Insulation	1,800 3,910 4,340 5,065 2,670	2,000 1,645 1,360 680 1,170	1,880 335 190 85 850	1,865 1,650 1,350 710 1,120	1,940 360 165 85			



C. CONDITION OF HOUSE (Continued)

	WHITE NON-OWNERS (Number of Entries)							
	Pres	ent Condition	Repairs or	Replacement or				
	Good	Fair	Poor	alterations needed	new instal- lation needed			
Foundation Walls, exterior Roof Chimmeys Doors and windows Screens Paint, exterior Interior walls and ceiling Floors Stairs Insulation	1,220 1,480 1,180 1,920 1,440 1,050 620 1,310 1,690 2,220 1,055	1,300 1,150 1,180 700 1,260 1,100 860 1,240 1,040 540 690	490 380 650 350 310 720 1,390 460 280 185 715	1,300 1,160 1,130 710 1,230 1,100 780 1,240 1,025 535 650	470 360 360 320 290 740 1,490 450 290 200 710			

C. CONDITION OF HOUSE

	NON-WHITE OWNERS (Number of Entries)							
	Present	Condition			Replacement or			
	Good	Fair	Poor		new instal- lation needed			
Foundation Walls, exterior Roof Chimmeys Doors and windows Screens Paint, exterior Interior walls and ceiling Floors Stairs Insulation	110 150 150 265 120 85 85 125 150 190 90	165 185 140 80 190 160 105 190 170 140	95 40 85 30 65 120 165 60 55 40 95	165 185 140 80 160 165 105 185 160 140	95 140 80 30 60 115 165 50 60 40			

C. CONDITION OF HOUSE

	NON-WHITE NON-OWNERS (Number of Entries)								
	Preser	nt Condition	Repairs or	Replacement or					
3	Good	Fair	Poor	alterations needed	new instal- lation needed				
Foundation Walls, exterior Roof Chimmeys Doors and windows Screens Paint, exterior Interior walls and ceiling Floors Stairs	100 125 85 185 135 75 40 95 150	175 175 210 165 200 110 115 170 190	150 135 140 70 100 230 250 170 95	170 170 210 160 195 110 110 170	160 140 140 70 105 220 260 160				
Insulation	210 110	150 130	75 135	150 110	75 140				

			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	· · her :		The second of th	regardy and gold for T	er =
	196 A 5 9 A		$\label{eq:continuous} \mathcal{L}(x) = \mathbf{k} \cdot (\mathbf{k} \cdot \mathbf{k}) + \mathbf{k} \cdot (k$		
			1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -		
			٠.		
	1.4		•	4	
				•	
			•		;
		. #			•
	8		j		•

C. CONDITION OF HOUSE (Concluded)

TOTAL	FOR	STATE	(Number	Entries)
-------	-----	-------	---------	----------

	Prese	ent Condition	Repairs or	Replacement •r	
	Good	Fair	Poor	alterations needed	new instal- lation needed
Foundation Walls, exterior Roof Chimneys Doors and windows Screens Paint, exterior Interior walls and ceiling Floors Stairs Insulation	5,000 5,725 4,340 7,080 5,835 4,530 2,545 5,440 6,330 7,685 3,925	3,510 3,110 3,635 1,835 3,200 3,220 3,080 3,245 2,760 1,510 2,145	1,185 875 1,735 690 675 1,720 3,685 1,025 620 385 1,795	3,505 3,095 3,350 1,820 3,105 3,225 2,860 3,245 2,725 1,535 2,030	1,175 960 1,750 650 645 1,725 3,855 1,020 605 400 1,800

D. SPACE REQUIREMENTS *

		WHITE		
	Own		Non-owne	r
	Have	Additional	Have	Additional
	now	room needed	now	room needed
Bedrocms **	20,000	173	9,985	75
Number of entries	5,890	115	3,000	65
Living room	5,860	29	2,960	5
Dining room	5,150	69	2,450	25
Kitchen	5,850	10	2,950	5
Work room	2,730	30	850	10
Wash room for				
farm help	750	50	1.90	5
Bathrooms	910	65	190	15
Halls	3,770	20	1,500	10 5
Easement	.1,260	10	, 335	5
Closets ***	17,900	180	8,540	150
Number of entries	5,600	95	2,850	\$0
Front or side porch	4,880	35	2,320	10
Back porch	4,060	20	1,960	- 1
Storage space for fresh				
fruits and vegetables	2,430	90	1,250	330
	D. SPACE REQU	IREMENTS * (Conclude	ed)	

D. SPACE REQUIREMENTS * (Concluded)									
	TOTA	FOR STITE							
	Ow	mer		Non-owner					
	Have	Additional	Have	Additional	Have	Additional			
	now	room needed	now	room needed	now	room needed			
Bedrocms **	1,110	40	1,160	90	32,255	378			
Number of entries	375	40	425	50	9,690	270			
Living room	360	-	410	30	9,590	55			
Diring room	280		220	10	8,100	95			
Kitchen	370	₩ .	415		9,585	15			
Work room	100		5 0	5	3,730	45			
Wash room for									
farm help	15	-	10		965	55			
Bathrooms	15		10	-	1,125	80			
Halls	185		175		5,930	30			
Basement	50		3 5		1,680	15			
Closets ***	825	40	930	10	28,195	380			
Number of entries	330	25	400	5	9.185	185			
Front or side porch	230	-	200	_	7,630	45			
Back porch	200		220	-	6,440	20			
Storage space for fresh									
fruits and vegetables	40		105	5	3,825	425			

^{*} Number of entries except where therwise indicated

** Number of bedrooms

*** Number of closets



E. WATER SUPPLY AND SEWAGE DISPOSAL

E. WATER SUPPLY AND SEWAGE DISPOSAL *								
	1122	Owner						
	Have	Repairs or	New instal-	Have	alterations			
	now	alterations	lation	now		needed		
C		needed	needed		needed	needed		
Source of water:			20	0.000		10		
Well, drilled or driven	5,600	90	20	2,600	50	10		
Well, dug or bored	290	-	-	100	15	-		
Spring	-	-	-	-		5		
Cistern	20	-	-	5	-	. 5		
Stream	-	-	-	-	-	-		
Water supply for house:								
Carried				38 050				
Distance (total feet)	22,650	-		17,650	-	-		
Number carrying water	1,420	<u>.</u> ⊸,	-	1,060	-	70		
Hand pump in dwelling	4,230	70	30	2,265	50	30		
Piped, cold	1,110	5	20	170	5 5	10		
Piped, hot	770	5	10	130	5	10		
Sanitary facilities:		•						
Outdoor toilet				1				
(privy):					_			
Improved	1,440	30	20	480	5	60		
Unimproved	3,700	-	-	2,360	-	-		
Indoor:								
Chemical	35		30	15	5	-		
Flush	465	-	20	60	10	10		
Bathrocm fixtures:								
fub	710	~	70	105	5	30		
Shower	90		35	10	-	5		
Lavatory	640	-	30	100	5	30		
Kitchen sink with drain	3,920	40	120	1,300	50	105		
Disposal of sewage:	,							
Septic tank	400	5	15	55	-	-		
Cesspool	1,360	15	30	600	40	70		
Stream	430	15	5	110	-	-		
Surface	3,610		-	2,200	-	-		
	TATA DILLA COLUMN	AND CUMAN	יני הדכסספאד י	(Canting				

E. WATER SUPPLY AND SEWAGE DISPOSAL * (Continued) NON-WHITE Non-owner Owner Repairs or Repairs or Have New instal-New instal-Have alterations lation lation now now alterations needed needed needed needed Scurce of water: 30 20 430 Well, drilled or driven 360 15 Well, dug or bored 10 Spring Cistern Stream Water supply for house: Cerried 4,500 250 2,800 Distance (total feet) Number carrying water 190 Hand pump in dwelling Piped, cold Piped, hot 205 20 10 270 5 5 5 Sanitary facilities: Putdoer toilet (privy): 5 40 Improved 5 5 120 Unimproved 390 250 Indoor: Chemical 5 Flush Bathroom fixtures: Tub 5 Shower Lavatory Kitchen sink with drain 5 10 5 120 220 Disposal of sewage: Septic tank 25 Cesspool 10 50 65 Stream 5 Surface 350 300

^{*} Number of entries except where otherwise indicated.

E. WATER SUPPLY AND SEWAGE DISPOSAL * (Concluded)

	TOTA	L FOR STATE	
	Have now	Repairs or alter- ations needed	New installation needed
Source of water:	,		
Well, drilled or driven	8,990	185	50
Well dug or bored	400	15	-
Spring Cistern	-	-	1 5
Stream	25	-	5
Water supply for house:	-	-	_
Carried Carried			
Distance (total feet)	47,600		
Number carrying water	2.920	-	
Hand pump in dwelling	6,970	135	80
Piped, cold	1,290	10	30
Piped, hot	900	10	20
Sanitary facilities:			
Outdoor toilet (privy):	0.000	10	99
Improved	2,080	40	90
Unimproved Indoor:	6,700	-	_
Chemical	55	5	30
Flush	525	10	30
Bathroom fixtures:	020		
Tub	820	5	100
Shower	100	-	40
Lavatory	745	5	60
Kitchen sink with drain	5,560	95	240
Disposal of sewage:	455	-	15
Septic tank	455	5	15
Cesspool Stream	2,075 545	55 15	135
Surface	6,460	15	5
2311000	0, ±00		

F. LIGHT AND HEAT (Number of Entrice) . .

WHITE								
		Owner		Non-owner				
	Have now	Repairs or alterations needed	New instal- lation needed	Have now	Repairs or alterations needed	New instal- lation needed		
Lighting: Kerosene or								
gasoline lamps	4,100	m .	7 5	2,775	-	85		
Acetylene Piped gas	185	10	- 5	25	5 5	5		
Electric:	100	10	5	15	5	5		
Home plant	600	20	10	45	5			
Power line	940	10	5	150	5	-		
Miles Number of entries	10,670 4,250	-	-	5,540 2,450	-	-		
Heating:	4,200	-	-	2,450	-	_		
Fireplaces	25	-	5	10		5		
Stoves	5,045	275	40	2,870	300	50		
Circulating heater Pipeless furnace	610	10 2 5	- 5	100	70	-		
Piped warm air,	265	4 5	5	30	10	-		
steam, or water								
furnace	90		5	15	_			

^{*} Number of entries except where otherwise indicated.

e e

F. LIGHT AND HEAT (Number of Entries) (Concluded)

	NON-WHITE							TOTAL FOR STATE		
		Owne	r	Non-owner			•			
	Have now	Repairs or alterations needed	New in- stal- lation needed	Have now	Repairs or alter- ations needed	New in- stal- lation needed	Have now	Repairs or alter- ations needed	New in- stal- lation needed	
Lighting: Kerosene or										
gasoline lamps	345	-	5	425	-	40	7,645	. 	205	
Acetylene Piped gas	10	-	~	-	-	- :	220 115	15 15	10	
Electric:	_	_	_	~		_	113			
Home plant			-	5	~-	-	650	25	10	
Power line	10	-	-	-	~	-	1,100	15	5	
Miles	740	-	-	1,000	-	-	17,950	-	-	
Number of entries	325		-	400	₩		7,425	-	-	
Heating:										
Fireplaces						_=	35	-	10	
Stoves	350	15		415	35	35	8,680	625	125	
Circulating heater	5	-	- :	=	-	-	715	10	-	
Pipeless furnace	15	-		5	-	-	315	35	5	
Piped warm air,										
steam, or water						Ì			_	
furnace	_		-	-	-		105		5	

G. REFRIGERATION, LAUNDRY, AND COCKING FACILITIES (Number of Entries)

WHITE					
Owne:			Non-owner		
Have now	Repairs or alterations needed	New instal- lation needed	Have now	Repairs or alterations needed	New instal- lation, needed
2,975 340	135	150 30	1,150 35	125	100
1,700 4,100 90	150 10	25 10	1,050 2,450 10	225	75 -
1,050	45	10	400	5	10
115 1,100 500	40 10	30 100 20	10 300 70	5	25 40 -
5,000	190	35	2,775	230	35
2,930 200 160	120	60 -	1,200	50	40
	1,700 4,100 90 1,050 1,15 1,100 5,000 2,930 200	Have now Repairs or alterations needed 2.975	Owner Have now Repairs or alterations needed 2.975 135 150 30 1.700	Owner Have now Repairs or alterations needed 2.975	Comparing the color of

The second secon

G. REFRIGERATION, LAUNDRY, AND COOKING FACILITIES (Concluded) (Number of entries)

NON-WHITE							- TOTAL FOR STATE		
		Owner			Non-owner				
	Have now	Repairs or alter- ations needed	New in- stal- lation needed	Have now	Repairs or alter- ations needed	New in- stal- lation needed	Have new	Repairs or alter- ations needed	New in- stal- lation needed
Refrigeration: Ice Mechanical Laundry: Where done:	150	20	1	150	. F	10	4,425	280	260 30
Out-of-doors In kitchen In basement In special room	50 350 -	5	5 -	125 400 -	20	45 -	2,925 7,300 100	400 10	150 10
on same level with kitchen	10	-	5	20	•	-	1,480	50	25
Equipment: Fixed tubs Power machine Hand machine Cooking facilities:	5 40 5	-	1 5	10 5	→ 5	5	130 1,450 380	50 10	60 145 20
Wood or coal stoves	375	20		425	35	40	8,575	475	110
Kerasene or gasoline stoves Gas atoves Electric stoves	40	-		50	5		4,220 220 160	175 10	100

H. LANDSCAPING OF HOUSE (Number of Entries)

WHITE										
	Owner Non-owner									
	Have now	Repairs or alterations needed	New instal- lation needed	Have now	Repairs or alterations needed	New instal- lation needed				
Yard: Surface drainage away from house Lawn established Plantings Walks and drives Fences	4,550 3,320 4,300 1,550 1,550	275 100 145 140 120	250 50 120 100 50	2,050 1,250 1,825 470 500	275 75 95 85 50	250 25 70 100 40				

H. LANDSCAPING OF HOUSE (Number of Entries) (Concluded)

			m	OTAL FOR S	ጥ ለ ጥ证				
		Owner		Non-owner			1	OTAL FOR S	THIE
	Have now	Repairs or alter- ations needed	New in- stal- lation needed	Have now	Repairs or alter- ations needed	New in- stal- lation needed	Have now	Repairs or alter- ations needed	New in- stal- lation needed
Yard: Surface drainage									
away from house	300	25	10	250	25	40	7,150	600	550
Lawn established	150	20	5	140	10	20	4,860	205	100
Plantings	250	-		200	5	20	6,575	245	210
Walks and drives		5	10	50	-	10	2,100	230	220
Fences	125	20	5	75	20	30	2,250	210	125

0. Service and a 1412 1312 AMADOLANIAN .H ·, : A. T. 1. Design to the control was a con-tion of the control (control) ••

- 10 - State of Delaware
I. RELATIVE IMPORTANCE OF REPAIRS AND IMPROVEMENTS WANTED
(Number of Entries)

			WHITE				
	Owner			Non-ow	Non-owner		
	\$500	\$250	\$100	\$500	\$250	\$100	
House repairs and improvements: Foundation Exterior walls Roof Chimneys Doors, windows,	250 1,750 1,065 175	150 1,600 825 110	100 1,350 900 85	125 900 470 100	125 800 430 85	80 550 400 60	
screens Porches Interior walls, ceilings, floors	320 650	250 400	230 425	230 400	250 350	275 300	
Additional room Water system Sanitary facilities Lighting system Heating system Bathroom equipment Laundry facilities Cooking facilities Landscaping Electricity:	550 800 230 585 225 700 150 75	885 350 400 150 285 100 375 150 70 50	775 200 200 50 175 75 150 185 45 60	260 225 120 240 80 170 100 50 35	600 200 250 100 100 30 100 75 20	575 150 120 70 35 35 75 100 35 20	
Home plant Power line Built-in-equipment Furnishings	200 275 60 200	60 125 30 100	20 45 40 125	100 185 45 100	20 35 25 45	10 10 50	

I. RELATIVE IMPORTANCE OF REPAIRS AND IMPROVEMENTS WANTED (Number of Entries) (Concluded)

	(Multiple)	I OI EHIOFI	.65)	(COLCI)	aded)		,		
			NON-WHIT	E			TOTAL TOTAL COLUMN		
		Owner			mer		TOTAL FOR STATE		
	\$500	\$250	\$100	\$500	\$250	\$100	\$500	\$250	\$100
House repairs and improvements: Foundation Exterior walls Roof Chimneys Doors, windows, screens Porche Interior walls,	50 100 50 25 45 25	40 100 60 20 25 25	25 75 30 - 15 20	35 85 60 10 45 50	65 100 85 50 75	30 75 100 10 50 40	310	380 2,600 1,400 265 600 855	235 2,050 1,430 155 570 785
ceilings, floors Additional	60	50	25	100	100	7 5	2,020	1,635	1,450
rocm Water system Sanitary facilities Lighting system Heating system Bathroom equipment Laundry facilities Cooking facilities Landscaping Electricity:	55 5 10 45 5 5 -	25 5 5 5 1 1 1 1 1	5 1 1 5 1 1	65 10 20 5 5 5 5 5 5 5	45 5 5 1 5 5 1	25 20 5 1 1 1 1 1 5 5	930 1,040 380 870 315 880 255 130 140	620 660 260 390 130 480 230 90 70	380 340 125 215 110 225 290 85 85
Home plant Power line Built-in-equipment Furnishings	20 20 10	- - 5	1 5 1 5	1 1 5 5	5 - 1 5	- - 5	300 480 110 315	85 160 55 155	20 60 50 185




Questions regarding new construction and availability of local credit sources to finance construction contained on the questionnaire were answered by the occupants as follows:

New Construction and Financing

	WH	ITE	NON-WH	ITE	TOTAL
	Owner	Non-owner	Owner	Non-owner	FOR STATE
Number of persons reporting contemplated construction of new house within next 3 years Number of rooms to be constructed Number of entries Estimated expenditure Number of entries	30 140 30 \$70,200 20	20 . 60 20 \$19,800 10	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5 40 5 \$11,700 5	55 240 55 \$101,700 35
Value of repairs or improvements made on the present house during the last 3 yrs: Less than \$100 \$100 to \$499 \$500 and over	1,500 740 280	1,000 300 50	80 10 5	100 10 5	2,680 1,060 340
Expenditure for repairs or improvements contemplated within next 12 months (total amount) Number of entries	\$106,000	\$38,600 350	\$2,200 40	\$1,300 20	\$148,100 1,240
Number of persons reporting that money is available from local credit sources to finance house construction, repairs, or improvements	1,325	600	10	60	1,995
Number of persons interested in borrowing money to finance construction, repairs, or improvements provided interest rate is satisfactory and repayments can be distributed over a period of 10 years. Not interested Total sum desired Number of entries	630 3,900 \$264,400 550	220 1,800 \$83,300 150	40 175 \$27,500 40	20 230 \$10,300 20	910 6,105 \$385,500 760

These are all preliminary data, subject to revision before publication.





U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



WASHINGTON, D. C.

Release - Immediate

:issued.

May 17, 1934.

FARM HOUSING SURVEY

(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration:
project, carried out by the U.S. Department of Agriculture and:
the State Agricultural Extension Services. The object is to:
provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the:
country are being covered by the investigators. This report:
on the State of Nevada is the fifth State Summary to be

PRELIMINARY REPORT FOR THE STATE OF NEVADA (Subject to later revision)

The Farm Housing Survey covered approximately ten per cent of the counties in each State except New York and Pennsylvania. Two of the seventeen counties in Nevada, Churchill and Washoe, were surveyed. Reports on 1056 farm houses in these counties have been tabulated. Of this number 1048 farm houses were owned or occupied by white occupants and 8 farm houses were owned or occupied by non-white occupants.

In each State the counties to be surveyed were selected as representative of typical farming areas, in order that the results of the surveyed counties might be projected over the whole State by applying appropriate multiplying factors. The number of farms in each area as reported in the 1930 Agricultural Census has been used as the basis of this projection.

Since the housing conditions in the two counties are considered typical of the rural housing conditions of the entire State of Nevada, appropriate multiplying factors were derived by dividing the number of farms in each county into the

2603-34


number of farms of its typical farm area as reported for the year 1929 in the Census of Agriculture, 1930. This method was applied to each of the two classifications of tenure (owners and non-owners) as well as to the number of farms. The data were not separated between white and non-white occupants. The factors were applied to each item included in the survey except those covering number of farms and acreage.

The figures for these items, on number of farms and acreage, were taken directly from the Census of Agriculture, 1930, because it was found that the number of acres per farm in the surveyed counties was substantially less than for some of the counties of Nevada. The figures taken from the Agricultural Census were those on Tôtal Acres in the Farm, Acres of Crop Land Harvosted, and Acres of Plowable Pasture Land. The figures for acres tillable are probably somewhat low as the total of 494,307 acres of crop land (as against 397,504 acres of crop land harvested) and 78,111 acres of plowable pasture land, or a total of 572,418 acres of tillable land, were reported in the Census of Agriculture, making an average of 166 acres of tillable land per farm. However, because the figures on Total Crop Land were not available in the classification of tenure used in the Farm Housing Survey, only those on Crop Land Harvested were included in this summary.

There were 3,442 farms in Nevada in 1929, of which 3,222 were reported to have a total value of farm dwellings of \$5,588,740. The farm population in Nevada was 16,441 in 1929.

Section A							
	Owner	Non-owner	TOTAL FOR STATE				
Total number of farm houses	2,400	1,000	3,400				
Total acres in farm*	2,156,490	. 1,924,416	4,080,906				
Number of entries*	2,770	672	3,442				
Average acres per farm*	779	2,864	1,186				
Total acres of crop land har-							
vested and of plowable pasture							
land*	317,697	157,918	475,615				
Number of entries*	2,770	672	3,442				
Average acres tillable per farm	115	235	138				

*Census of Agriculture, 1930



State of Nevada

B. HOUSE - GENERAL INFORMATION

	 		
	Owner	Non-owner	TOTAL FOR STATE
Kind of house			
Log	20		20
Earth	40	30	70
Frame			
Unpainted	830	390	1,220
Painted	1,230	510	1,740
Stucco	80	20	100
Brick	100	20	120
Stone	20	10	30
Concrete	30	20	100
Age of house			
Under 10 years	520	200	720
10 to 24 years	1,130	410	1,540
25 to 49 years	520	270	790
50 and over years	230	120	350
One story house	2,000	775	2,775
kore than 1 story	400	225	625
Total number of rooms	11,850	4,675	16,525
Number of entries	2,375	1,000	3,375
Average number of rooms			
per house	5.0	4.7	4.9
Total number of rooms not			
in use at any time of year	410	470	880
Number of entries	130	1 50	280
Total number of regular			:
occupants	9,050	3,700	12,750
Number of entries	2,350	975	3,325
Average number of			
occupants per house	3.9	3.8	3.8
Average number of			
occupants per room	0.3	0.8	0.8




C. CONDITION OF FOUSE

	O an ars									
	F	resent Con	dition	Repairs or	Replacement					
	Good	Fair	Poor	alterations needed	or new in- stallation needed					
Foundation	1.075	5 7 5	650	400	600					
Walls, exterior	1,200	800	400	5 75	250					
Roof	1,150	ഭറാ	450	675	315					
Chimneys	1,625	450	325	175	300					
Doors and windows	1,325	700	375	525	275					
Screens	1,100	625	475	475	525					
Faint, exterior	550	500	775	4 7 5	1,000					
Interior walls and ceiling	975	925	500	775	350					
Floors	1,175	700	525	500	375					
Stairs	450	100	75	50	50					
Insulation	1,250	350	500	225	500					

		OW_	OWNERS		
	P	resent Con	dition	depairs or	Replacement
	Good	Fair	Poor	alterations needed	or new in- stallation needed
Foundation	300	22 0	400	170	330
Walls, exterior	375	375	250	265	150
Roof	425	300	275	275	185
Chimneys	600	ဥ၁၁	200	100	125
Doors and windows	430	335	235	250	175
Screens	350	250	275	175	325
Paint, exterior	150	225	375	175	450
Interior walls and ceiling	325	350	325	350	225
Floors	375	350	275	250	225
Stairs	150	75	75	25	50
Insulation	450	15 0	250	100	250

	TOTAL FOR STATE									
	P	resent Con	dition	Repairs or	Replacement					
	Good	Fair	Poor	alterations	or new in-					
				necded	stallation					
					needed					
Foundation	1,375	795	1,050	570	930					
Walls, exterior	1,575	1,175	650	840	400					
Roof	1,575	1,100	725	950	500					
Chimneys	2,225	650	525	275	425					
Doors and windows	1,755	1,035	610	775	450					
Screens	1,450	875	750	650	850					
Paint, exterior	7 00	725	1,150	650	1,450					
Interior walls and ceiling	1,300	1,275	825	1,125	575					
Floors	1,550	1,050	800	750	600					
Stairs	600	175	150	75	100					
Insulation	1,700	500	750	325	750					



Of the 1056 farm houses surveyed, complete replacement of 246 farm houses was desired by the occupants.

D. SPACE REQUIREMENTS

	1 -					mon (00470
	0	wner	Non-	owner	TOTAL	FOR STATE
	Have	Additional	Have	Additional	Have	Additional
	now	rooms needed	now	rooms needed	now	rooms needed
Bedrooms	5,650	1,200	2,320	490	7,970	1,690
Number of entries	2,300	780	950	320	3,250	1,100
Living room	1,880	240	610	160	2,490	400
Dining room	1,320	290	460	150	1,780	440
Kitchen	2,300	50	890	20	3,190	70
Work room	430	370	170	160	600	530
Wash room for farm help	120	340	60	150	180	490
Bathrooms	1,050	740	290	310	1,340	1,050
Halls	400	40	180	20	580	60
Basement	680	240	220	90	900	330
Closets	5,470	2,080	1,650	1,050	7,120	3,130
Number of entries	1,860	960	670	410	2,530	1,370
Front or side porch	1,400	450	520	160	1,920	610
Back porch	1,210	475	440	150	1,650	625
Storage space for fresh						
fruits and vegetables	1,670	380	560	300	2,230	580

E. WATER SUPPLY AND SEWAGE DISPOSAL

L. WAIER SUITHI AND DEWARD DISCORD										
	!	Owner		Non-owner .						
	Have	Repairs	New in-		Repairs or	New in-				
	now	or altera-	stalla-	now	alterations	stalla-				
		tions needed	tion		needed	tion				
	1		needed			needed				
Source of water:		•								
Well, drilled or driver	720	30	40	260	10	40				
Well dug or bored	1,280	120	110	460	60	50				
Spring	150	15	10	80	5	- :				
Cistern	20	5	-	-	-	_				
Stream	230	_		130		-				
Water supply for house:										
Carried				•						
Distance (total feet	454,000	-	-	592,000	_					
Number carrying water	980	_	_	490	-	-				
Hand pump in dwelling	230	5	40	7 0	_	10				
Piped, cold	1,200	30	520	390	30	240				
Piped, hot	920	110	620	260	30	280				
Sanitary facilities:	1									
Outdoor toilet (privy)										
Improved	160	5	70	40	-	20				
Unimproved	1,800	_	_	750	-	_				
Indoor:										
Chemical	20	_	10	5	-	-				
Flush	690	20	8 60	200	5	330				
Bathroom fixtures:										
Tub	960	30	890	250		340				
Shower	120	10	530	50		240				
Lavatory Kitchen sink with drain	700	30	875	200	_	325 220				
Disposal of sewage:	1,600	110	550	530	30	220				
Septic tank	350	10	600	75	_	240				
Cesspool	350 360	10 30 5	600 150 50	170	105	240 50 20				
Stream Surface	1,225	5	50	175 575	5	20				



E. WATER SUPPLY AND SEWAGE DISPOSAL (Concluded)

T	OTAL FOR STATE	
Have now	Repairs or altera- tions needed	New installa- tion needed
980	40	80
1,740	180	160
230	20	10
20	5	-
360		
1,046,000	-	
1,470	-	-
300	5	50
1,590	60	760
1,180	140	900
200	5	90
2,550		-
25	_	10
890	25	1,190
1,210	40	1,230
170	15	770
900	40	1,200
2,130	140	770
425	10	840
		200
	10	70
	930 1,740 230 20 360 1,046,000 1,470 300 1,590 1,180 200 2,550 25 890 1,210 170 900 2,130	## ## ## ## ## ## ## ## ## ## ## ## ##

F. LIGHT AND HEAT (Number of Entrics)

		Owner		, N	du-dwift				
	Have	Repairsor	Mew instrl-	Hc. ve	Repairs or	New in-			
	now	alterations	letion meeled		altera-	stalla-			
		noelud	•		tions	tion			
				-	needed	needed			
Lighting:					liceded	needed			
Kerosene or gasoline lamps	660		40	350	_	30			
Acetylene	10	-	-	-	_	-			
Piped gas	20	5	5	-	_	-			
Electric:		_							
Home plant	70	10	30 230	40 600 520	10	150			
Power line Miles	1,650 3,070	30	230	520	20	150			
Number of entries		_		390	_	_			
Heating:	0.00								
Fireplaces	190	10	60	30	_	40			
	1,980	30	80	820	30	40 60			
Circulating heater	260		300	70		1 30			
Pipeless furnace	30	- 5	50	10	-	20			
Piped warm air,									
steam, or water	80	5	חמור	10		70			
furnace	80	2	170	10	i				



F. LIGHT AND HEAT (Concluded)

		TOTAL FOR STATE	E
	Have now	Repairs or alter- ations needed	New installa- tion needed
Lighting:			
Kerosene or			+
gasoline lamps	1,010	-	70
Acetylene	10	-	***
Piped gas	20	5	5
Electric:			
Home plant	110	20	50
Power line	2,250	50	380
Miles	3,590	_	
Number of entries	1,210	-	-
Heating:			
Fireplaces	220	10	100
Stoves	2,800	60	1 40
Circulating heater	330	•	430
Pipeless furnace	40	5	70
Piped warm air, steam,			
or water furnace	90	5	240

G. REFRIGE	RATION	, LAUNDRY,	AND COO	KING	FACILITIE	S (Numb	er of	intrical)		
		Owner			Non-owner			TOTAL FOR STATE		
	Ha ve now	Repairs or alter- ations needed	New in- stalla- tion needed	Have now	Repairs or alter- ations needed	New in- stalla- tion needed	Have	Repairs or alterations	New in- stalla- tion needed	
Refrigeration: Ice Mechanical Lanndry: Where done:	780 210	5 5	150 830	300 50	15 -	70 300	1,08 0 26 0	20 5	220 1,130	
Out-of-doors In kitchen In basement In special	330 1,030 60	30 5	40 20	330 420 10	10 -		1,160 1,450 70	40 5	50 30	
room on same level with kitchen Equipment:	340	20	290	120		100	460	20	390	
Fixed tubs Power machine Hand machine Cooking facili	100 760 50	20 5	350 580 10	50 240 10	5	140 240 5	150 1,000 60	20 10	490 820 15	
Kerosene or	2,250	30	110	8 7 5	30	60	3,125	60	170	
gasoline stoves Gas stoves Electric	200 80	20	20 120	50 5	11	20 50	250 85	20	40 170	
stoves	220	5	210	30	5	100	250	10	310	

H. LANDSCAPING OF HOUSE (Number of Intries)

		Owner			Non-owne	r	TOTAL FOR STATE		
	Have now	or alter- ation's	New in- stalla- tion needed		or alter- ations	New in- stalla- tion needed	now	Repairs or alter- ations needed	New In- stalla- tion needed
Yard: Surface drainage									
away from house	1,920	250	260	680	100	150	2,600	310	410
Lawn established	810	230	920	170	90	470	980	320	1,390
Plantings	1,540	250	770	430	75	4 40	1,970	325	1,210
Walks and drives	620	250	990	160	90	460	780	340	1,450
Tences	1,125	340	1,050	350	130	525	1,475	470	1,575

I. RELATIVE IMPORTANCE OF REPAIRS AND IMPROVEMENTS WANTED

		Owner]	Non-ow	ner	TOT.	TOTAL FOR STATE			
		\$500	\$250	\$100	\$500	\$250	\$100	\$50 0	\$250	\$100	
H	ouse repairs and										
	improvements:					. '					
	Foundation	340	160	150	120	90	80	460	250	230	
	Exterior walls	510	290	230	190	100	70	700	390	300	
	Roof	480	370	300	160	110	80	640	480	380	
	Chimneys	120	60	30	60	40	40	180	100	70	1
	Doors, windows,										
	screens	290	150	120	130	100	60	420	250	180	1
	Porches	460	220	150	130	60	50	590	280	200	-
	Interior walls,										
	cailings, floors	740	470	410	290	200	170	1,030	670	580	
	Additional room	700	360	200	240	150	90	940	510	290	
Wa	ater system	760	430	260	350	220	170	1,110	650	430	1
Şa	anitary facilities	430	140	80	150	80	20	580	220	100	!
	ighting system	160	70	60	90	40	10	250	110	70	
He	eating system	170	70	40	40	10	10	210	60	50	1
BE	throom equipment	880	440	240	350	180	100	1,230	520	300	
La	undry facilities	200	100	90	90	50	30	290	150	120	:
	ooking facilities	100	1 50	30	40	20	5	140	70	35	3
L	undscaping	150	70	40	30	5	5	180	7 5	45	:
E]	lectricity:										
	Home plant	30	5	-	20	5	-	50	10	-	-
	Power line	200	80	40	90	50	20	290	130	60	
Bı	uilt-in-equipment	160	50	30	40	40	10	2 00	90	40	
Fu	urnishings	400	170	150	160	70	70	560	240	220	_ i

* to with more some office.

Questions regarding new construction and availability of local credit sources to finance construction contained on the questionnaire were answered by the occupants as follows:

New Construction and Financing

	Owner	Non-owner	TOTAL FOR STATE
Number of persons reporting contemplated construction of new house within next			
3 years	270	50	320
Weaber of rooms to be constructed	1,030	170	1,200
Number of entries	190	40	230
Estimated expenditure	\$ 527,000	\$77,000	\$604,000
Number of entries	190	40	230
Value of repairs or improvements made on the present house during the last 3 yrs:			
Less than \$100	830	300	1,130
\$100 to \$499	410	100	510
\$500 and over	200	40	240
	200	40	2 10
Expenditure for repairs or improvements contemplated within next 12 months			
(total amount)	\$140,000	\$17,000	\$157,000
Number of entrics	390	110	500
Number of persons reporting that money is available from local credit sources to finance house construction, repairs or			
improvements	190	40	230
Number of persons interested in borrowing money to finance construction, repairs, improvements provided interest rate is satisfactory and repayments can be dis-	ידס		
tributed over a period of 10 years.	800	220	1,020
Not interested	1,240	520	1,760
Total sum desired	\$991,000	\$218,000	\$1,209,000
Number of entries	790	200	990

These are all preliminary data, subject to revision before publication.



INFORMATION FOR THE PRESS



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE



Release - Immediate

WASHINGTON, D. C

May 31, 1934

FARM HOUSING SURVEY

(A Civil Works Administration Project)

PAMPILET CLIEFTICE

The Farm Housing Survey is a Civil Works Administration project, carried out by the U.S. Department of Agriculture and SEP 4-1934 the State Agricultural Extension Services. The object is to provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the country are being covered by the investigators. This repertease of Agricultural Economic on the State of New Mexico is the sixth State Summary to be issued.

PRELIMINARY REPORT FOR THE STATE OF NEW MEXICO (Subject to later revision)

The Farm Housing Survey covers approximately ten per cent of the counties in each State except New York and Pennsylvania. Six counties in New Mexico were partially surveyed. The surveyed counties are Chaves, Curry, Eddy, Mora, Quay, and San Miguel. Reports on 5143 farm houses in these counties have been tabulated.

In each State the counties to be surveyed were selected as representative of typical famin farming areas in order that the results of the surveyed counties might be projected over the whole State by applying appropriate multiplying factors. The number of farms in each area as reported in the Agricultural Census of 1930 is used as the basis of this projection.

Since the housing conditions in the six counties surveyed in New Mexico were considered typical of the rural housing conditions in the areas of the whole State, appropriate multiplying factors were derived by dividing the number of farm houses covered by the survey of these counties into the number of farms in the representative areas as reported for the year 1929 in the Census of Agriculture, 1930. This method was applied to each of the classifications of tenure (owner and non-owner) as well as to the total number of farms. The factors were applied to each item included in the survey except those covering number of farms and acreage.

The figures for these items, on number of farms and acreage, were taken directly from the Census of Agriculture of 1930, because it was found that the number of acres per farm in these counties were substantially less than for the other two counties in the State. The figures taken from the Agricultural Census were these on <u>Total Acres in the Farm, Acres of Crop Land</u>, <u>Harvested</u>, and <u>Acres of Plowable Pasture Land</u>. These figures are probably somewhat low, as a total of 1,799,190 acres of crop land (as against 1,493,998 acres crop land <u>harvested</u>) and 3,198,497 acres

2710-34

The state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the s

and the state of t

of plowable pasture land, or a total of 4,997,687 acres of tillable land, were reported in the Census of Agriculture, making an average of 159 acres of tillable land per farm. However, because the figures on Total Crop Land were not available in the classifications of tenure used in the Farm Housing Survey, only those on Crop Land Harvested were included in this surmary.

Mora and San Miguel, in the northern part of New Mexico, were selected as typical Spanish-American counties. These counties are in a rather mountainous section of the State. They are characterized by a stable Spanish-American culture and general farming. Quay and Curry were selected as typical of the dry land ares. Chaves and Eddy Counties were selected as typical of the irrigated area located in the southeastern part of New Mexico.

The survey shows that water is carried to the majority of farm houses. The distance which the water is carried varies from a few feet to twelve miles, as in some instances no water is available on the farm and must be hauled from adjoining farms, springs, or nearby streams. Of the 5143 farm houses surveyed, complete replacement of 818 farm houses was desired by the occupants.

There were 31,404 farms in New Mexico in 1929, of which 27,771 were reported to have a total value of farm dwellings of \$16,506,597. The farm population in New Mexico was 158,631 in 1929.

SECTION A

	Owner	Non-owner	Total for State
Total number of farm houses	25,300	6,600	31,900
Total acres in farm *	21,856,825	8,965,209	30,822,034
Number of farms *	24,740	6,664	31,404
Average acres per farm *	883	1,345	981
Total acres of cropland harvested and of plowable pasture land '	3,400,459	1,292,036	4,692,495
Number of farms; *	24,740	6,664	31,404
Average acres tillable per farm *	137	194	149

^{*} Census of Agriculture, 1930

B. HOUSE - GENERAL INFORMATION

	Owner	Non-owner	Total for State
Kind of house (number)			and the second s
Log	2,900	300 900	3,200 8,600
Earth Frame	7,700	900	8,000
Unpainted	4,100	2,900	7,000
Painted Stucco	5,000 1,700	1,650 400	6,650 2,100
Brick	130	30	160
Stone	3,350	320	3,670
Concrete Age of house (number)	430	100	520
Under 10 years	6,400	1,200	7,600
10 to 24 years	9,200	3,100	12,300 9,100
25 to 49 years 50 and over years	7,000 2,700	2,100 200	2,900
One story house (number)	22,400	6,000	28,400
More than 1 story (number) Total number of rooms	2,900 102,000	600 24,000	3,500 126,000
Number of entries	25,300	6,600	31,900
Average number of rooms per house	4.0	3.6	3₊9
Total number of rooms not in use at any time of year	1,275	700	1,975
Number of entries	600	300	900
Total number of regular occupants	118,800	33,200	152,000
Number of entries Average number of occupants	25,250	6,650	31,900
per house	4.7	5.0	4.8
Average number of occupants per room	1.2	1.4	1.2

C. CONDITION OF HOUSE

Owner (Number of Entries)									
	Pres	sent Condition	Repairs or	Replacement					
	Good	Fair	Poor	alterations needed	new instal- lation needed				
Foundation Walls, exterior Roof Chimneys Doors and windows Screens Paint, exterior Interior walls and ceiling	13,900 12,200 9,100 9,600 9,700 6,500 4,500 7,700	5,000 8,200 6,800 3,300 8,600 5,800 6,300	4,300 4,900 9,400 3,500 7,000 7,500 12,200 7,500	3,300 5,800 6,400 1,700 6,700 3,500 4,100 7,400	3,100 2,300 6,500 4,100 4,100 10,500 9,100 4,200				
Floors Stairs Insulation	8,750 2,100 7,700	8,950 560 4,300	7,600 490 3,300	5,800 350 2,400	5,200 360 2,400				

C. CONDITION OF HOUSE (Continued) State of New Mexico

,	Non-owner (Number of Entries)									
	Pr	esent Conditio	Repairs or	Replacement or						
	Good	Fair	Poor	alterations needed	new instal- lation needed					
Foundation	2,300	1,300	2,000	1,300	1,400					
Walls, exterior Roof	2,000	2,300	2,300	2,100	800					
Chimneys	1,900 2,400	1,800	2,900 1,300	2,000 700	1,600 1,600					
Doors and windows	1,600	2,000	3,000	2,400	1,400					
Screens	1,300	1,400	2,600	1,300	3,300					
Paint, exterior	700	1,200	3,200	1,000	2,800					
Interior walls and ceiling	1,100	2,300	3,200	2,800	1,400					
Floors	1,550	2,350	2,700	1,900	1,400					
Stairs	300	160	140	110	80					
Insulation	1,400	1,200	1,500	1,000	1,200					

C. CONDITION OF HOUSE (Concluded)

Total for State (Number of Entries)									
	Pre	Repairs or	Replacement or						
	Good	Fair	Poor	alterations needed	new instal- lation needed				
Foundation Walls, exterior Roof Chimneys Doors and windows Screens Paint, exterior Interior walls and ceiling Floors Stairs Insulation	16,200 14,200 11,000 12,000 11,300 7,800 5,200 8,800 10,300 2,400 9,100	6,300 10,500 8,600 4,400 10,600 7,200 7,500 12,400 11,300 720 5,500	6,300 7,200 12,300 4,800 10,000 10,100 15,400 10,700 10,300 630 4,800	4,600 7,900 8,400 2,400 9,100 4,800 5,100 10,200 7,700 460 3,400	4,500 3,100 8,100 5,700 5,500 13,800 11,900 5,600 6,600 440 3,600				

D. SPACE REQUIREMENTS *

The state of the s									
	Ow	mer	Non	-owner	Total for State				
	Have	Additional	Have	Additional	Have	Additional			
1	now	room nooded	work	room needed	now .	room needed			
Bedrooms **	46,800	10,100	10,200	4,700	57,000	14,800			
Number of entries	23,400	7,200	5.400	3,000	28,800	10,200			
Living room	14,500	2,000	4,900	600	19,400	2,600			
Dining room	7,500	1,900	1,400	7 00	8,900	2,600			
Kitchen	23,700	6 7 0	6,000	400	29.700	1,070			
Work room	3,600	1,600	600	600	4,200	2,200			
Wash room for									
farm help	770	630	160	120	930	750			
Bathrooms	3,100	3,500	450	1,200	3,550	4,700			
Halls	3,000	7 5	400	25	3,400	100			
Basement	2,400	750	500	100	2,900	850			
Closets ***	18,600	14,000	4,000	6,100	22,600	20,100			
Number of entries	9,100	7,900	2,200	3,100	11,300	11,000			
Front or side porch	9,400	2,700	2,300	700	11,700	3,400			
Back porch	5,500	1,700	1,400	700	6 ,9 00	2,400			
Storage space for fresh									
_fruits and vegetables	7,400	3,400	1,700	1,100	9,100	4,500			

^{*} Number of entries except where otherwise indicated
** Number of bedrooms
*** Number of closets



5 - State of New Mexico
E. WATER SUPPLY AND SEWAGE DISPOSAL*

E. WATER SUPPLY AND SEWAGE DISPOSAL*									
		Owner		Non-owner					
	Have now	Repairs or alterations needed	New instal- lation needed	Have now	Repairs or alterations needed	New instal- lation needed			
Source of water: Well, drilled or driven Well dug or bored Spring Cistern Stream Water supply for house: Carried	10,000 4,100 1,600 3,000 6,500	900 900 170 325	1,000 250 15 400	4,100 500 250 600 700	400 100 20 100	370 50 15 175			
Distance (total feet) Number carrying water Hand pump in dwelling Piped, cold Piped, hot Sanitary facilities: Outdoor toilet (privy):	19,900 230 4,900 1,700	45 160 150	230 2,300 1,500	9,420,000 5,700 70 900 200	5 60 20	- - 50 - 860 - 500			
Improved Unimproved Indoor:	1,150 19,800	100	900 -	150 5,600	⊒ : \ ⊒ "	600 -			
Chemical Flush Bathroom fixtures:	2,200	10 60	5 2,400	5 300	5 15	800			
Tub Shower Lavatory Kitchen sink with drain Disposal of sewage:	3,100 325 2,100 4,400	130 5 60 150	2,800 525 2,100 2,800	450 50 300 800	10 10 50	850 225 625 1,000			
Septic tank Cesspool Stream Surface	350 3,000 120 4,100	10 160	425 2,500 20	25 500 20 1.800	20 10 5 -	200 800 5			

E. WATER SUPPLY AND SEWAGE DISPOSAL* (Concluded).

		Total for State	
	Have now	Repairs or alter- ations needed	New installation needed
Source of water: Well, drilled or driven Well dug or bored Spring Cistern Stream Water supply for house:	14,100 4,600 1,850 3,600 7,200	1,300 1,000 190 425	1,300 300 30 575
Carried Distance (total feet) Number carrying water Hand pump in dwelling Piped, cold Piped, hot Sanitary facilities:	39,840,000 25,600 300 5,800 1,900	50 220 170	280 3,160 2,000
Outdoor toilet (privy): Improved Unimproved Indoor:	1,300 25,400	100	1,500
Chemical Flush Bathroom fixtures:	20 2,500	15 75	5 3 , 200
Tub Shower Lavatery Kitchen sink with drain Disposal of sewage:	3,550 375 2,400 5,200	140 5 7 0 200	3,650 750 2,725 3,800
Septic tank Cesspool Stream Surface * Number of entries except when	375 3,500 140 5,900	30 170 5	625 3,300 25

Number of entries except where etherwise indicated.



F. LIGHT AND HEAT (Number of Entries)

		Owner		Non-owner		Total for State			
	Have now	or alter- ations	New in- stal- lation needed	Have now			now	Repairs or alter- ations needed	New in- stal- lation needed
Lighting: Kerosene or						222	om 400		3 650
gasoline lamps Acetylene Piped gas Electric:	21,200 825 100	100 20	1,450 200 50	6,200 75 25	25 5	200 125 10	27,400 900 125	125	1,650 325 60
Home plant Power line Miles	900 2,550 345,000	80 25	375 420 -	100 350 58,800	10 15 -	125 110 -	1,000 2,900 403800	40	500 530
Number of entries Heating: Fireplaces	20,000 3,500	200	190	5,750 375	40	10	25,750 3,875	240	200
Stoves Circulating heater Pipeless furnace Piped warm air,	19,500 1,000 100	6 75 25 15	1,175 350 50	5,400	75 10	175 175 5	1,125 100	25	1,350 525 55
steam, or water furnace	270	30	50	30	5	10	300	35	60

G. REFRIGERATION, LAUNDRY, AND COOKING FACILITIES (Number of Entries)


		^		3.7			Total for State			
		Owner			on-owner					
	ovsH woa	or alterations	New in- stal- lation needed	Have now	Repairs or alter- ations needed	New in- stal- lation needed	Have now	or alter- ations	New in- stal- lation needed	
Refrigeration:	4,500	50	350	900	15	150	5,400	65	500	
Mechanical Laundry:	1,100	25	1,200	100	5	450	1,200	30	1,650	
Where done:	C 200			0.000			0.700			
In kitchen	6,200 15,600	40	450	2,900 3,100	10	75	9,100	50	525	
In basement In special room on same level	175	~	25	25		25	200	-	50	
with kitchen Equipment:	2,700	40	7 00	500	10	300	3,200	50	1,000	
Fixed tubs Power machine	1,350 4,100	25 150	1,000 1,750	100 700	25 25	400 750	1,450 4,800	50 175	1,400	
Hand machine Cooking facilities: Wood or coal	850	25	450	150	-	100	1,000	25	550	
stoves Kerosene or gas-	21,100	1,600	1,350	5,100	200	250	26,200	1,800	1,600	
oline stoves	4,800		175	1,900	25	75	6,700	175	250	
Gas stoves Electric stoves	675 610		20 40	75 40	-	5 10	750 650	-	25 50	

H. LANDSCAPING OF HOUSE (Number of Entries)

		Owner		Non-owner			Total for State		
	Have now	Repairs or alter- ations needed	New in- stal- lation needed	Have now	Repairs or alter- ations needed	New in- stal- lation necded	Have now	Repairs or alter- ations needed	New in- stal- lation needed
Yard: Surface drainage away from house Lawn established Plantings Walks and drives Fences	19,600 4,600 8,700	1,900 750 800	900 1,500 5,300 1,750 3,400	4,200 650 1,600 500 1,950	750 200 250 200 750	750 900 1,100 850 1,150	23,800 5,250 10,300 3,300 13,850	2,650 950 1,050 1,000 4,150	1,650 2,400 6,400 2,600 4,550

I. RELATIVE IMPORTANCE OF REPAIRS AND IMPROVEMENTS WANTED (Number of Entries)

		Owner		ſ	Non-owne	ŗ	Tot	al for	State
	\$500	\$250	\$100	\$500	\$250	\$100	\$500	\$250	\$100
House repairs and									
improvements:									
Foundation	1,400	1,100	900	400	300	250	1,800	1,400	1,150
Exterior walls	3,400	3,200	2,600	750	700	500	4,150	3,900	3,100
Roof	6,050	6,575	7,500	850	875	1,000	6,900	7,450	8,500
Chimneys	975	975	1,350	275	175	150	1,250	1,150	1,500
Doors, windows,						Ì			
screens	4,700	4,700	4,550	950	950	950	5,650	5,650	5,500
Porches	2,400	2,100	1,700	400	300	200	2,800	2,400	1,900
Interior walls,									
ceilings,						}			
floors	6,300	5,900	4,800	1,200	1,200	1,200	7,500	7,100	6,000
Additional									
room	5,400	3,600	2,300	1,200	700	400	6,600	4,300	2,700
Water system	4,800	3,400	2,000	1,000	700	400	5,800	4,100	2,400
Sanitary facilities	1,600	900	400	300	100	100	1,900	1,000	500
Lighting system	650	280	200	100	40	40	7 50	320	240
Heating system	430	240	150	7 0	20	10	500	260	160
Bathroom equipment	2,900	1,500	640	650	300	120	3,550	1,800	760
Laundry facilities	700	450	25 0	280	200	100	980	650	350
Cooking facilities	1,050	800	500	100	100	100	1,150	900	600
Landscaping	1,400	7 50	475	200	100	75	1,600	850	550
Electricity:									
Home plant	200	7 0	50	50	5		250	75	50
Power line	300	115	60	50	35	20	350	150	80
Built-in-equipment	1,400	875	650	200	150	100	1,600	1,025	750
Furnishings	2,600	1,900	870	275	200	230	2,875	2,100	1,100



Questions regarding new construction and availability of local credit sources to finance construction contained on the questionnaire were answered by the occupants as follows:

NEW CONSTRUCTION AND FINANCING

	Owner	Non-owner	Total for State
	Owner	Mon-owner.	100811 101 20806
Number of persons reporting contemplated construction of new house within next 3 years	4,300	700	5,000
Number of rooms to be constructed	14,500	2,300	16,800
Number of entries	4,100	600	4,700
Estimated expenditure	\$2,683,000	\$502,000	\$3,185,000
Number of entries	3,900	600	4,500
Value of repairs or improvements made on the prosent house during the last 3 yrs: Less than \$100	9,800	2,100	11,900
\$100 to \$499	3,600	400	4,000
\$500 and over	700	100	800
Expenditure for repairs or improvements contemplated within next 12 months (total amount)	\$1, 450,000	\$402,000	\$1,852,000
Number of entries	7,400	800	8,200
Number of persons reporting that money is available from local credit sources to finance house construction, repairs, or improvements	900	150	1,050
Number of persons interested in borrowing money to finance construction, repairs, or improvements provided interest rate is satisfactory and repayments can be distributed over a period of 10 years.	11,900	1,400	13,300
Not interested	10,300	3,800	14,100
Total sum desired	\$5,067,000	\$945,000	\$6,012,000
Number of entries	11,500	1,400	12,900

These are all preliminary data, subject to revision before publication.

t, ' 44



U. S. DEPARTMENT OF AGRICULTURE OFFICE OF INFORMATION PRESS SERVICE

WASHINGTON, D. C.



Release - Immediate

June 9, 1934

1 80 1 61 m. 1

FARM HOUSING SURVEY
(A Civil Works Administration Project)

The Farm Housing Survey is a Civil Works Administration project, carried out by the U.S. Department of Agriculture and the State Agricultural Extension Services. The object is to provide the basic information necessary for a program of improvement for farm homes. About 300 counties throughout the country are being covered by the investigators. This report on the State of Arkansas is the seventh State Summary to be issued.

PRELIMINARY REPORT FOR THE STATE OF ARKANSAS (Subject to later revision)

The Farm Housing Survey eovers approximately ten per cent of the counties in each State, except New York and Pennsylvania. Seven of the 75 counties of Arkansas were surveyed: Arkansas, Drew, Faulkner, Hempstead, Izard, Phillips, and Washington. Reports on 20,365 farm houses in these counties have been tabulated.

In each State the counties to be surveyed were selected as representative of typical farm areas in order that the results of the surveyed counties might be projected over the whole State by applying appropriate multiplying factors.

Washington County was selected as representative of the morthwestern limestone area. Although this is a typical fruit county, seven cash crops are also produced. These crops are produced in the majority of eounties included in the limestone area. The Ozark National Forest Reservation is within this section. The principal crops in Arkansas County are rice and cotton. Drew County was selected as typical of the large and small cotton plantations with some truck farms and timber land. Izard County was selected to represent the hill counties. Field workers had to go on horse back to make many of the surveys. It has only one power line within its borders. Cotton, fruit, and truck farms are found in Hempstead County. Phillips County represents the Delta country and has many large plantations. All counties in the State, except Benton, Carroll, Washington, and Madison, produce cotton. The survey shows only two negro families in Washington County. In Drew, Hempstead, and Phillips Counties the negro farm population is larger than the white farm population.

The weighted data show 70 per cent unpainted frame houses, 25 per cent painted frame houses, 4 per cent log houses and 1 per cent earth, brick, stone and concrete houses in the State of Arkansas. Twenty per cent of the houses are under 10 years of age, 37 per cent are between 10 and 24 years of age, 33 per cent are between 25 and 49 years of age, and 10 per cent are 50 years of age or over. Ninety-three and four-tenths per cent of the houses have only one story and 6.6 per cent are of more than one story. An average of 3.9 rooms per house and 4.7 persons per house, or 1.2 persons per room, is shown by the survey, indicating a condition of overcrowding.



In approximately 95 per cent of the houses the water supply is earried from outside. Two per cent of the homes have hand pumps in the dwelling, 3 per cent have running water in the dwelling, 42 per cent have drilled or driven wells, 32 per cent have dug or bored wells, 9 per cent have springs, 11 per cent have eisterm and water is carried from streams into 1 per cent of the dwellings.

Structural repairs to the present houses come first in indicated needs with 50 per cent of the foundations shown as poor, 46 per cent of the interior walls shown as poor, 44 per cent of the roofs shown as poor, 39 per cent of the doors and windows shown as poor, and 34 per cent of the exterior walls, of the chimneys, and of the floors shown as poor.

Replacements, renewals, or new installation and repairs or alterations are needed in the following percentages:

	Percentage of houses in which replacement or new installation is needed	Percentage of houses in which repairs or alterations are needed
	76	%
Foundation	29	34
Walls, exterior	17	41
Roof	26	34
Chimneys	20	28
Doors and windows	20	41
Sereens	42	21
Interior walls and eciling	27	39
Floors	17	38

Additional room, especially sleeping space and storage space for elothes and linen as well as for fresh fruits and vegetables, is badly needed.

There were 242,334 farms in Arkansas in 1929, of which 219,381 were reported to have a total value of farm dwellings of \$94,901,462. The farm population was 1,119,464 in 1929.

SECTION A NON-WHITE WHITE TOTAL FOR STATE Owner Non-owner Omner Non-owner Total number of farm houses 75,000 85,300 10,500 63,200 234,000 Total acres in farm* 16,052,962 8,285,121 5,280,079 705,156 1,782,606 Number of farms* 77,554 85,201 11,455 63,124 242,334 Average acres per farm* 66 107 62 62 26 Total aeres of erop land harvester and plowable pasture land in farm* 3,229,467 2,754,702 325,729 1,441,897 7,751,795 Number of farms* 77,554 242,334 85,201 11,455 68,124 Average acres till-42 28 able per farm'

*Total acreage and tillable acreage were taken directly from the Census of Agriculture, 1930, because the average number of acres per farm in the surveyed counties was substantially different from the average of the remaining counties in the State.



-3B. HOUSE - GENERAL INFORMATION

State of Arkansas

Under 10 years 18,100 17,700 2,200 10,700 48,700 10 to 24 years 24,500 31,300 4,600 26,400 86,800 25 to 49 years 23,100 27,100 3,200 22,800 76,200 50 and over years 9,300 9,200 500 3,300 22,300 One story house (number) 67,000 79,400 10,300 61,800 218,500 More than 1 story (number) 8,000 5,900 200 1,400 15,500							
Non-owner Non-owner Non-owner State		Whi	to	Non-w	hite		
Log		Owner	Non-owner	Owner	Non-owner		
Log	Kind of house (number)						
Frame Unpainted 36,900 60,900 8,700 57,200 163,700 Painted 32,800 19,800 1,400 4,900 58,900 Stucco 125 200 25 - 550 Stone 400 150 - 550 Stone Concrete 50 - 25 - 550 Age of house (number) Under 10 years 18,100 17,700 2,200 10,700 48,700 10 to 24 years 24,500 31,300 4,600 26,400 86,800 25 to 49 years 23,100 27,100 3,200 22,800 76,200 50 and over years 9,300 9,200 500 3,300 22,300 One story house (number) 67,000 79,400 10,300 61,800 218,500 More than 1 story (number) 8,000 5,900 200 1,400 15,500 More than 1 story (number) 75,000 85,300 10,500 63,200 234,000 Average number of rooms not in use at any time of year 4,600 10,400 400 4,800 20,200 Total number of regular occupants 75,000 85,300 10,500 83,200 234,000 Average number of regular occupants 75,000 85,300 10,500 63,200 234,000 Average number of rooms not in use at any time of year 2,800 5,300 300 3,100 12,000 Average number of regular occupants 75,000 85,300 10,500 63,200 234,000 Average number of regular occupants per house 4.5 4.8 4.8 4.8 4.6 4.7		4,200	4,175	350	1,100	9,825	
Unpainted 36,900 60,900 8,700 57,200 163,700 Painted 32,800 19,800 1,400 4,900 58,900 32,800 125 200 25 - 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 350 35	Earth	75	25	-	-	100	
Painted 32,800 19,800 1,400 4,900 58,900	Frame						
Stuceo 125 200 25 - 350 Brick 400 150 - - 550 Stone 450 50 - - 500 Concrete 50 - 25 - 75 Age of house (number) 18,100 17,700 2,200 10,700 48,700 10 to 24 years 24,500 31,300 4,600 26,400 86,800 25 to 49 years 23,100 27,100 3,200 22,800 76,200 50 and over years 9,300 9,200 500 3,300 22,300 One story house (number) 67,000 79,400 10,300 61,800 218,500 More than 1 story (number) 8,000 5,900 200 1,400 15,500 More than 1 story (number) 8,000 324,100 41,600 211,200 914,300 Number of entries 75,000 85,300 10,500 63,200 234,000 Average number of entries 2,8	Unpainted	36,900	60,900	8,700	57,200	163,700	
Stucco	Painted	32,800	19,800	1,400	4,900	58,900	
Stone 450 50 - 500 - 75	Stucco		200	1	_	350	
Concrete 50 - 25 - 75 Age of house (number) 18,100 17,700 2,200 10,700 48,700 10 to 24 years 24,500 31,300 4,600 26,400 86,800 25 to 49 years 23,100 27,100 3,200 22,800 76,200 50 and over years 9,300 9,200 500 3,300 22,300 One story house (number) 67,000 79,400 10,300 61,800 218,500 More than 1 story (number) 8,000 5,900 200 1,400 218,500 More than 1 story (number) 8,000 5,900 200 1,400 15,500 More than 1 story (number) 8,000 5,900 200 1,400 15,500 Mumber of entries 75,000 85,300 10,500 63,200 234,000 Average number of entries 4,600 10,400 400 4,800 20,200 Number of entries 36,700 413,300 50,100 289,600	Brick	400	1 50	-	_	550	
Age of house (number) 18,100 17,700 2,200 10,700 48,700 10 to 24 years 24,500 31,300 4,600 26,400 86,800 25 to 49 years 23,100 27,100 3,200 22,800 76,200 50 and over years 9,300 9,200 500 3,300 22,300 One story house (number) 67,000 79,400 10,300 61,800 218,500 More than 1 story (number) 8,000 5,900 200 1,400 218,500 More than 1 story (number) 8,000 5,900 200 1,400 15,500 Mumber of centries 75,000 85,300 10,500 63,200 234,000 Average number of rooms not in use at any time of year 4,600 10,400 400 4,800 20,200 Number of entries 2,800 5,300 300 3,100 12,000 Total number of regular occupants 336,700 413,300 50,100 289,600 1,089,700 Number of entries 75,000	Stone	450	50	-	-	500 ⁻	
Under 10 years 18,100 17,700 2,200 10,700 48,700 10 to 24 years 24,500 31,300 4,600 26,400 86,800 25 to 49 years 23,100 27,100 3,200 22,800 76,200 50 and over years 9,300 9,200 500 3,300 22,300 22,300 20,200 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,000 20,0	Concrete	50	_	25	-	75	
10 to 24 years 24,500 31,300 4,600 26,400 86,800 25 to 49 years 9,300 9,200 500 3,300 22,300 22,300 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 20,200 2	Age of house (number)						
25 to 49 years 23,100 27,100 3,200 22,800 76,200 50 and over years 9,300 9,200 500 3,300 22,300 One story house (number) 67,000 79,400 10,300 61,800 218,500 More than 1 story (number) 8,000 5,900 200 1,400 15,500 Total number of rooms 337,400 324,100 41,600 211,200 914,300 Average number of 4.5 3.8 4.0 3.3 3.9 Total number of rooms 4,600 10,400 400 4,800 20,200 Number of entries 2,800 5,300 300 3,100 12,000 Total number of regular 336,700 413,300 50,100 289,600 1,089,700 Number of entries 35,300 40,500 63,200 234,000 Average number of occupants per house 4.5 4.8 4.8 4.6 Average number of 4.5 4.8 4.8 4.6	Under 10 years	18,100	17,700	2,200	10,700	48,700	
25 to 49 years 50 and over years 9,300 9,200 500 3,300 22,300	10 to 24 years	24,500	· ·		26,400	86,800	
One story house (number) 67,000 79,400 10,300 61,800 218,500 More than 1 story (number) 8,000 5,900 200 1,400 15,500 Total number of rooms 337,400 324,100 41,600 211,200 914,300 Number of entries 75,000 85,300 10,500 63,200 234,000 Average number of rooms 4.5 3.8 4.0 3.3 3.9 Total number of rooms 4,600 10,400 400 4,800 20,200 Number of entries 2,800 5,300 300 3,100 12,000 Total number of regular occupants 336,700 413,300 50,100 289,600 1,089,700 Number of entries 75,000 85,300 10,500 63,200 234,000 Average number of occupants per house 4.5 4.8 4.8 4.6 4.7 Average number of 4.5 4.8 4.8 4.6 4.7	25 to 49 years	23,100	27,100	3,200	22,800	76,200	
One story house (number) 67,000 79,400 10,300 61,800 218,500 More than 1 story (number) 8,000 5,900 200 1,400 15,500 Total number of rooms 337,400 324,100 41,600 211,200 914,300 Number of entries 75,000 85,300 10,500 63,200 234,000 Average number of rooms 4.5 3.8 4.0 3.3 3.9 Total number of rooms 4,600 10,400 400 4,800 20,200 Number of entries 2,800 5,300 300 3,100 12,000 Total number of regular 336,700 413,300 50,100 289,600 1,089,700 Number of entries 75,000 85,300 10,500 63,200 234,000 Average number of occupants per house 4.5 4.8 4.8 4.6 4.7 Average number of 4.5 4.8 4.8 4.6 4.7	50 and over years	9,300	9,200	500	3,300	22,300	
More than 1 story (number) 8,000 5,900 200 1,400 15,500 Total number of rooms 337,400 324,100 41,600 211,200 914,300 Number of entries 75,000 85,300 10,500 63,200 234,000 Average number of rooms not in use at any time of year 4,600 10,400 400 4,800 20,200 Number of entries 2,800 5,300 300 3,100 12,000 Total number of regular occupants 336,700 413,300 50,100 289,600 1,089,700 Number of entries 75,000 85,300 10,500 63,200 234,000 Average number of occupants per house 4.5 4.8 4.8 4.6 4.7 Average number of 4.5 4.8 4.8 4.6 4.7	One story house (number)		·	10,300		218,500	
Total number of rooms 337,400 324,100 41,600 211,200 914,300 Number of entries 75,000 85,300 10,500 63,200 234,000 Average number of rooms not in use at any time of year 4,600 10,400 400 4,800 20,200 Number of entries 2,800 5,300 300 3,100 12,000 Total number of regular occupants 336,700 413,300 50,100 289,600 1,089,700 Number of entries 75,000 85,300 10,500 63,200 234,000 Average number of occupants per house Average number of occupants per house Average number of 4.5 4.8 4.8 4.6 4.7	More than 1 story (number)		The state of the s	200		15,500	
Number of entries 75,000 85,300 10,500 63,200 234,000 Average number of rooms not in use at any time of year 4.600 10,400 400 4,800 20,200 Number of entries 2,800 5,300 300 3,100 12,000 Total number of regular occupants 336,700 413,300 50,100 289,600 1,089,700 Number of entries 75,000 85,300 10,500 63,200 234,000 Average number of occupants per house A	Total number of rooms	337,400	· ·	41.600	211,200	914,300	
Average number of rooms per house 4.5 3.8 4.0 3.3 3.9 Total number of rooms not in use at any time of year 4,600 10,400 400 4,800 20,200 Number of entries 2,800 5,300 300 3,100 12,000 Total number of regular occupants 336,700 413,300 50,100 289,600 1,089,700 Average number of occupants per house 4.5 4.8 4.8 4.6 4.7 Average number of	Number of entries			· ·	· ·	234,000	
Total number of rooms not in use at any time of year Number of entries Total number of regular occupants Number of entries 75,000 Average number of occupants per house Average number of	Average number of	ŕ	, ,		,		
Total number of rooms not in use at any time of year Number of entries Total number of regular occupants Number of entries 336,700 Number of entries Average number of occupants per house Average number of	3	4.5	3-8	4.0	3.3	3.9	
not in use at any time of year 4,600 10,400 400 4,800 20,200 Number of entries 2,800 5,800 300 3,100 12,000 Total number of regular occupants 336,700 413,300 50,100 289,600 1,089,700 Number of entries 75,000 85,300 10,500 63,200 234,000 Average number of occupants per house 4.5 4.8 4.8 4.6 4.7 Average number of 4.5 4.8 4.8 4.6 4.7	-		, , ,				
of year 4,600 10,400 400 4,800 20,200 Number of entries 2,800 5,300 300 3,100 12,000 Total number of regular occupants 336,700 413,300 50,100 289,600 1,089,700 Number of entries 75,000 85,300 10,500 63,200 234,000 Average number of occupants per house 4.5 4.8 4.8 4.6 4.7							
Number of entries 2,800 5,300 300 3,100 12,000 Total number of regular occupants 336,700 413,300 50,100 289,600 1,089,700 Number of entries 75,000 85,300 10,500 63,200 234,000 Average number of occupants per house 4.5 4.8 4.8 4.6 4.7	·	4.600	10 400	400	4.800	20,200	
Total number of regular 336,700 413,300 50,100 289,600 1,089,700 Number of entries 75,000 85,300 10,500 63,200 234,000 Average number of occupants per house Average number of 4.5 4.8 4.8 4.6 4.7	· ·	·		•			
Occupants 336,700 413,300 50,100 289,600 1,089,700 Number of entries 75,000 85,300 10,500 63,200 234,000 Average number of 4.5 4.8 4.8 4.6 4.7		~, 55	5,000	000	0,200		
Number of entries 75,000 85,300 10,500 63,200 234,000 Average number of occupants per house Average number of 4.5 4.8 4.8 4.6 4.7		336.700	413.300	50.100	289,600	1.089.700	
Average number of occupants per house 4.5 4.8 4.8 4.6 4.7 Average number of	~		· ·	i i			
occupants per house 4.5 4.8 4.8 4.6 4.7 Average number of		,	00,000	23,000	00,000		
Average number of		4.5	4-8	4.8	4-6	4.7	
		1.50	1.0	1.0			
1.0	0	1.0	1.3	1.2	1.4	1.2	
	Transfer from		1.0		- •	2.0	



- 4 - State of Arkansas
C. CONDITION OF HOUSE

	White owners (Number of entries)							
	Pro	sent condit	Repairs or	Rcplacement or new				
	Good	Fair	needed	installa- tion needed				
Foundation	22,700	24,600	27,500	20,800	14,900			
Walls, exterior	29,300	31,300	14,400	24,300	5,600			
Roof	30,000	21,400	23,600	22,400	13,000			
Chimneys	34,100	20,000	16,200	14,100	9,200			
Doors and windows	31,300	27,800	15,900	22,800	7,500			
Screens	19,900	19,200	13,400	18,300	23,100			
Paint, exterior	9,400	11,500	13,700	10,800	29,200			
Interior walls and ceiling	20,650	33,350	21,000	26,500	12,600			
Floors	30,200	29,400	15,400	21,900	6,400			
Stairs	3,900	2,400	1,200	900	900			

		White non-	owners (Num	ber of entri	es)
	$\mathtt{P}_{\mathtt{re}}$	sent condit	ion	Repairs or	Replacement or new
	Good	Fair	Poor	alterations needed	installa- tion needed
Foundation	14,000	25,600	45,400	30,100	24,300
Walls, exterior	18,600	35,400	31,300	37,500	13,000
Roof	24,700	23,900	36,700	30,000	20,000
Chimneys	23,200	26,800	29,300	25,100	15,900
Doors and windows	19,000	31,500	34,800	36,900	16,500
Screens	10,800	15,700	28,400	19,300	38,800
Paint, exterior	3,200	5,500	14,800	8,300	36,000
Interior walls and ceiling	12,200	31,350	41,750	34,700	23,000
Floors	21,600	33,600	30,100	33,700	14,300
Stairs	2,300	2,500	2,300	1,100	820

	Non-white owners (Number of entries)							
	Pre	sunt conditi	Repairs or	Replacement or new				
	bood	Fair	Poor	alterations needed	installa- tion needed			
Foundation	1,400	3,000	6,100	4,600	3,200			
Walls, exterior	1,900	4,300	4,360	5,300	1,900			
Roof	1,600	2,300	6,700	4,500	3,700			
Chimneys	2,100	2,500	5,300	3,000	3,000			
Doors and windows	1,500	3,600	5,400	5,500	2,600			
Screens	500	900	3,800	2,400	5,500			
Paint, exterior	200	400	1,000	600	3,200			
Interior walls and ceiling	1,200	3,100	6,200	4,900	3,100			
Floors	2,000	4,000	4,500	5,100	2,200			
Stairs	50	100	50	100	10			



- 5 - State of Arkaneas C. CONDITION OF HOUSE (Continued)

		Non-white	non-owners (Number of en	tries)
	Pro	esent conditi	ion	Repairs or	Replacement or new
	. Good	Fair	Poor	alterations needed	installa- tion needed
Foundation	7,700	16,500	39,000	22,800	25,500
Walls, exterior	9,300	23,500	30,400	29,000	18,200
Roof	11,400	15,500	36,300	23,600	23,600
Chimneys	12,100	19,000	28,800	22,200	19,700
Doors and windows	7,300	21,400	34,500	29,800	20,400
Scroens	1,600	3,400	23,300	10,000	29,700
Paint, exterior	400	1,000	4,000	1,800	12,200
Interior walls and ceiling	6,500	18,100	38,600	24,500	23,700
Floors	11,600	22,700	28,900	27,100	16,800
Stairs	450	500	550	300	7.50

	c. cc	NDITION OF	HOUSE (Concl.	uded)			
	Total for State (Number of entries)						
	Pro	sent condit	ion	Repairs or	Replacement or new		
,	Good	Fair	Poor	alterations needed	installa- tion needed		
Foundation	45,800	69,700	118,000	78', 300	67,900		
Walls, exterior	59,100	94,500	80,400	96,100	38,700		
Roof	67,700	63,000	103,300	80,500	60,300		
Chimneys	71,500	68,300	79,600	65,300	47,300		
Doors and windows	59.100	84,300	90,600	95,000	47,000		
Screens	32,800	39,200	73,900	50.000	97,100		
Paint, exterior	13,200	18,400	33,500	21,500	80,600		
Interior walls and ceiling	40,550	85,900	107,550	90,600	62,400		
Floors	65,400	89,700	78,900	87,800	39,700		
Stairs	6 700	5 500	1 700	2 400	2 480		

D. SPACE REQUIREMENTS *								
	White							
	Ow	ner	Non-owner					
	Have	Additional	Have	Additional				
	now	room needed	TLOW	room needed				
Bedrooms **	180,200	14,800	173,700	23,300				
Number of entries	74,700	11,000	85,200	17,700				
Living room	33,100	5,600	24,000	6,500				
Dining room	38,100	4,300	31,500	6,400				
Kitchen	73,400	375	82,600	425				
Work room	5,500	3,000	4,200	2,200				
Washroom for farm help	2,075	2,800	1,350	2,500				
Bathrooms	5,300	2,200	2,150	1,800				
Halls	20,600	200	14,800	400				
Basement	3,700	500	1,700	400				
Closets ***	46,500	34,300	26,900	38,300				
Number of entries	26,900	16,300	15,900	18,800				
Front or side porch	65,600	1,900	73,300	2,400				
Back porch	48,500	5,200	39,400	8,100				
Storage space for fresh				3				
fruits and vegetables	27,500	17,400	16,100	22,700				



D. SPACE REQUIREMENTS * (Concluded)

			D. DIMOH RHQUE	<u></u>			
			Non-v	vhite		m	C C + - t - t
		0,	wner	Non	-owner	Total	for State
		Have	Additional	Havo	Additional	Have	Additional
		now	room needed	now	room needed	now	room needed
Bedrooms	**	24,100	2,800	126,600	19,000	504,600	59,900
Number	of entries	10,500	2,000	63,200	13,600	233,600	44,300
Living n	coom	1,600	700	4,300	2,900	63,000	15,700
Dining r	coom	4,700	500	18,300	1,700	92,600	12,900
Kitchen		10,400	75	62,700	150	229,100	1,025
Work roo	om	450	350	1,250	450	11,400	6,000
Wash roc	m for farm help	25	100	50	100	3,500	5,500
Bathroom	ns	125	175	125	225	7,700	4,400
Halls		2,700	100	5,000	20	43,100	720
Basement	;	75	75	100	25	5,575	1,000
Closets	* * *	1,700	5,200	5,400	14,000	80,500	91,800
Number	of entries	1,400	2,400	4,100	7,500	48,300	45,100
Front or	side porch	8,800	600	53,400	2,700	201,100	7,500
Back por	eh	4,600	1,500	13,200	3,600	105,700	18,400
Storage	space for fresh						
fruits	and Vagetables	1,000	1,400	3,500	3,800	48,100	45,300


E. WATER SUPPLY AND SEWAGE DISPOSAL *

	T	· 	Wh	ite		
		Owner		N	on-owner	
	Have	Repairs	New	Have Repairs		New
	now	or alter-	instal-	now	or altera-	instal-
		ation	lation		tions	lation
		needed	needed		needed .	nceded
Source of water:						
Well, drilled or driven	23,900	1,200	900	35,600		3,000
Well, dug or bored	30,700		1,200	26,000		2,300
Spring	8,800	400	250	9,400		25
Cistern	13,200	2,300	500	10,900		1,300
Stream	300	-	-	800	-	-
Water supply for house:						
Carried	n mnm 000			10 107 800		
Distance (total feet) Number carrying water	7,777,800	-	-	18,183,700		-
Hand pump in dwelling	58,500 1,300	100	200	71,800 1,800	75	400
Piped, cold	4,100	50	200	2,200		400
Piped, hot	1,750	-	200	620	25	300
Sanitary facilities:						
Outdoor toilet (privy):	0.0					
Improved	4,500	400	4,300	3,300	700	8,500
Unimproved Indoor:	46,100	-	-	51,300	-	-
Chemical	120	_	50	550	_	50
Flush	1,720	25	100	1,050	1	50 200
Bathroom fixtures:						
Tub	3,100	50	800	1,400	50	500 .
Shower	400	0.7	300 500	\$500	-	300 500
Lavatory Kitchen sink with drain	2,350 5,900	25 200	3,100	1,050 2,200	100	3,000
Disposal of sewage:	0,000	200	0,100	2,200	100	0,000
Septie tank	1,100	20	200	400	50	300
Cesspool		_	_		_	20
Stream Surface	700	5	25	400 225	-	-
OUTIACO	6,200	-		2,700	<u>-</u>	

^{*} Number of entries except where otherwise indicated

*** Number of bedrooms

*** Number of closets



			-7-		State of A	ກ ^າ ເກກ ຂອ ຊ			
	E. WATER SUPPLY AND SEWAGE DISPOSAL *								
		(Conti	nued)						
			Non-white						
		Owner			Non-owner				
	Have	Repairs or	New instal-	Have		New instal-			
	now	alterations	lation	now	alterations	nceded			
Source of water:		needed	nooded		needed	needed			
Well, drilled or driven	3,400	600	800	34,800	4,500	8,200			
Well dug or bored	4,800	1,200	700	13,900	3,300	2,900			
Spring	700	25	-	2,000	25	25			
Cistern	400	100	75	1,200	200	400			
Stream	200	-	-	600		-			
Water supply for house:									
Carried									
	3143,100	-	-	19640,300	-	-			
Number carrying water	9,600	-	-	61,000	-	-			
Hand pump in dwelling	50	-	-	300	25	25			
Piped, cold	50	-	-	400	10	-			
Piped, hot	10	-	-	20	-	100			
Sanitary facilities:									
Outdoor toilet (privy):	300	100	2 700	2 000	7 700	6 000			
Improved Unimproved	6,400	100	2,100	2,900 44,000	1,300	6,000			
Indoor:	0,400	-	-	44,000		_			
Chemical	_	_		_	_	_			
Flush	20	_	_	30	10	-			
Bathroom fixtures:	20								
Tub	25	_	-	50	10				
Shower	5	-	_	20		-			
Lavatory	20	-	-	50	20				
Kitchen sink with drain	50	-	200	75	10	150			
Disposal of sewage:									
Septic tank	20	-	-	20	10				
Cesspool	10	-	-	20	-	-			
Stream	-	-	-	-	-	-			
Surface	300	-	-	500	-	-			

E. WATER SUPPLY AND SEWAGE DISPOSAL *

(Concluded)								
		Total for State						
	Have	Repairs or altera-	New installation					
	now	tions needed	, needed					
Source of water:								
Well, drilled or driven	97,700	9,500	12,900					
Well dug or bored	75,400	12,800	7,100					
Spring	20,900	900	300					
Cistern	25,700	5,000	2,375					
Stream	1,900		-					
Water supply for house:								
Carried								
Distance (total feet)	48,744,900	-	_					
Number carrying water	200,900	-	-					
Hand pump in dwelling	3,450	200	625					
Piped, cold	3 ,7 50	135	600					
Piped, hot	2,400	25	500					
Sanitary facilities:								
Outdoor toilet (privy):								
Improved	11,000	2,500	20,900					
Unimproved	147,800	_	_					
Indoor:								
Chemical	670		100					
Flush	2,800	45	300					
Bathroom fixtures:			300					
Tub	4,575	110	1,300					
Shower	625	_	600					
Lavatory	3,470	45	1,000					
Kitchen sink with drain	8,225	. 310	6,450					
Disposal of sewage:			,					
Septic tank	1,540	80	500					
Cesspool	1,130	-	20					
Stream	450	5	25					
Surface	9,700	-	-					
			<u> </u>					

^{*} Number of entries except where otherwise indicated.



F. LIGHT AND HEAT (Number of entries)

	!		White	······································		
		Owner		Non-owner		
	Have	Repairs	New	Have	Repairs	New
	now	or altera-	instal-	now	or altera-	instal-
		tions	lation	·	tions	lation
		necded	needed /		necded	needed
T. 1.1.						
Lighting:				,		
Kerosene or	20 000			25 200		2 700
gasoline lamps	69,200		1,400	83,200	_	2,300
Acetylene	475	75	5	175	75	-
Piped gas	325	25	25	50	10	-
Electric:						
Home plant	2,250	300	50	550	50	25
Power line	3,375	25	200	1,700		350
Miles	443,000		-	500,000	-	-
Number of entries	56,000	-		66,700	-	-
Heating:						į
Fireplaces	40,200	3,800	1,300	39,600	6,700	2,100
Stoves	52,400	2,000	1,000	57,600	3,200	2,500
Circulating heater	820	5	_	230	_	-
Pipeless furnace	25	100	-	50	50	50
Piped warm air						
steam, or water						
furnace	200	5	-	25	_	_

F. LIGHT AND HEAT

			Non-v	white		
		Owner		Non-owner Non-owner		
·	Have	Repairs	New	Have	Repairs	New
	now	or altera-	instal-	now	or altera-	instal-
		tions	lation		tions	lation
-		needed	needed		Ineeded	needed
Lighting:						ı
Kerosene or						
gasoline lamps	10,400	_	400	61,800	-	3,900
Acetylene	25	_	_	50	-	-
Piped gas	10		_	_	-	-
Electric:						
Home plant	50	-	_	50	-	25
Power line	50	-	_	225	~	_
Miles	35,000		-	267,000	-	- :
Number of entries	9,400	-	-	59,300	-	-
Heating:						
Fireplaces	5,200	1,500	800	30,100	10,200	3,900
Stoves	7,000	1,000	600	39,800	5,800	4,800
Circulating heater	10	-	-	20	-	-
Pipeless furnace	_		-	-		- .
Piped warm air,						
steam, or water			- 4			
furnace	-	_	_	_	-	-

f

*

F. LIGHT AND HEAT (Concluded)

	the state of the s	Total for State	
	Have	Repairs or	New in-
	now	alterations	stallation
	······································	needed	needed
Lighting:			
Kerosene or			
gasoline lamps	224,600	-	8,000
Acetylene	725	150	5
Piped gas	385	35	25
Electric:			
Home plant	2,900	350	. 100
Power line	5,350	25	550
Miles	1,245,000	-	_
Number of entries	191,400	-	-
Heating:			
Fireplaces	115,100	22,200	8,100
Stoves	156,800	12,000	8,900
Circulating heater	1,080	5	-
Pipeless furnace	75	150	50
Piped warm air,			
steam, or water			
furnace	225	5	-

G. REFRIGERATION, LAUNDRY, AND COOKING FACILITIES (Number of entries)

	White						
		Owner	Whit	<u>e</u>	Non-owner		
	Have	Repairs	New in-	Have	Repairs	New in-	
	now	or altera-		now	or altera-	stalla-	
	110 W	tions	tion	210W	tions	tion	
		needed	needed.		needed .	needed	
Refrigeration:		incened	needed.		nesueu	iiceaca	
Ice	13,200	500	5,900	9,700	850	7,000	
Mechanical	2,100	50	100	575	10	200	
Laundry:	2,200		100	0,0			
Where done:							
Out-of-doors	53,700	<u></u>		80,700		-	
In kitchen	24,800	90	45	30,600	70	95	
In basement	350	_	25	75		10	
In special room							
on same level							
with kitchen	2,200	15	650	775	125	700	
Equipment:						}	
Fixed tubs	2,100		150	900	25	250	
Power machine	1,900	80	135	1,200	20	275	
Hand machine	1,800	1 40	1,300	600	20	1,600	
Cooking facilities:							
Wood or coal							
stoves	72,000	2,800	2,200	83,000	4,600	4,100	
Kerosene or gas-							
oline stoves	5,100	200	50	3,450	100	75	
Gas stoves	400	25	-	100	-	-	
Electric stoves	250		25	25	_	30	



ii.	Non-white							
		Owner		Non-owner ;				
f ·	Have	Repairs	New in-	Have	Repairs	New in-		
	now	or altura-	stalla-	now	or altera-	stalla-		
		tions	tion		tions	tion		
		needed	necded		necded	necded		
Refrigeration:								
Ice	1,000	200	400	4,100	400	1,100		
Mechanical	-	~	-	10	_	•••		
Laundry:								
Where done:								
Out-of-doors	10,300		- -	61,100	~	-		
In kitchen	2,800	40 ;	-	28,700	95	30		
In basement	5	 ,	-	-		-		
In special room		<i>*</i>						
on same level		•						
with kitchen	10	-	25	-		25		
Equipment:								
Fixed tubs	10	-	-	90	-	10		
Power machine	5	- :	10	10	-	-		
Hand machine	25	~	50	175	-	-		
Cooking facilities:								
Wood or coal		•						
stoves	10,400	1,200	1,300	61,100	8,300	10,600		
Kerosone or gas-								
oline stoves	50	20	-	350	50	10		
Gas stoves	10	10.	-	10		-		
Electric stoves	-	_	-		_	-		

G. REFRIGERATION, LAUNDRY, AND COOKING FACILITIES

(Concluded) Total for State Have Repairs or New installation alterations now needed needed Refrigeration: Ice 14,400 28,000 1,950 Mechanical 2,685 60 300 Laundry: Where done: Out-of-doors 205,800 In kitchen 86,900 170 295 In basement 430 35 In special room on same level with kitchen 2,985 140 1,400 Equipment: Fixed tubs 3,100 25 410 Power machine 3,115 420 100 Hand machine 2,600 160 2,950 Cooking facilities: Wood or coal stoves 226,500 16,900 18,200 Kerosene or gasoline stoves 8,950 370 135 Gas stoves 520 35 Electric stoves 275 55



Η.	LANDSC	APING	OF	HOUSE
	(Number	of e	ntri	.es)

White								
	,	Owner			Non-owner_			
	Have	Repairs or	New instal-	Have	Repairs or	New instal-		
	now	alterations	lation	now	alterations	lation		
		necded	nceded .		nceded	nceded		
Yard:								
Surface drainage								
away from house	67,400	7,300	3,900	73,100	11,500	7,200		
Lawn established	30,300	9,700	24,000	21,300	8,200	31,450		
Plantings	23,900	7,700	27,200	12,700	5,100	35,800		
Walks and drives	12,500	6,700	33,300	6,700	4,300	39,200		
Fences	36,700	19,200	21,200	35,600	19,200	31,800		

H. LANDSCAPING OF HOUSE (Number of entries)

		Non-white						
			Owner			Non-owner	Ď.	
		Have	Repairs or	New instal-	Have	Repairs or	New instal	
		now	alterations	lation	now	alterations	lation	
			needed	needed		needed	needed	
Yard:								
Surfa	ce drainage							
away	from house	9,100	2,200	700	50,900	12,800	5,500	
Lawn	established	1,800	500	2,350	6,100	2,500	11,000	
Plant	ings	2,000	600	2,200	5,500	1,800	10,900	
Walks	and drives	7 00	500	2,500	5,400	4,700	12,200	
Fence	S	5,300	3,100	3,000	28,500	17,300	14,300	

H. LANDSCAPI RG OF HOUSE (Number of entries)

	Total for State						
Have now		Rcpairs or alterations needed	New in- stallation nceded				
Yard:							
Surface drainage							
away from house	200,500	33,800	17,300				
Lawn established.	59,500	20,900	68,800				
Plantings	44,100	15,200	76,100				
walks and drives	25,300	16,200	87,200				
Fences	106,100	58,800	70,900				



I. RELATIVE IMPORTANCE OF REPAIRS AND IMPROVEMENTS WANTED
(Number of entries)

	White					
	Owner			.Non-owner		
	\$500	\$250	\$100	\$500	\$250	\$100
House repairs and			,			
Improvements:						
Foundation	11,500	12,300	11,400	11,800	13,500	17,800
Exterior walls	18,200	20,500	17,200	17,100	18,800	18,100
Roof	18,000	20,700	20,900	15,300	18,600	27,200
Chimneys	6,500	6,900	5,800	7,600	9,300	10,300
Doors, windows,		,				
screens	13,900	16,800	14,400	18,700	23,600	26,700
Porches	11,600	13,700	10,400	12,400	15,900	13,800
Interior walls,						
ceilings,						
floors	21,250	24,700	20,000	22,550	28,300	26,900
Additional						
room	13,600	11,300	7,600	11,900	11,500	7,700
Water system	9,100	6,800	3,700	7,400	5,700	4,300
Sanitary facilities	4,700	3,400	2,300	4,400	4,400	6,000
Lighting system	2,400	1,100	400	1,700	800	300
Heating system	750	400	100	400	300	200
Bathroom equipment	5,700	3,300	1,650	3,700	2,300	1,200
Laundry facilities	2,700	1,500	625	2,500	1,150	525
Cooking facilities	2,500	1,500	650	2,900	1,700	1,200
Landscaping	3,500	2,600	2,000	2,700	2,100	1,500
Electricity:						
Home plant	1,100	350	125	430	75	75
Power line	1,150	625	275	950	500	175
Built-in-equipment	4,100	2,600	1,400	3,500	2,900	1,400
Furnishings	8,600	6,100	3,600	10,400	7,100	5,300



	Non-white					
	Owner			Non-owner ,		
	\$500	\$250	\$100	\$500	\$250	\$100
House repairs and						
improvements:						20.000
Foundation	2,100	3,300	3,500	11,400	14,000	27,900
Exterior walls	2,200	3,200	2,700	11,000	14,100	21,200
Roof	2,500	3,900	4,700	12,300	16,300	31,900
Chimneys	1,600	2,800	2,200	8,400	12,100	16,400
Doors, windows,					00.000	go 000
screens	2,500	4,500	3,600	14,000	20,900	30,000
Porches	1,700	3,300	2,300	9,000	14,700	13,900
Interior walls,						
ceilings,						~~ ~~~
floors	2,700	4,500	3,100	13,000	21,700	21,100
Additional						
room	1,400	1,600	800	7,100	8,000	4,000
Water system	600	800	600	2,700	4,700	5,400
Sanitary facilities	700	1,200	7 00	2,500	5,300	10,100
Lighting system	25	25	20	100	125	30
Heating system	100	100	-	350	500	100
Bathroom equipment	200	100	25	800	700	625
Laundry facilities	300	150	25	1,000	300	125
Cooking facilities	500	300	100	2,100	1,600	950
Landscaping	200	300	200	1,100	1,000	600
Electricity:						
Home plant	5	-	-	40	10	
Power line	-	-	10	75	75	35
Built-in-equipment	400	300	_50	1,200	1,200	700
Furnishings	1,200	500	300	5,600	4,100	2,300

I. RELATIVE IMPORTANCE OF REPAIRS AND IMPROVEMENTS WANTED (Concluded) (Number of entries)

	· ·				
	Total for State				
	\$500	\$250	\$100		
House repairs and					
improvements:					
Foundation	36,800	43,100	60,600		
Exterior walls	48,500	56,600	59,200		
Roof	48,100	59, 500	84,700		
Chimneys	24,100	31,100	34,700		
Doors, windows,	49,100	65,800	74,700		
screens					
Porches	34,7 00	47,600	40,400		
Interior walls,					
ceilings					
floors	59,500	79,700	71,100		
Additional					
room	34,000	32,400	20,100		
Water system	19,800	18,000	14,000		
Sanitary facilities	12,300	14,300	19,100		
Lighting system	4,225	2,050	750		
Heating system	1,600	1,300	400		
Bathroom equipment	10,400	6,400	3,500		
Laundry facilities	6,500	3,100	1,300		
Cooking facilities	8,000	5,100	2,900		
Landscaping	7,500	6,000	4,300		
Electricity:					
Home plant	1,575	435	200		
Power line	2,175	1,200	495		
Built-in-equipment	9,200	7,000	3,550		
Furnishings	25,800	17,800	11,500		



Questions regarding new construction and availability of local credit sources to finance construction contained on the questionnaire were answered by the occupants as follows:

J. NEW CONSTRUCTION AND FINANCING

	Wh	ite
	Owner	Non-owner
Number of persons reporting		
contemplated construction		
of new house within next 3 yrs.	5,600	4,000
Number of rooms to be constructed	20,625	15,125
Number of entries	5,100	3,700
Estimated expenditure	\$1,959,200	\$2,234,400
Number of entries	5,100	3,600
Value of repairs or improvements		
made on the present house during		
the last 3 years.		
Less than \$100	21,400	18,400
\$100 to \$499	5,800	2,300
\$500 and over	1,400	400
Expenditure for repairs or improvements		
contemplated within next 12 months		
(total amount)	\$3,629,900	\$2,480,200
Number of entries	13,100	13,800
Number of persons reporting that money		
is available from local credit sources		
to finance house construction, repairs,		
or improvements	4,100	3,800
Number of persons interested in borrow-		
ing money to finance construction.		
repairs, or improvements provided		
interest rate 's satisfactory and		
repayments can be distributed over a		
period of 10 years.	30,500	21,800
Not interested	29,900	56,500
Total sum desir à	\$9,451,300	\$6,863,900
Number of entries	29,300	21,100



J. NEW CONSTRUCTION AND FINANCING (Concluded)

	Non-w	Non-white	
	Owner	Non-owner	State
Number of persons reporting			
contemplated construction	1		
of new house within next 3 yrs.	1,400	2,700	13,700
Number of rooms to be constructed	4,800	10,550	51,100
Number of entries	1,200	2,700	12,700
Estimated expanditure	\$513,400	\$1,215,900	\$5,922,900
Number of entries ·	1,300	2,700	12,700
Value of repairs or improvements		*	
made on the present house during			
the last 3 years.			
Less than \$100	2,400	7,600	49,800
\$100 to \$499	300	. 500	8,900
\$500 and over	_	100	1,900
Expenditure for repairs or improvements			
contemplated within next 12 months			
(total amount)	\$1,099,400	\$1,374,500	\$8,584,000
Number of entries	5,300	10,100	47,300
Number of persons reporting that money			
is available from local credit sources			
to finance house construction, repairs,			
or improvements	200	2,300	10,400
Number of persons interested in borrow-			
ing money to finance construction,			
repairs, or improvements provided			
interest rate is satisfactory and			
repayments can be distributed over a			
period of 10 years.	8,100	25,900	· ·
Not interested	2,200	32,500	
Total sum desired	\$2,143,500	\$6,293,800	
Number of entries	8,100	25,900	84,400

These are all preliminary data, subject to revision before publication.





